

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG20000357/R1QD3E2

**Date:** 22/04/2020

### REFERENCE

Insured/Claimant:	LIM HOCK HAI	Policy No:	1800033031	
Date of Loss:	27/12/2019	Nature of Claim:	OD	Claim No: 4997116012SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7606M		
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Engine No:	CYG020601
Reg. Date:	10/04/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4GXHN128184
Colour:	Grey	Odometer:	44497 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,703.00	5,286.72	5,416.28	50.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,272.00	1,922.00	5,350.00	73.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,975.00</b>	<b>7,208.72</b>	<b>10,766.28</b>	<b>59.90</b>
<b>- Excess (\$\$)</b>	800.00	800.00	0.00	0.00
<b>(\$\$)</b>	17,175.00	6,408.72	10,766.28	62.69
<b>+ GST 7.00/7.00% (\$\$)</b>	1,202.25	448.61	753.64	62.69
<b>Nett Amount (\$\$)</b>	<b>18,377.25</b>	<b>6,857.33</b>	<b>11,519.92</b>	<b>62.69</b>

### INSPECTION

Date of Assignment:	07/01/2020	
Date Inspected:	06/01/2020	Inspected At: 281 Alexandra Road
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,787.00 FS	*2,229.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	491.00 FS	*- FS
3	1		*FRONT BUMPER CENTRE GRILLE - LOWER	Cracked	116.00 FS	*92.40 FS
4	14		*FRONT BUMPER AIR GUIDE GRILLE LOCKING CLIP	Not Necessary	51.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	199.00 FS	*- FS
6	1		*FRONT BUMPER LOWER SPOILER	Deformed	227.00 FS	*181.20 FS
7	1		*FRONT BUMPER UPPER SPOILER	Cracked	860.00 FS	*687.60 FS
8	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,412.80 FS
9	1		*RADIATOR GRILLE COVER	Serviceable	33.00 FS	*- FS
10	2		*RADIATOR SENSOR SUPPORT - LH / RH	Serviceable	122.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Serviceable	904.00 FS	*- FS
12	2		*FRONT BUMPER AIR GUIDE GRILLE COVER - LH / RH	Serviceable	92.00 FS	*- FS
13	2		*FRONT WHEEL SPOILER - LH / RH	Serviceable	482.00 FS	*- FS
14	2		*FRONT HEADLAMP WASHER COVER - LH / RH	Serviceable	104.00 FS	*- FS
15	1		*FOAM FILLER PIECE	Serviceable	215.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT	Bent	754.00 FS	*602.80 FS
17	1		*FRONT BUMPER TOP COVER	Serviceable	112.00 FS	*- FS
18	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
19	2		*FRONT SENSOR	Serviceable	419.00 FS	*- FS
20	4		*FRONT SENSOR SEAL RING	Not Necessary	5.00 FS	*- FS
21	2		*FRONT BUMPER AIR GUIDE - LH / RH	Serviceable	50.00 FS	*- FS
22	1		*RADIATOR UPPER COVER	Serviceable	27.00 FS	*- FS
23	1		*RADIATOR LOWER SEALING STRIP	Serviceable	21.00 FS	*- FS
24	1		*AIR COOLER	Serviceable	513.00 FS	*- FS
25	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
26	1		*SUNDRIES	Necessary	300.00 FS	*40.32 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **10,703.00** **5,286.72**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCOND CONDENSER AND RADIATOR. TO RENEW CHARGED AIR COLLER. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER. TO REMOVE AND REINSTALL FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,200.00	750.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>7,272.00</b>	<b>1,922.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >