

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20000361/KTF3E2

Date: 26/06/2020

REFERENCE

Insured/Claimant: RIEZQI TRANSPORTATION	Policy No: DMB1SN3076621800	
Date of Loss: 02/01/2020	Nature of Claim: OD	Claim No: SNM20D200056/PC2630M/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2630M		
Make & Model:	TOYOTA HIACE, 3.0 (A)	Engine No:	1KD2396426
Reg. Date:	30/06/2014 (Man. Year: 2014)	Chassis No:	KDH2230019876
Colour:	Metallic Silver	Odometer:	433436 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$42,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Journey 9 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Journey 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,600.00	6,990.00	1,610.00	18.72
Miscellaneous Items	185.00	155.00	30.00	16.22
Paintwork Materials	139.50	139.50	0.00	0.00
Labour	537.60	436.80	100.80	18.75
Paintwork Labour	315.00	315.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,777.10	8,036.30	1,740.80	17.80
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	9,777.10	6,536.30	3,240.80	33.15
+ GST 7.00/7.00% (\$\$)	684.40	457.54	226.86	33.15
Nett Amount (\$\$)	10,461.50	6,993.84	3,467.66	33.15

INSPECTION

Date of Assignment:	07/01/2020 Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	07/01/2020 Inspected At:	S & H Motor Pte Ltd (Sin Ming)
		160 Sin Ming Drive #07-02, Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Jun 2020)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC2630M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare parts		8,160.00 F	*6,550.00 F
<u>Supplementary #1</u>						
2	1		*Air inlet duct	Dented	70.00 F	*70.00 F
3	1		*RH front bumper retainer	Bent	75.00 F	*75.00 F
4	1		*LH front bumper retainer	Bent	75.00 F	*75.00 F
5	1		*Front wiper garnish	Dented	220.00 F	*220.00 F
F=Franchise part.						
Total Parts (S\$)					8,600.00	6,990.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork material	139.50	139.50
<u>Miscellaneous Items</u>				
2	1	misc	185.00	155.00
Sub Total (\$\$)			324.50	294.50

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	315.00	315.00
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	537.60	436.80
Gross Labour Cost (\$\$)			852.60	751.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >