

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000362/KBS3Q2

**Date:** 15/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800136226

**Claimant**  
**Vehicle No :** SMD5401T **Insured Vehicle No :** SMF8254X

Date of Loss: 02/01/2020 Nature of Claim: TP Claim No: 0034936918SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMD5401T</b>		
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 G (A)	Engine No:	1NZ8402642
Reg. Date:	24/08/2018 (Man. Year: 2017)	Chassis No:	NHP1707110645
Colour:	Metallic Silver	Odometer:	99537 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Double Star 4 mm	Rear Left Side:	Double Star 6 mm
Front Right Side:	Double Star 4 mm	Rear Right Side:	Double Star 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	171.67	111.67	60.00	34.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	550.00	150.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>871.67</b>	<b>661.67</b>	<b>210.00</b>	<b>24.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	61.02	46.32	14.70	24.09
<b>Nett Amount (S\$)</b>	<b>932.69</b>	<b>707.99</b>	<b>224.70</b>	<b>24.09</b>
<b>+ Car Rental (3.0 x S\$70.00/day) (S\$)</b>		210.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>919.99</b>		

### INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 10/01/2020 Inspected At:

9A SERANGOON NORTH AVE 5

Repairer: Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	68.90 FL	*68.90 FL
2	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
3	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
4	1		*FRONT ALLOY RIM RH (REPAIR)	Scratched	120.00 FS	*60.00 FS
					<b>Sub Total (\$)</b>	<b>188.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>17.23</b>
					<b>Total Parts (\$)</b>	<b>171.67</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE TO REMOVE ,REPAIR ,REFIX ,READJUST ACCIDENT AREAS & ETC	New	200.00	150.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER RH ,FRONT BUMPER & ETC	New	500.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>700.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >