

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20000366/ESF3E2

**Date:** 18/05/2020

### REFERENCE

Insured/Claimant:	NARINDER KABOOR	Policy No:	2100499441	
Date of Loss:	04/01/2020	Nature of Claim:	OD	Claim No: 5411488881SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCW7585B			
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR021773	
Reg. Date:	26/01/2017 (Man. Year: 2016)	Chassis No:	WAUZZZ4M1HD014201	
Colour:	Silver	Odometer:	23254 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$190,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,190.76	6,605.76	9,585.00	59.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,562.00	5,032.00	8,530.00	62.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>29,752.76</b>	<b>11,637.76</b>	<b>18,115.00</b>	<b>60.89</b>
<b>+ GST 7.00/7.00% (S\$)</b>	2,082.69	814.64	1,268.05	60.89
<b>Nett Amount (S\$)</b>	<b>31,835.45</b>	<b>12,452.40</b>	<b>19,383.05</b>	<b>60.89</b>

### INSPECTION

Date of Assignment:	07/01/2020	
Date Inspected:	07/01/2020	Inspected At: 24 Benoi Sector
		Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,121.00 FS	*896.80 FS
2	1		*REAR BUMPER COVER	Dented	1,677.00 FS	*1,341.60 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	188.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Broken	1,151.00 FS	*920.80 FS
5	1		*REAR BUMPER SPOILER TRIM	Not Necessary	97.00 FS	*- FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	350.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	1,238.00 FS	*- FS
8	1		*REAR BUMPER HOLDING STRAP	Not Necessary	166.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	129.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION	Broken	58.00 FS	*45.76 FS
11	1		*REAR BUMPER SEAL-LH	Not Necessary	13.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	462.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
14	1		*REAR BUMPER WIRING SET	Not Necessary	594.00 FS	*- FS
15	1		*AUDI EMBLEM	Not Necessary	113.00 FS	*- FS
16	1		*Q7 INSCRIPTION	Not Necessary	87.00 FS	*- FS
17	1		*TFSI INSCRIPTION	Not Necessary	87.00 FS	*- FS
18	1		*QUATTRO INSCRIPTION	Not Necessary	87.00 FS	*- FS
19	1		*LED TAIL LIGHT	Not Necessary	1,750.00 FS	*- FS
20	1		*REAR CROSS PANEL	Not Necessary	577.00 FS	*- FS
21	1		*REAR CROSS PANEL REINFORCEMENT	Not Necessary	1,225.00 FS	*- FS
22	1		*CENTRE SILENCER	Dented	2,459.00 FS	*1,967.20 FS
23	1		*DUAL CLIP	Necessary	52.00 FS	*41.60 FS
24	1		*EXHAUST TAIL PIPE TRIM-LH	Cut	300.00 FS	*240.00 FS
25	2		*REAR WHEEL COVER-LH/RH	Necessary	688.00 FS	*550.40 FS
26	1		*WHEEL HOUSING LINER	Crumpled	298.00 FS	*238.40 FS
27	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
28	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
29	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
30	1		*SUNDRIES	Necessary	300.00 FS	*16.64 FS
31	1		*RETAINER FOR AERIAL	Bent	30.08 FS	*30.08 FS
32	1		*VENT TRIM	Broken	55.68 FS	*55.68 FS
33	1		*TAIL LIGHT-LH	Broken	326.00 FS	*260.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 16,190.76 6,605.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS REAR FENDER.TO CUT OUT AND REWELD END PANEL INNER AND END PANEL OUTER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,950.00	1,200.00
4	TO RESPRAY REAR BUMPER,REAR LOWER BUMPER,REAR LID,BOTH REAR WHEEL ARCH TRIMS,END PANELLING.LHS REAR FENDER AND SPARE WHEEL HOUSING.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	7,100.00	2,800.00
5	TO REMOVE AND RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	480.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>13,562.00</b>	<b>5,032.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >