

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000380/UKA3Q2

**Date:** 04/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900117541

**Claimant**  
**Vehicle No :** SJG8576Y **Insured Vehicle No :** SMN576C

Date of Loss: 07/01/2020 Nature of Claim: TP Claim No: 7993658494SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJG8576Y</b>		
Make & Model:	NISSAN SUNNY, 1.6 EX (M)	Engine No:	QG16431716
Reg. Date:	17/07/2008 (Man. Year: 2007)	Chassis No:	JN1CFAN16Z0113668
Colour:	Silver	Odometer:	176849 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,317.90	4,206.80	6,111.10	59.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,080.00	2,310.00	52.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,707.90</b>	<b>6,286.80</b>	<b>8,421.10</b>	<b>57.26</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,000.00</b>		
<b>(\$\$)</b>	14,707.90	5,000.00	9,707.90	66.00
<b>+ GST 7.00/7.00% (\$\$)</b>	1,029.55	350.00	679.55	66.00
<b>Nett Amount (\$\$)</b>	<b>15,737.45</b>	<b>5,350.00</b>	<b>10,387.45</b>	<b>66.00</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (\$\$)</b>		200.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>5,552.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,550.00</b>		

### INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	735.00 F	*613.30 FN
2	2		*BOOTLID HINGES	Not Necessary	210.00 F	*- FN
3	1		*BOOTLID REAR LOGO	Necessary	45.00 F	*45.00 FN
4	1		*BOOTLID SUNNY EMBLEM	Necessary	49.00 F	*49.00 FN
5	1		*BOOTLID EX SALOON EMBLEM	Necessary	92.00 F	*48.50 FN
6	1		*BOOTLID CVTC EMBLEM	Necessary	68.00 F	*46.20 FN
7	1		*BOOTLID THROTTLE EMBLEM	Necessary	70.00 F	*70.00 FN
8	1		*BOOTLID OUTER CHROME GARNISH TOP	Bent / Cracked	369.10 F	*369.10 FN
9	1		*BOOTLID OUTER CHROME GARNISH LOWER	Bent / Cracked	266.20 F	*208.90 FN
10	1		*BOOTLID INNER LOCK	Twisted	145.50 F	*109.20 FN
11	1		*BOOTLID WEATHERSTRIP	Torn	109.30 F	*109.30 FN
12	1		*BOOTLID LOCK STICKER	Not Necessary	68.00 F	*- FN
13	1		*BOOTLID INNER TRIM	Not Necessary	311.20 F	*- FN
14	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FN
15	1		*REAR BUMPER	Dented / Deformed	566.20 F	*452.50 FN
16	1		*REAR BUMPER CHROME MOULDING	Necessary	199.20 F	*175.20 FN
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FN
18	1		*REAR BUMPER BRACKETS	N/S Dented	173.20 F	*86.60 FN
19	1		*REAR BUMPER SPONGE	Not fitted	166.20 F	*- FN
20	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FN
21	2		*TAILLAMPS	Cracked	900.00 F	*720.40 FN
22	2		*TAILLAMP HOUSING PANELS	Repair	304.00 F	*- FN
23	1		*REAR END PANEL CENTRE TRIM	Torn	188.20 F	*125.30 FN
24	1		*REAR END PANEL	Badly Dented	462.00 F	*335.60 FN
25	1		*REAR END PANEL TOP GARNISH	Twisted	166.90 F	*66.50 FN
26	1		*REAR FLOOR PANEL	Repair	832.70 F	*- FN
27	1		*REAR FLOOR PANEL TOP BOARD	Torn	160.80 F	*160.80 FN
28	2		*REAR FENDERS	Repair	1,550.00 F	*- FN
29	2		*REAR FENDER INNER TRIMS	Torn	590.00 F	*530.60 FN
30	1		*REAR WINDSCREEN MOULDING	Not Necessary	145.20 F	*- FN
31	1		*REAR EXHAUST	Not Necessary	715.00 F	*- FN
32	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
34	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>10,317.90</b>	<b>4,642.00</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$)</b>	<b>0.00</b>	<b>435.20</b>
<b>Total Parts (\$)</b>	<b>10,317.90</b>	<b>4,206.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	150.00	60.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
<b>Gross Labour Cost (\$)</b>			<b>4,390.00</b>	<b>2,080.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**