



Your Ref : S0M02C8S

Date: 14th January 2020

Our Ref : CS/ASM20000382/Pqd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Kian Chuan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGK 8626B
ACCIDENT ON 31/12/2019**

Instruction was received to inspect the vehicle Reg. No. SGK 8626B. The inspection was conducted on 07/01/2020 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit) Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SGK 8626B
Make/Model	: Toyota Estima 2.4 AERAS A SIR
Year of Registration	: 2009
Body Colour	: Silver
Chassis Number	: ACR500077040
Engine Capacity	: 2362 cc
Speedometer Reading	: NIL

The vehicle sustained damages at the front windscreen, front o/s headlamp and engine damaged. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 69,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 32,981.00)
Nett Liability	<u>S\$ 36,019.00</u>

Vehicle Inspected By:



SHERWIN BEH SWEE YANG
Technical Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.