Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000383/ABS3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100278310 Policy No: Claimant **EP231G** Insured Vehicle No: SKC4201P Vehicle No:

Date of Loss: Nature of Claim: ΤP 31/12/2019 Claim No: 0153316029SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

EP231G Reg No:

Make & Model: SUBARU IMPREZA 5D, 2.0 I-S EYESIGHT (A) Engine No: FB20YE58774

Reg. Date: 03/10/2018 (Man. Year: 2018) Chassis No: JF1GT7KL5JG045996

Colour: White Odometer: 30247 km

Engine Capacity: 1995 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,502.07	2,865.60	1,636.47	36.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,230.00	480.00	28.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,212.07	4,095.60	2,116.47	34.07
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,212.07	3,200.00	3,012.07	48.49
+ GST 7.00/7.00% (S\$)	434.84	224.00	210.84	48.49
Nett Amount (S\$)	6,646.91	3,424.00	3,222.91	48.49
+ Car Rental (6.0 x S\$1	20.00/day) (S\$)	720.00		
Ne	tt Liability (S\$)	4,144.00		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 03/01/2020

Date Inspected: 03/01/2020 Inspected At: J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*SUBARU EMBLEM	Necessary	90.00 FL	*90.00 FL
1		*AWD EMBLEM	Necessary	68.00 FL	*68.00 FL
1		*LOGO EMBLEM	Necessary	90.00 FL	*90.00 FL
1		*EYESIGHT EMBLEM	Necessary	90.00 FL	*90.00 FL
1		*REAR BUMPER	Deformed	800.00 FL	*800.00 FL
2		*REAR BUMPER RETAINER	Necessary	72.00 FL	*72.00 FL
2		*REAR BUMPER HOLDER	Necessary	72.00 FL	*72.00 FL
1		*REAR BUMPER CLIPS (13 PCS)	Necessary	53.30 FL	*30.00 FL
2		*REAR BUMPER REFLECTOR	Not Necessary	70.00 FL	*- FL
1		*REAR BUMPER TOW HOOK COVER	Deformed	22.00 FL	*22.00 FL
4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	904.00 FL	*452.00 FL
2		*REAR BUMPER LOWER BRACKET	Not Necessary	72.00 FL	*- FL
1		*END PANEL	Dented	532.00 FL	*532.00 FL
1		*END PANEL INNER GARNISH	Not Necessary	118.00 FL	*- FL
1		*EXHAUST PIPE	Not Necessary	600.00 FL	*- FL
2		*TAILLAMP	Cracked	976.00 FL	*976.00 FL
1		*EXHAUST HEAT SHIELD	Not Necessary	85.00 FL	*- FL
1		*REAR BUMPER REINFORCEMENT	Bent	288.00 FL	*288.00 FL
nchise	part. L=ListI	temDisc.			
			()	5,002.30	3,582.00
- List Item Discount on L Items 10.00/20.00% (S\$)			500.23	716.40	
			Total Parts (S\$)	4,502.07	2,865.60
	1 1 1 1 1 2 2 1 4 2 1 1 1 1 2 1 1	1 1 1 1 1 2 2 1 1 4 2 1 1 1 1 2	1 *AWD EMBLEM 1 *LOGO EMBLEM 1 *EYESIGHT EMBLEM 1 *REAR BUMPER 2 *REAR BUMPER RETAINER 2 *REAR BUMPER HOLDER 1 *REAR BUMPER CLIPS (13 PCS) 2 *REAR BUMPER REFLECTOR 1 *REAR BUMPER TOW HOOK COVER 4 *REAR BUMPER REVERSE SENSOR 2 *REAR BUMPER LOWER BRACKET 1 *END PANEL 1 *END PANEL 1 *END PANEL INNER GARNISH 1 *EXHAUST PIPE 2 *TAILLAMP 1 *EXHAUST HEAT SHIELD 1 *REAR BUMPER REINFORCEMENT nchise part. L=ListItemDisc.	*SUBARU EMBLEM Necessary *AWD EMBLEM Necessary 1 *LOGO EMBLEM Necessary 1 *EYESIGHT EMBLEM Necessary 1 *REAR BUMPER Deformed 2 *REAR BUMPER RETAINER Necessary 2 *REAR BUMPER HOLDER Necessary 1 *REAR BUMPER CLIPS Necessary 1 *REAR BUMPER REFLECTOR Not Necessary 2 *REAR BUMPER REFLECTOR Deformed 4 *REAR BUMPER TOW HOOK COVER Deformed 4 *REAR BUMPER REVERSE SENSOR Damaged (2 PCS ONLY) 2 *REAR BUMPER LOWER BRACKET Not Necessary 1 *END PANEL Dented 1 *END PANEL INNER GARNISH Not Necessary 1 *EXHAUST PIPE Not Necessary 2 *TAILLAMP Cracked 1 *EXHAUST HEAT SHIELD Not Necessary 1 *EXHAUST HEAT SHIELD Not Necessary 1 *REAR BUMPER REINFORCEMENT Bent **Comparison of the model o	*SUBARU EMBLEM Necessary 90.00 FL

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	PANEL BEATING	New	800.00	600.00				
2	SPRAY PAINTING	New	800.00	600.00				
3	WIRING	New	30.00	30.00				
4	REMOVE & REFIT EXHAUST PIPE	New	80.00	0.00				
		Gross Labour Cost (S\$)	1,710.00	1,230.00				

Report was unsubmitted during this print-out.

< END OF ESTIMATES >