



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2004065
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE INV Date 21/05/2020
SINGAPORE 189556 Reference CS/INC20000384/Kyf3n2
ATTN: AIRWAN Code INC



PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 6137T
Insured Veh. SKB 6358M
Claim No. MT/1078516-002
Policy No.
Accident Date 04/01/2020
Inspection Date 07/01/2020

Description	Total
Damage Assessment	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000384/Kyf3n2

73 BRAS BASAH ROAD

Date: 21-05-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 6358M	Veh. Inspected	SMJ 6137T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078516-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	07/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VOXY (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800367313	Colour	METALLIC BLACK
Odometer	65847 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	9 mm
L/H Front Tyre	195/65 R15	MICHELIN	9 mm
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/01/2020	Inspect Date / Time	07/01/2020 (11:40 AM)
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 6137T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,876.20	-
1	REAR BUMPER DUST COVER	SERVICEABLE	195.20	-
1	REAR BUMPER REFLECTOR	SERVICEABLE	176.40	-
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	163.50	-
1	REAR FENDER PANEL	TO REPAIR SEE LABOUR	967.30	-
1	REAR TAIL LAMP APRON PANEL	TO REPAIR SEE LABOUR	456.30	-
	LESS 25% DISCOUNT		-958.72	-
			2,876.18	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
1	TUBE GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
			280.00	-
	<u>LABOUR</u>			
	TO REMOVE & REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT & REALIGN THE NECESSARY AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR FENDER PANEL AND REAR TAIL LAMP APRON PANEL.		500.00	350.00
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		800.00	700.00
	TO CHECK WIRING SYSTEM.		50.00	15.00
	TO INSTALL REVERSE SENSORS.	NOT NECESSARY	80.00	-
	TO REMOVE & REINSTALL SIDE GLASS TO ENABLE REPAIR.	NOT NECESSARY	140.00	-
	TO REMOVE & REINSTALL TRIMMING TO ENABLE REPAIR.		120.00	60.00
			1,690.00	1,125.00
	GRAND TOTAL		4,846.18	1,125.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,125.00

Report Ref No. CS/INC20000384/Kyf3n2



Report Ref No. CS/INC20000384/Kyf3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

A handwritten signature in black ink, appearing to be a stylized 'L' followed by a cursive 'K'.

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 6137T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

