

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000409/UES3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBD5473R **Insured Vehicle No :** SMN5099E

Date of Loss: 10/12/2019 **Nature of Claim:** TP **Claim No:** 5339081108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD5473R	Engine No:	1KD2463429
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y20K203933
Reg. Date:	27/11/2014 (Man. Year: 2014)	Odometer:	177833 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	OHTSU 5 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	OHTSU 5 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,193.51	5,305.24	3,888.27	42.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	2,350.00	1,700.00	41.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,243.51	7,655.24	5,588.27	42.20
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	13,243.51	6,100.00	7,143.51	53.94
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		6,664.00		
Global Sum Settlement (S\$)		6,530.00		

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At:

Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884
EUNOSVILLE
Singapore 400832

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	958.60 FL	*589.65 FL
2	1		*FRONT BUMPER REINFORCEMENT		189.20 FL	*- FL
3	1		*FRONT BUMPER BRACKET	Not Necessary	126.00 FL	*- FL
4	1		*FRONT LEFT HEADLAMP ASSY	Cracked	998.70 FL	*731.92 FL
5	1		*FRONT CENTRE GRILLE	Cracked	424.12 FL	*424.12 FL
6	1		*FRONT CENTRE GRILLE LOGO	Necessary	98.00 FL	*98.00 FL
7	1		*FRONT CENTRE GRILLE CLIPS	Not Necessary	60.00 FL	*- FL
8	1		*FRONT LEFT CORNER PANEL	Buckled	275.80 FL	*275.80 FL
9	1		*FRONT LEFT CORNER PANEL TOP GARNISH (BLACK)	Cracked	195.60 FL	*195.60 FL
10	1		*FRONT CENTRE PANEL	Dented	1,126.00 FL	*1,126.00 FL
11	1		*FRONT CENTRE PANEL EMBLEM (DYNA)	Necessary	70.35 FL	*70.35 FL
12	1		*FRONT CENTRE PANEL GARNISH (BLACK)	Not Necessary	275.60 FL	*- FL
13	1		*FRONT CENTRE PANEL GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
14	1		*FRONT LEFT DOOR	Buckled	1,349.30 FL	*1,349.30 FL
15	1		*FRONT LEFT DOOR TOP HINGE	Not Necessary	68.00 FL	*- FL
16	1		*FRONT LEFT DOOR LOWER HINGE	Not Necessary	58.00 FL	*- FL
17	1		*FRONT LEFT DOOR LINKAGE	Not Necessary	35.00 FL	*- FL
18	1		*FRONT LEFT STEP GARNISH	Cracked	472.50 FL	*472.50 FL
19	1		*FRONT LEFT WING MIRROR GARNISH	Cracked	425.60 FL	*425.60 FL
20	1		*FRONT LEFT WING MIRROR ROUND	Not Necessary	154.70 FL	*- FL
21	1		*AC CONDENSER	Punctured	986.20 FL	*986.20 FL
22	1		*AC FAN COWLING ASSY	Serviceable	565.30 FL	*- FL
23	1		*AC BLOWER MOTOR ASSY	Not Necessary	1,037.10 FL	*- FL
24	1		*AC EVAPORATOR ASSY	Not Necessary	1,786.40 FL	*- FL
25	1		*FRONT WINDSCREEN GLASS RUBBER	Necessary	288.61 FL	*288.61 FL
26	1		*FRONT DOOR COMPANY STICKER (ROC)	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,214.68	7,063.65
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,021.17	1,758.41
Total Parts (\$\$)	9,193.51	5,305.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, RENEW & INSTALL AFFECTED AREA	New	1,600.00	1,000.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	900.00
3	RE-CONNECT ALL ELECTRICAL WIRINGS	New	100.00	30.00
4	TO REMOVE & INSTALL FRONT DASHBOARD	New	250.00	200.00
5	TO VACUM & TOP UP AC GAS	New	150.00	100.00
6	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS	New	150.00	60.00
7	TO RUST PROOF AFFECTED AREAS	New	150.00	60.00
8	RE-PROGRAMME & RESET DIANOSTIC	New	250.00	0.00
Gross Labour Cost (S\$)			4,050.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >