



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1645Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER GRILLE AIR DUCT	CRACKED	80.50	80.50
1	FRONT BUMPER COVER	TORN	418.30	418.30
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,075.10	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	86.90	-
1	FRONT BUMPER CENTRE MOULDING	NOT NECESSARY	188.00	-
1	FRONT BUMPER GRILLE LH	NOT NECESSARY	186.90	-
1	FRONT BUMPER LIP	NOT NECESSARY	35.10	-
1	FRONT BUMPER BRACKET TOP	CRACKED	35.00	35.00
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	28.00	-
1	FRONT BUMPER SIDE BRACKET SUPPORT	NOT NECESSARY	12.00	-
1	FRONT FENDER LH	DENTED	490.70	490.70
1	FRONT FENDER SHIELD	NOT NECESSARY	114.70	-
1	FRONT HEADLAMP SUPPORT PANEL	CRACKED	949.30	949.30
1	FRONT HEADLAMP LH	CRACKED	1,198.80	1,198.80
1	FRONT HEADLAMP RH	NOT NECESSARY	1,198.80	-
1	FRONT HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	398.00	-
1	DAY LIGHT	MTG CRACKED	642.50	642.50
1	FRONT ENGINE UNDER COVER	NOT NECESSARY	469.40	-
1	FRONT WHEEL RIM LH	NOT NECESSARY	1,124.20	-
1	FRONT WHEEL HUB CAP LH	CUT	346.40	346.40
1	FRONT WHEEL BEARING	DAMAGED	454.00	454.00
1	FRONT SHOCK ABSORBER ASSY	DISTORTED	372.50	372.50
1	FRONT SHOCK ABSORBER MOUNTING	NOT NECESSARY	206.90	-
1	FRONT SUSPENSION LOWER ARM	DISTORTED	296.80	296.80
1	KNUCKLE ARM	DISTORTED	363.60	363.60
	LESS 20% DISCOUNT		-2,158.88	-1,134.08
			8,635.52	4,536.32

Report Ref No. CC4/FCI20000412/Dka3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	FRONT FENDER ADVERTISEMENT LOGO RH/LH (SN)	N/S NECESSARY / O/S NOT NECESSARY	200.00	100.00
1	FRONT TYRE (SN)	NOT NECESSARY	216.00	-
			416.00	100.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		900.00	500.00
	SPRAY PAINTING CHARGE.		800.00	400.00
	TUFF KOTE.		60.00	30.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	120.00	-
	FRONT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE /REFIX UNDERCARRIAGE (FRT).		280.00	150.00
	DIAGNOSE & RESETTING TO ERASE FAULT CODE.		480.00	180.00
			2,840.00	1,320.00
	<b>GRAND TOTAL</b>		<b>11,891.52</b>	<b>5,956.32</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,750.00</b>

Report Ref No. CC4/FCI20000412/Dka3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.