

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20000415/ESD3E2  
**Date:** 06/01/2021

### REFERENCE

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD Policy No: 0999994048  
Date of Loss: 04/01/2020 Nature of Claim: OD Claim No: 1502498549SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC2123G**  
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR090196  
Reg. Date: 30/08/2019 (Man. Year: 2019) Chassis No: WAUZZZ4M2KD030897  
Colour: Blue Odometer: 4616 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$244,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19  
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm  
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,588.00	5,328.96	2,259.04	29.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,252.00	5,252.00	3,000.00	36.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,840.00</b>	<b>10,580.96</b>	<b>5,259.04</b>	<b>33.20</b>
<b>- Excess (S\$)</b>	<b>1,800.00</b>	<b>1,800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>14,040.00</b>	<b>8,780.96</b>	<b>5,259.04</b>	<b>37.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>982.80</b>	<b>614.67</b>	<b>368.13</b>	<b>37.46</b>
<b>Nett Amount (S\$)</b>	<b>15,022.80</b>	<b>9,395.63</b>	<b>5,627.17</b>	<b>37.46</b>

### INSPECTION

Date of Assignment: 07/01/2020  
Date Inspected: 07/01/2020 Inspected At: 281 ALEXANDRA ROAD  
Estimated Period of Repair: 7.0 days Repairer : Premium Automobiles Pte Ltd

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Dented	1,481.00 FS	*1,184.80 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	69.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - RH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT FENDER BRACE - RH	Not Necessary	94.00 FS	*- FS
5	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	223.00 FS	*- FS
6	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	50.00 FS	*- FS
7	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,044.00 FS	*835.20 FS
8	1		*EXTERIOR MIRROR MOUNTING - RH	Cut	1,380.00 FS	*1,104.00 FS
9	1		*MIRROR CAP - RH	Not Necessary	160.00 FS	*- FS
10	1		*TURN SIGNAL INDICATOR - RH	Cut	149.00 FS	*119.20 FS
11	1		*FRONT DOOR WINDOW - RH	Cut	309.00 FS	*247.20 FS
12	1		*WINDOW GUIDE - RH	Bent	461.00 FS	*368.80 FS
13	1		*FRONT COVER TRIM - RH	Cut	354.00 FS	*283.20 FS
14	1		*FRONT ALUMINIUM RIM - RH	Cut	1,116.00 FS	*892.80 FS
15	1		*SUNDRIES	Necessary	300.00 FS	*2.56 FS
16	1		*FRONT 1/4 GLASS RHS	Cut	239.00 FS	*191.20 FS
17	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)7,588.005,328.96

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE FRONT BUMPER AND RENEW RHS FRONT FENDER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIMS, RENEW RHS FRONT DOOR GLASS AND WING MIRROR ASSY	New	800.00	500.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, WING MIRROR COVER AND WHEEL ARCH TRIMS	New	3,800.00	2,500.00
5	TO RENEW RHS FRONT DOOR GLASS SOLAR FILM (NPA)	New	0.00	0.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND RENEW RHS FRONT 1/4 GLASS	New	300.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,252.00</b>	<b>5,252.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >