Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000420/UKS3Q2

**Date:** 10/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: FBG5455C Insured Vehicle No: SMK8409R

Date of Loss: 25/12/2019 Nature of Claim: TP Claim No: 5725350867SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBG5455C

Make & Model: KTM 200 DUKE, 200cc Engine No: 0290607524

Reg. Date: 23/08/2012 (Man. Year: 2012) Chassis No: VBKJUC4C8CC008704

Colour: Orange/Black Odometer: 20374 km

Engine Capacity: 200 cc
Market Value/New Car

Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 120/60 ZR17 Rear Tyre Size: 160/60 ZR17
Front Left Side: Metzeler 7 mm Rear Left Side: Metzeler 7 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,606.50	203.50	1,403.00	87.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	330.00	150.00	180.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,936.50	353.50	1,583.00	81.75
Approved Total (Overridden) (S\$)		280.00		
Nett Amount (S\$)	1,936.50	280.00	1,656.50	85.54
+ Loss of Use (4.0 x S\$2	20.00/day) (S\$)	80.00		
Net	tt Liability (S\$)	360.00		

**INSPECTION** 

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At: Erofia Motor Trading Pte Ltd - (kaki

Bukit) (HQ)

1 Kaki Bukit Avenue 6, #02-62

AutoBay @ Kaki Bukit Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR FENDER	Warped	130.00 FL	*130.00 FL		
2	1		*REAR NUMBER LIGHT	Cracked	85.00 FL	*85.00 FL		
3	1		*REAR LAMP	Not Necessary	120.00 FL	*-FL		
4	1		*REAR TYRE	Not Necessary	280.00 FL	*-FL		
5	1		*REAR SWING ARM	Serviceable	450.00 FL	*- FL		
6	2		*REAR BRAKE DISC	Not Necessary	250.00 FL	*-FL		
7	1		*REAR RIM SHAFT	Not Necessary	45.00 FL	*-FL		
8	3		*REAR RIM BEARING	Not Necessary	90.00 FL	*-FL		
9	1		*REAR RIM	Not Necessary	320.00 FL	*-FL		
10	1		*REAR NUMBER PLATE	Bent	13.50 FS	*10.00 FS		
F=Franchise part. S=SpcNett. L=ListItemDisc.								
	Sub Total (S\$)			1,783.50	225.00			
- List Item Discount on L Items 10.00/10.00% (S\$)			177.00	21.50				
Total Parts (S\$)			1,606.50	203.50				
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING	New	50.00	0.00
2	TO PROVIDE LABOUR	New	280.00	150.00
		Gross Labour Cost (S\$)	330.00	150.00
	Re	port was unsubmitted during this print-out.		

< END OF ESTIMATES >