

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000435/UES3Q2
Date: 27/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLH5693H	Insured Vehicle No :	SMA1562D
Date of Loss:	31/12/2019	Nature of Claim:	TP
		Claim No:	5062396843SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH5693H		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1852895
Reg. Date:	10/11/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W80J005855
Colour:	White	Odometer:	128437 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	MAXIMUM 6 mm	Rear Left Side:	MAXIMUM 6 mm
Front Right Side:	MAXIMUM 6 mm	Rear Right Side:	MAXIMUM 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,424.65	6,129.40	3,295.25	34.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,670.00	660.00	28.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,754.65	7,799.40	3,955.25	33.65
Approved Total (Overridden) (S\$)		6,200.00		

(S\$)	11,754.65	6,200.00	5,554.65	47.25
+ GST 7.00/7.00% (S\$)	822.83	434.00	388.83	47.26
Nett Amount (S\$)	12,577.48	6,634.00	5,943.48	47.25
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020

Estimated Period of Repair: 5.0 days

Inspected At: Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SUPPORT PANEL	Repair	1,559.60 FL	*- FL
2	1		*FRONT SUPPORT PANEL TOP GARNISH	Torn	361.90 FL	*361.90 FL
3	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPSE	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT FENDER -RH	Distorted	796.90 FL	*796.90 FL
5	1		*FRONT FENDER DUST COVER -RH	Torn	169.00 FL	*169.00 FL
6	8		*FRONT FENDER DUST COVER CLIP-RH	Necessary	44.00 FL	*44.00 FL
7	1		*FRONT WHEEL HOUSING PANEL -RH	Badly Dented	481.90 FL	*481.90 FL
8	1		*FRONT HEAD LAMP -RH (HID)	Broken	1,399.80 FL	*1,399.80 FL
9	1		*FRONT HEAD LAMP HID BALLAST RH	Damaged	720.10 FL	*720.10 FL
10	1		*FRONT GRILLE	Cracked	391.60 FL	*391.60 FL
11	1		*FRONT WASHER TANK	Distorted	169.80 FL	*169.80 FL
12	1		*FRONT WASHER TANK MOTOR	Cracked	265.00 FL	*265.00 FL
13	1		*FRONT RADIATOR SPARE TANK	Deformed	195.80 FL	*195.80 FL
14	1		*FRONT BUMPER	Distorted	899.60 FL	*566.20 FL
15	1		*FRONT BUMPER INNER SPONGE	Torn	97.60 FL	*97.60 FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	391.60 FL	*- FL
17	1		*FRONT BUMPER SIDE RETAINER -RH	Cracked	81.50 FL	*81.50 FL
18	1		*FRONT BUMPER FOG LAMP -RH	Broken	319.60 FL	*319.60 FL
19	1		*FRONT BUMPER FOG LAMP COVER -RH	Torn	121.90 FL	*121.90 FL
20	1		*FRONT BUMPER FOG LAMP CHROME COVER -RH	Missing	151.60 FL	*151.60 FL
21	1		*FRONT BUMPER LOWER SIDE GRILLE	Torn	55.60 FL	*55.60 FL
22	1		*FRONT A.B.S BUMPER	Not Necessary	1,242.60 FL	*- FL
23	1		*FRONT SHOCK ABSORBER -RH	Not Necessary	399.80 FL	*- FL
24	1		*FRONT KNUCKLE ARM -RH	Bent	561.90 FL	*561.90 FL
25	1		*FRONT LOWER ARM -RH	Bent	487.60 FL	*487.60 FL
26	1		*FRONT HUB BEARING	Necessary	155.90 FL	*155.90 FL
27	1		*FRONT SPORT RIM -RH	Cut / Bent	750.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,316.20	8,039.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,891.55	1,909.80
Total Parts (\$\$)	9,424.65	6,129.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	20.00
2	PANEL BEATING	New	950.00	600.00
3	CHECK WIRING AND DIAGNOSE TEST	New	150.00	50.00
4	ALIGNMENT ADJUSTMENT	New	50.00	50.00
5	RUST PROOFING	New	60.00	30.00
6	TO REMOVE & REPLACE FRONT UNDER CARRIAGE	New	250.00	120.00
7	TO SPRAY PAINTING	New	820.00	800.00
Gross Labour Cost (S\$)			2,330.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >