

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000442/HBA3N2

Date: 22/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMD222B **Insured Vehicle No :** SMD1577X

Date of Loss: 18/12/2019 **Nature of Claim:** TP **Claim No:** 2210640904SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD222B		
Make & Model:	HONDA JAZZ, 1.5 (A)	Engine No:	L15B33114345
Reg. Date:	13/08/2018 (Man. Year: 2018)	Chassis No:	JHMGK5850JX208453
Colour:	Silver	Odometer:	45873 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,500.88	1,057.44	1,443.44	57.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	950.00	1,330.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,780.88	2,007.44	2,773.44	58.01
+ GST 7.00/7.00% (S\$)	334.66	140.52	194.14	58.01
Nett Amount (S\$)	5,115.54	2,147.96	2,967.58	58.01
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,684.96		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 06/01/2020

Date Inspected: 06/01/2020 Inspected At:

Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	985.00 FL	*850.80 FL
2	1		*REAR BOOT LID JAZZ EMBLEM	Necessary	65.00 FL	*65.00 FL
3	1		*REAR BOOT LID MECHANISM LOCK	Serviceable	218.90 FL	*- FL
4	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	92.30 FL	*- FL
5	1		*REAR BUMPER ASSY	Repair	549.70 FL	*- FL
6	2		*REAR BUMPER SIDE HOLDER L/R	Serviceable	56.00 FL	*- FL
7	1		*REAR END PANEL	Repair	350.90 FL	*- FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	158.30 FL	*118.50 FL
9	1		*SET WINDSCREEN SEALANT	Necessary	40.00 FS	*30.00 FS
10	1		*SET REVERSE SENSOR	Shorted	480.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,996.10	1,264.30
- List Item Discount on L Items 20.00/20.00% (\$)	495.22	206.86
Total Parts (\$)	2,500.88	1,057.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE,REINSTAL FRT WINDSCREEN	New	200.00	120.00
3	TO REMOVE REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
4	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,280.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >