

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000447/T1DA3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100425647-04

Claimant
Vehicle No : SKW2618D **Insured Vehicle No :** GBE393R

Date of Loss: 03/01/2020 **Nature of Claim:** TP **Claim No:** 4395891472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW2618D		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK056164
Reg. Date:	28/03/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49JA121727
Colour:	Grey	Odometer:	51560 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,846.38	6,507.95	9,338.43	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,610.00	1,940.00	54.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,396.38	8,117.95	11,278.43	58.15
Approved Total (Overridden) (\$\$)		6,450.00		
(\$\$)	19,396.38	6,450.00	12,946.38	66.75
+ GST 7.00/7.00% (\$\$)	1,357.75	451.50	906.25	66.75
Nett Amount (\$\$)	20,754.13	6,901.50	13,852.63	66.75
+ Car Rental (5.0 x S\$120.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		7,537.95		

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,863.63 FL	*1,612.00 FL
2	1		*REAR BUMPER RETAINER	Not Necessary	74.04 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	748.25 FL	*748.25 FL
4	1		*REAR BUMPER BRACKET	Necessary	92.40 FL	*92.40 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	126.60 FL	*- FL
6	1		*REAR BUMPER LOWER LIP	Not Necessary	706.00 FL	*- FL
7	1		*END PANEL	Repair	714.72 FL	*- FL
8	1		*END PANEL TOP GARNISH	Deformed	248.74 FL	*248.74 FL
9	2		*REAR EXHAUST SILENCER	Not Necessary	2,298.50 FL	*- FL
10	2		*REAR EXHAUST MOUNTING	Not Necessary	175.80 FL	*- FL
11	1		*BOOTLID	Bent	2,207.60 FL	*1,564.00 FL
12	1		*BOOTLID LOCK	Bent	260.38 FL	*260.38 FL
13	1		*BOOTLID LOCK STRIKER	Not Necessary	35.48 FL	*- FL
14	1		*BOOTLID WEATHERSTRIP	Twisted	173.34 FL	*173.34 FL
15	1		*BOOTLID EMBLEM -LOGO	Necessary	107.70 FL	*107.70 FL
16	1		*BOOTLID INNER TRIM	Not Necessary	331.60 FL	*- FL
17	2		*BOOTLID LAMP	Cracked	1,584.82 FL	*938.40 FL
18	2		*TAILLAMP	Not Necessary	1,604.48 FL	*- FL
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*SET END PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
21	1		*SET REVERSE SENSOR	Not Working	800.00 FS	*300.00 FS
22	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
23	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
24	1		*REVERSE XAMERA	Not Necessary	500.00 FS	*- FS
25	1		*REAR NUMBER PLATE LAMP	Distorted	120.00 FS	*120.00 FS
26	1		*REAR BUMPER DIFFUSAL (AFTER MARKET)	Deformed	1,500.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,514.08	6,795.21
- List Item Discount on L Items 5.00/5.00% (\$\$)	667.70	287.26
Total Parts (\$\$)	15,846.38	6,507.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
4	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
5	REMOVE AND RENEW FLOOR INSULATOR	New	120.00	0.00
6	REMOVE AND RENEW FUEL TANK	New	120.00	0.00
7	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	700.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	700.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$)			3,550.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >