

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000460/ATF3E2

Date: 22/06/2020

REFERENCE

Insured/Claimant:	LEONG CHUEN TUCK	Policy No:	1900113392	
Date of Loss:	04/01/2020	Nature of Claim:	OD	Claim No: 0678746212SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5070S			
Make & Model:	AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)	Engine No:	CHZB23421	
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V4KA080785	
Colour:	Black	Odometer:	9952 km	
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$113,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,233.60	18,156.64	22,076.96	54.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	46,624.00	20,009.00	26,615.00	57.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	86,857.60	38,165.64	48,691.96	56.06
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	86,257.60	37,565.64	48,691.96	56.45
+ GST 7.00/7.00% (\$\$)	6,038.03	2,629.59	3,408.44	56.45
Nett Amount (\$\$)	92,295.63	40,195.23	52,100.40	56.45

INSPECTION

Date of Assignment:	07/01/2020	
Date Inspected:	07/01/2020	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	28.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,698.00 FS	*1,358.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH / RH	O/S Damaged	70.00 FS	*27.52 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMNET - LOWER CENTRE	Not Necessary	270.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	O/S Damaged	540.00 FS	*216.00 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	172.00 FS	*137.60 FS
12	1		*FOAM FILLER PIECE COVER	Not Necessary	111.00 FS	*- FS
13	1		*SIGNAL HORN - RH LOW TONE	Damaged	182.00 FS	*145.60 FS
14	1		*FRONT FENDER - LH / RH	O/S Distorted / N/S Repair	1,556.00 FS	*622.00 FS
15	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
16	1		*FRONT FENDER BRACKET - RH	Distorted	25.00 FS	*19.76 FS
17	1		*FRONT FENDER BRACKET - RH	Distorted	43.00 FS	*34.08 FS
18	1		*FRONT FENDER INSULATION - RH	Distorted	38.00 FS	*29.84 FS
19	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	30.00 FS	*23.76 FS
20	1		*FRONT FENDER INSULATION SEAL - RH	Damaged	31.00 FS	*24.40 FS
21	1		*FRONT FENDER BRACE	Distorted	88.00 FS	*69.84 FS
22	1		*FRONT FENDER CLOSING ELEMENT - RH	Distorted	56.00 FS	*44.24 FS
23	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	158.00 FS	*126.00 FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
25	1		*BONNET	Distorted	2,501.00 FS	*2,000.80 FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
27	2		*BONNET LIF HINGE - LH / RH	Not Necessary	112.00 FS	*- FS
28	1		*SIDE SEAL - RH	Not Necessary	37.00 FS	*- FS
29	1		*BONNET GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
30	1		*BONNET EDGE PROTECTION - FRONT	Necessary	25.00 FS	*19.92 FS
31	1		*BONNET CATCH HOOK	Necessary	81.00 FS	*64.72 FS
32	2		*BONNET STRIKER - LH / RH	Not Necessary	200.00 FS	*- FS
33	1		*WATER BOX ADAPTER SEAL - RH	Not Necessary	12.00 FS	*- FS
34	2		*BONNET LID LOCK	Not Necessary	367.00 FS	*- FS
35	2		*CONNECTOR HOUSING BRACKET	Not Necessary	11.00 FS	*- FS
36	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
37	1		*BONNET LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
38	1		*BONNET BRACKET	Not Necessary	35.00 FS	*- FS
39	1		*PLENUM CHAMBER COVER	Not Necessary	164.00 FS	*- FS
40	1		*BONNET SOUND ABSORBER	Not Necessary	201.00 FS	*- FS
41	1		*BONNET ACTUATING LEVER	Not Necessary	45.00 FS	*- FS
42	1		*FRONT END PLATE - RH	Bent	68.00 FS	*53.76 FS
43	1		*LED HEADLIGHT - RH	Smashed	5,029.00 FS	*4,023.20 FS
44	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	693.00 FS	*- FS
45	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	508.00 FS	*- FS
46	1		*LED WITH HEAT SINK - RH	Not Necessary	666.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*HEADLAMP REPAIR KIT	Not Necessary	120.00 FS	*- FS
48	1		*HEADLIGHT HOSE - RH	Not Necessary	36.00 FS	*- FS
49	1		*LIFT CYLINDER - RH	Not Necessary	128.00 FS	*- FS
50	1		*HEADLIGHT HOSE	Not Necessary	61.00 FS	*- FS
51	1		*LOCK CARRIER	Deformed	663.00 FS	*530.40 FS
52	4		*READY MIX COOLANT	Not Necessary	165.00 FS	*- FS
53	1		*RADIATOR AIR GUIDE - RH	Not Necessary	22.00 FS	*- FS
54	1		*FRONT DOOR - RH	Repair	2,073.00 FS	*- FS
55	1		*FRONT DOOR OUTER SEAL	Not Necessary	146.00 FS	*- FS
56	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
57	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
58	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
59	1		*TYRE PRESSURE DATA PLATE	Not Necessary	26.00 FS	*- FS
60	1		*FRONT DOOR - LH	Repair	2,073.00 FS	*- FS
61	1		*FRONT DOOR OUTER SEAL - LH	Not Necessary	146.00 FS	*- FS
62	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
63	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
64	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
65	1		*REAR DOOR - LH	Dented	2,073.00 FS	*1,658.40 FS
66	1		*REAR DOOR OUTER SEAL	Necessary	146.00 FS	*116.80 FS
67	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
68	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.68 FS
69	1		*REAR DOOR CATCH	Not Necessary	85.00 FS	*- FS
70	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	117.00 FS	*- FS
71	2		*WINDOW SLOT SEAL - LH FRONT / REAR	Not Necessary	494.00 FS	*- FS
72	1		*WATER REFLECTOR STRIP - LH / RH	N/S Cut	122.00 FS	*48.72 FS
73	1		*ROOF MOLDING - LH	Not Necessary	537.00 FS	*- FS
74	1		*CORNER TRIM - LH	Cut	41.00 FS	*32.80 FS
75	1		*B PILLAR TRIM - LH	Cut	88.00 FS	*70.24 FS
76	1		*B PILLAR TRIM - LH	Cut	105.00 FS	*83.60 FS
77	16		*CLIP	Necessary	12.00 FS	*8.96 FS
78	1		*OUTER SIDE PANEL FRAME - LH	Dented	3,004.00 FS	*2,403.20 FS
79	1		*REAR WINDSCREEN	Not Necessary	742.00 FS	*- FS
80	1		*PRIMER	Necessary	19.00 FS	*14.88 FS
81	1		*SIDE WINDOW - LH	Necessary	267.00 FS	*213.20 FS
82	1		*REAR SIDE WINDOW TRIM STRIPS - LH	Not Necessary	239.00 FS	*- FS
83	1		*WHEEL HOUSING LINER - LH	Not Necessary	223.00 FS	*- FS
84	1		*EXTERIOR MIRROR MOUNTING - LH	Distorted	938.00 FS	*750.40 FS
85	1		*MIRROR CASP - LH	Missing	136.00 FS	*108.80 FS
86	1		*MIRROR GLASS - LH	Missing	1,132.00 FS	*905.60 FS
87	1		*ALUMINIUM RIM (3PCS)	Cut (2Pcs Only)	1,953.00 FS	*1,041.60 FS
88	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
89	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*- FS
90	1		*ACRYLIC SEALANT	Necessary	360.00 FS	*180.00 FS
91	1		*CAVITY WAX	Necessary	280.00 FS	*140.00 FS
92	1		*STONE CHIP	Necessary	360.00 FS	*180.00 FS
93	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
94	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
95	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
96	1		*SUNDRIES	Necessary	800.00 FS	*124.40 FS
97	1		*FLAT CONTACT HOUSING WITH CONTACT LOCKING MECHANISM 2 PIN	Cracked	12.88 FS	*12.88 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*FLAT CONTACT HOUSING WITH CONTACT LOCKING MECHANISM 14 PIN	Cracked	22.72 FS	*22.72 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					40,233.60	18,156.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TECT ON CAR O-LINER	New	800.00	0.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	0.00
5	TO PLACE VEHICLE ON CAR O-LINER	New	1,800.00	0.00
6	TO REMOVE AND TRANSFER RHS FRONT DOOR, LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	840.00	280.00
7	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY. TO RENEW LHS WING MIRROR ASSY	New	600.00	600.00
8	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	300.00
9	TO INSTALL REAR WINDSCREEN GLASS SOLAR FILM	New	400.00	0.00
10	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
11	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS HEADLIGHTS, RHS FRONT DOOR, LHS FRONT DOOR, LHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND REWELD RHS FENDER SUPPORT AND CLOSING ELEMENT, LHS REAR FENDER, LHS SILL PANEL AND LHS B-PILLAR. TO RENEW FRONT BUMPER, BONNET BOTH FRONT FENDERS, RHS HEADLIGHT, BOTH FRONT DOORS AND LHS REAR DOOR. }	New	16,800.00	6,500.00
12	RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED }	New	0.00	0.00
13	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BOTH UPPER A-PILLAR, ENGINE COMPARTMENT, LHS FRONT FENDER TOP SUPPORT, BOTH FRONT DOORS, BOTH REAR DOORS, DOOR HANDLES, LHS WING MIRROR COVER, LHS REAR FENDER, LHS SILL PANEL, LHS B-PILLAR, DOOR ENTRANCES, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	14,000.00	7,025.00
14	TO RENEW RHS FRONT RIM, LHS FRONT RIM, LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	360.00	360.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
16	TO RENEW 1/4 GLASS SOLAR FILM	New	200.00	200.00
17	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS	New	2,800.00	0.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
18	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
19	TO DISLODGE ABCD REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
Gross Labour Cost (S\$)			46,624.00	20,009.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >