

**REPAIR DETAILS**

**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)  
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ComfortDelGro Engineering Pte Ltd/SHC7652L/07/01/2020 19:40  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	①	*BOOTLID DD			
2	1		*BOOTLID RUBBER <i>2xnn</i>	20.00	0.00	*2,480.40 FL
3	1		*BOOTLID HINGE LH <i>1xnn</i>	20.00	0.00	*127.40 FL
4	1		*BOOTLID HINGE RH <i>1xnn</i>	20.00	0.00	*31.30 FL
5	1		*BOOTLID LOCK UPPER <i>1xnn</i>	20.00	0.00	*31.30 FL
6	1		*BOOTLID KEY LOCK <i>xnn</i>	20.00	0.00	*224.00 FL
7	1		*BOOTLID H EMBLEM <i>1xnn</i>	20.00	0.00	*141.00 FL
8	1		*BOOTLID CRDI PLATE <i>1xnn</i>	20.00	0.00	*28.00 FL
9	1	③	*BOOTLID HYBRID EMBLEM <i>1xnn</i>	20.00	0.00	*58.00 FL
10	1	③	*BOOTLID IONIQ EMBLEM <i>1xnn</i>	20.00	0.00	*24.30 FL
11	1		*ASSY BSD-BLIND SPOT RADAR <i>2xnn</i>	20.00	0.00	*31.30 FL
12	1	④	*BOOTLID COMFORT LOGO <i>1xnn</i>	20.00	0.00	*758.50 FL
13	1	⑤	*BOOTLID TEL. NO STICKER <i>1xnn</i>	0.00	0.00	*30.00 F
14	1	⑥	*BOOTLID APPS STICKER <i>1xnn</i>	0.00	0.00	*30.00 F
15	1	⑦	*BOOTLID GLASS UPPER <i>1xnn</i>	0.00	0.00	*40.00 F
16	1	⑧	*BOOTLID GLASS LOWER <i>1xnn</i>	20.00	0.00	*543.30 FL
17	2	⑩	*REAR WINDSCREEN SEALANT <i>1xnn</i>	20.00	0.00	*384.90 FL
18	1		*REAR SPOILER <i>xnn</i>	0.00	0.00	*46.00 F
19	1		*BOOTLID LAMP LH <i>xnn</i>	20.00	0.00	*665.40 FL
20	1		*BOOTLID LAMP RH <i>2xnn</i>	20.00	0.00	*794.40 FL
21	1		*BOOTLID TRIMBOARD <i>xnn</i>	20.00	0.00	*794.40 FL
22	1	⑩	*LICENCE LAMP COVER <i>1xnn</i>	20.00	0.00	*159.70 FL
23	1	⑩	*REAR NO. PLATE <i>1xnn</i>	20.00	0.00	*35.10 FL
24	1		*REAR NO. PLATE TRIM COVER <i>1xnn</i>	0.00	0.00	*25.00 F
25	10		*BOOTLID TRIMBOARD CLIPS <i>xnn</i>	0.00	0.00	*30.00 F
26	1		*BOOTLID GLASS MOULDING <i>1xnn</i>	20.00	0.00	*11.00 FL
27	1		*BOOTLID GARNISH <i>xnn</i>	20.00	0.00	*28.30 FL
28	1		*BOOTLID LOWER GARNISH <i>xnn</i>	20.00	0.00	*36.10 FL
29	1	⑨	*REAR BUMPER <i>1xnn</i>	20.00	0.00	*25.40 FL
30	1	⑨	*REAR BUMPER REINFORCEMENT <i>1xnn</i>	20.00	0.00	*459.40 FL
31	1	⑨	*REAR BUMPER REINFORCEMENT BRACKET LH <i>1xnn</i>	20.00	0.00	*294.80 FL
32	1	⑨	*REAR BUMPER REINFORCEMENT BRACKET RH <i>1xnn</i>	20.00	0.00	*138.10 FL
33	1	⑩	*REAR BUMPER CENTRE MOULDING ASSY <i>1xnn</i>	20.00	0.00	*138.10 FL
34	1	⑩	*REAR BUMPER LOWER CENTRE MOULDING ASSY <i>1xnn</i>	20.00	0.00	*451.25 FL
35	1		*REAR BUMPER SIDE BRACKET LH <i>xnn</i>	20.00	0.00	*47.50 FL
36	1		*REAR BUMPER SIDE BRACKET RH <i>xnn</i>	20.00	0.00	*33.10 FL
37	10	⑫	*REAR BUMPER CLIPS <i>1xnn</i>	20.00	0.00	*33.10 FL
38	1		*REAR BUMPER UNDER CENTRE <i>1xnn</i>	20.00	0.00	*22.00 FL
39	1		*REAR BUMPER REFLECTOR LH <i>1xnn</i>	20.00	0.00	*53.85 FL
40	1		*REAR BUMPER REFLECTOR RH <i>xnn</i>	20.00	0.00	*31.90 FL
41	1	⑬	*REAR BUMPER FOG LAMP ASSY <i>1xnn</i>	20.00	0.00	*31.90 FL
42	1		*REAR BUMPER TOWING COVER <i>xnn</i>	20.00	0.00	*201.50 FL
43	1		*REAR BUMPER REVERSE SENSOR <i>1xnn</i>	20.00	0.00	*98.80 FL
44	1	⑬	*REAR PANEL <i>1xnn</i>	0.00	0.00	*135.70 F
45	1		*REAR PANEL GARNISH <i>xnn</i>	20.00	0.00	*532.00 FL
				20.00	0.00	*57.70 FL

ComfortDelGro Engineering Pte Ltd/SHC7652L/07/01/2020 19:40. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*SPARE TYRE HOLDER <i>xms</i>	20.00	0.00	*223.10 FL
			F=Franchise part. L=ListItemDisc.			
				<b>Sub Total (S\$)</b>		<b>10,598.30</b>
				<b>- List Item Discount on L Items (S\$)</b>		<b>2,052.32</b>
				<b>Total Parts (S\$)</b>		<b>8,545.98</b>

ComfortDelGro Engineering Pte Ltd/SHC7652L/07/01/2020 19:40. Not valid without Reference section.  
Generated using Merlmen e-Claims IEAS

LKK Auto Care (Singapore) Pte Ltd  
 the Repairs and Maintenance of  
 • Tyres and wheels (including painting)  
 • Oil and filter services (including resurvey)  
 • Fluids and top-ups (including oil change)  
 • Third party vehicle hire (with or without basis)  
 • No liability for any loss or damage  
 • Supplementary services are not included and  
 is subject to final approval from insurance company.  
 Authorized by Repater  
 Sign:  
 Date:

# Estimates on Miscellaneous Items

No Qty Particulars

Amount

## Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

# Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

*Merimen charge*

1 PANEL PANEL

New

\$1280 1,800.00

2 SPRAY PAINTING CHARGE

New

\$600 900.00

3 WIRING CHARGE

New

50.00

4 TUFF KOTE

New

50.00

5 TOWING FEE CHARGE

New

\$60 60.00

6 REMOVE/REFIX REAR WINDSCREEN GLASS

New

\$80 150.00

7 REMOVE/REFIX REVERSE SENSOR

New

\$50 120.00

8 RESET BSD-BLIND SPOT RADAR

New

\$480 480.00

Gross Labour Cost (S\$)

3,610.00

ComfortDelGro Engineering Pte Ltd/SHC7652L/07/01/2020 19:40. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*J. Kam (LKK)*  
*08/01/2020*  
*1630 hrs*  
*P. Ganesan @ LKK auto.com*  
*REF 22TB*  
*BEF paint plus*  
*5 days*

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**(SUPPLEMENTARY)**

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CCPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MK000574	Date of Loss:	04/01/2020
Vehicle Reg. No.:	<b>SHC7652L</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	14/11/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU387389	Chassis No:	KMHC851CVLU183489
Odometer:	19253 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	32.40
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>32.40</b>
<b>+ GST 7.00% (S\$)</b>	<b>2.27</b>
<b>Nett Amount (S\$)</b>	<b>34.67</b>
<b>+ Previous Estimates (S\$)</b>	<b>13,018.67</b>
<b>Claim Total (S\$)</b>	<b>13,053.34</b>

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

**ComfortDelGro Engineering Pte Ltd/SHC7652L/04/02/2020 08:48**. Not valid without Reference section.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305372609  
Date : 30.01.20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : Mr RAM  
Vehicle Reg No. SHC7652L CCPL

Fax :  
04.01.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLQ5707E
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	\$4,750.08
(b) Labour Charges	\$2,181.00
<b>Total for Part-By-Part Repair Cost</b>	<b>\$6,931.08</b>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	
<b>Final Lumpsum Repair cost</b>	
3. Estimated normal period for repairs: 5 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : RAM  
Date : 15/2/2020

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305372609  
 REGN NO : SHC7652L  
 MILEAGE : 000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 14.11.2019  
 DATE/TIME IN : 04.01.2020 23:00  
 ACCIDENT DATE : 04.01.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2256-G	IONIQVC PANEL ASSY-TAIL G	1 L	2,480.40	20.00	1,984.32	pp
0002	04-01-0104-2270-G	IONIQ EMBLEM-HYBRID	1 L	24.30	20.00	19.44	rec
0003	04-01-0104-2271-G	IONIQ EMBLEM-IONIQ	1 L	31.30	20.00	25.04	rec
0004	28-01-0103-0009-A	(I40)REAR BOOT LOGO CCTPL	1 N	30.00	2.00-	30.00	rec
0005	28-01-0103-0010-A	(I40)REAR BOOT TEL NUMBER	1 N	30.00	0.20	30.00	rec
0006	28-01-9999-2026-A	APP LOGO REAR BONNET CCPL	1 N	40.00	0.02-	40.00	rec
0007	04-01-0104-2257-G	IONIQ GLASS ASSY-TAIL GAT	1 L	384.90	20.00	307.92	rec
0008	04-01-0104-2258-G	IONIQ GLASS ASSY-TAIL GAT	1 L	543.30	20.00	434.64	rec
0009	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	ora
0010	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1 L	451.25	20.00	361.00	ora
0011	04-01-0104-2288-G	IONIQ BEAM-RR BUMPER	1 L	294.80	20.00	235.84	Bu
0012	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	rec
0013	04-01-0104-2346-G	IONIQ PANEL ASSY-BACK	1 L	532.00	20.00	425.60	Bu

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305372609  
 REGN NO : SHC7652L  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 14.11.2019  
 DATE/TIME IN : 04.01.2020 2:  
 ACCIDENT DATE : 04.01.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 FNPS NO PLATE(S) WITH TRIM COV	1	N	55.00	2.00-	55.00 <i>crab</i>
0015 04-01-0104-3819-G IONIQ STAY-RR BUMPER LH	1	L	138.10	20.00	110.48 <i>Bt</i>
0016 04-01-0104-2370-G IONIQ LAMP ASSY-REAR FOG	1	L	201.50	20.00	161.20 <i>crab</i>
0017 04-01-0104-2545-G IONIQVC MOULDING-REAR BUM	1	L	47.50	20.00	38.00 <i>Br</i>
0018 09-01-0104-2133-G IONIQ ANTENNA ASSY-SMARTK	1	L	40.50	20.00	32.40 <i>Br</i>
0019 04-01-0104-2226-G IONIQVC LAMP ASSY-LICENSE	1	L	35.10	20.00	28.08 <i>crab</i>
0020 05-01-0199-0032-A (ALL)WINDSCREEN AHESIVE-3	2	N	46.00	2.00-	46.00 <i>nee</i>

SUB-TOTAL : 4,750.08

4750.08

## JOB NATURE

0000 23-01	TOWING FEE	60.00
0001 L	MERIMEN CHARGE	11.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305372609  
 REGN NO : SHC7652L  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 14.11.2019  
 DATE/TIME IN : 04.01.2020 23:00  
 ACCIDENT DATE : 04.01.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 L	PANEL BEATING	1280.00				
0003 23-502	SPRAYPAINT ON AFFECTED AREA	600.00				
0004 17-01	CHECK ALL LIGHTING	50.00				
0005 20-00	TUFF COAT ON AFFECTED PARTS.	50.00				
0006 20-20	REMOVE/REFIX RR W/SCREEN TO ASST R/P	80.00				
0007 L	REMOVE/REFIX REVERSE SENSOR	50.00				
SUB-TOTAL :						2,181.00
TOTAL :						6,931.08

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2020 18:48	07 Jan 2020 19:40	08 Jan 2020 10:53	<b>S\$6,931.08</b>	<b>S\$6,931.08</b>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
	<a href="#">Sendback Est</a>	<b>S\$12,166.98</b>	<a href="#">Edit Adj Rpt</a>	<a href="#">Edit Estimates</a>	<a href="#">View Rpt</a>		
Supp #1	04 Feb 2020 08:45	04 Feb 2020 08:48	04 Feb 2020 08:48			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	CCPL, Co. Reg. No.: 199303839G		
Main Claimant:	CCPL		
Vehicle Reg. No.:	SHC7652L	Date of Loss:	04/01/2020 22:00 - :59 [1 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000159	Policy/Cover Note No.:	MK000574 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLQ5707E	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Nurulhaida Binte Mohd Seain]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 17/01/2020]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



## Claim Documents

**SHC7652L (M2000159)**

**[SLQ5707E]**

**TP**

**CCPL**

**Jan 4 2020 10:00PM**

**[CCPL]**

**ComfortDelGro Engineering Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser ▼
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	07/01/20 19:40	<b>Repairer Estimates</b>		Load HTM
2	04/02/20 08:48	<b>Repairer Estimates Suppl. #1</b>		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/01/20 16:18	<b>Adjuster Immediate Advice</b>		Load HTM
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
2	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
3	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
16	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
17	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
18	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
19	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
20	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
21	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
22	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
23	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
24	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
25	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
26	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
27	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
28	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
29	13/01/20 17:58	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
30	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/01/20 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	24/01/20 10:13	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
59	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
60	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
61	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
62	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
63	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
64	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
65	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
66	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
67	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
68	11/02/20 10:41	Before Paint Photos	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	07/01/20 19:42	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/20 10:40	SUPPLEMENTARY	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20000496/FQD3S2  
**Date:** 12/02/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000574  
**Claimant Vehicle No :** SHC7652L **Insured Vehicle No :** SLQ5707E  
 Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: M2000159

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7652L**  
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU387389  
 Reg. Date: 14/11/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU183489  
 Colour: Yellow Odometer: 19253 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

### CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm  
 Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,578.38	4,750.08	3,828.30	44.63
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,610.00	2,170.00	1,440.00	39.89
Paintwork Labour	0.00	0.00	0.00	0.00
Towing	0.00	0.00	0.00	0.00
<b>Gross Total (S\$)</b>	<b>12,199.38</b>	<b>6,931.08</b>	<b>5,268.30</b>	<b>43.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>853.96</b>	<b>485.18</b>	<b>368.78</b>	<b>43.18</b>
<b>Nett Amount (S\$)</b>	<b>13,053.34</b>	<b>7,416.26</b>	<b>5,637.08</b>	<b>43.18</b>

### INSPECTION

Date of Assignment: 08/01/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)  
 Date Inspected: 07/01/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969  
 Estimated Period of Repair: 5.0 days

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Feb 2020)

**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHC7652L)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID	Dented	2,480.40 FL	-	*2,480.40 FL
2	1		*BOOTLID RUBBER	Not Necessary	127.40 FL	-	*- FL
3	1		*BOOTLID HINGE LH	Not Necessary	31.30 FL	-	*- FL
4	1		*BOOTLID HINGE RH	Not Necessary	31.30 FL	-	*- FL
5	1		*BOOTLID LOCK UPPER	Not Necessary	224.00 FL	-	*- FL
6	1		*BOOTLID KEY LOCK	Not Necessary	141.00 FL	-	*- FL
7	1		*BOOTLID H EMBLEM	Not Necessary	28.00 FL	-	*- FL
8	1		*BOOTLID CRDI PLATE	Not Necessary	58.00 FL	-	*- FL
9	1		*BOOTLID HYBRID EMBLEM	Necessary	24.30 FL	-	*24.30 FL
10	1		*BOOTLID IONIQ EMBLEM	Necessary	31.30 FL	-	*31.30 FL
11	1		*ASSY BSD-BLIND SPOT RADAR	Not Necessary	758.50 FL	-	*- FL
12	1		*BOOTLID COMFORT LOGO	Necessary	30.00 F	-	*30.00 F
13	1		*BOOTLID TEL. NO STICKER	Necessary	30.00 F	-	*30.00 F
14	1		*BOOTLID APPS STICKER	Necessary	40.00 F	-	*40.00 F
15	1		*BOOTLID GLASS UPPER	Necessary	543.30 FL	-	*543.30 FL
16	1		*BOOTLID GLASS LOWER	Necessary	384.90 FL	-	*384.90 FL
17	2		*REAR WINDSCREEN SEALANT	Necessary	46.00 F	-	*46.00 F
18	1		*REAR SPOILER	Not Necessary	665.40 FL	-	*- FL
19	1		*BOOTLID LAMP LH	Not Necessary	794.40 FL	-	*- FL
20	1		*BOOTLID LAMP RH	Not Necessary	794.40 FL	-	*- FL
21	1		*BOOTLID TRIMBOARD	Not Necessary	159.70 FL	-	*- FL
22	1		*LICENCE LAMP COVER	Broken	35.10 FL	-	*35.10 FL
23	1		*REAR NO. PLATE	Cracked	25.00 F	-	*25.00 F
24	1		*REAR NO. PLATE TRIM COVER	Broken	30.00 F	-	*30.00 F
25	10		*BOOTLID TRIMBOARD CLIPS	Not Necessary	11.00 FL	-	*- FL
26	1		*BOOTLID GLASS MOULDING	Not Necessary	28.30 FL	-	*- FL
27	1		*BOOTLID GARNISH	Not Necessary	36.10 FL	-	*- FL
28	1		*BOOTLID LOWER GARNISH	Not Necessary	25.40 FL	-	*- FL
29	1		*REAR BUMPER	Cracked	459.40 FL	-	*459.40 FL
30	1		*REAR BUMPER REINFORCEMENT	Buckled	294.80 FL	-	*294.80 FL
31	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	138.10 FL	-	*138.10 FL
32	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	138.10 FL	-	*- FL
33	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	-	*451.25 FL
34	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Broken	47.50 FL	-	*47.50 FL
35	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	33.10 FL	-	*- FL
36	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	33.10 FL	-	*- FL
37	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
38	1		*REAR BUMPER UNDER CENTRE	Not Necessary	53.85 FL	-	*- FL
39	1		*REAR BUMPER REFLECTOR LH	Not Necessary	31.90 FL	-	*- FL
40	1		*REAR BUMPER REFLECTOR RH	Not Necessary	31.90 FL	-	*- FL
41	1		*REAR BUMPER FOG LAMP ASSY	Cracked	201.50 FL	-	*201.50 FL
42	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount	
43	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 F	-	*- F	
44	1		*REAR PANEL	Buckled	532.00 FL	-	*532.00 FL	
45	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	-	*- FL	
46	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	-	*- FL	
<b>Supplementary #1</b>								
47	1		*ANTENNA ASSY-SMARTKEY	Broken	40.50 FL	-	*40.50 FL	
					<b>Sub Total (S\$)</b>	<b>10,638.80</b>	<b>5,887.35</b>	
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>2,060.42</b>	<b>1,137.27</b>	
					<b>Total Parts (S\$)</b>	<b>8,578.38</b>		<b>4,750.08</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL PANEL	New	1,800.00	1,280.00
2	SPRAY PAINTING CHARGE	New	900.00	600.00
3	WIRING CHARGE	New	50.00	50.00
4	TUFF KOTE	New	50.00	50.00
5	TOWING FEE CHARGE	New	60.00	60.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	150.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	50.00
8	RESET BSD-BLIND SPOT RADAR	New	480.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,610.00</b>	<b>2,170.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**