

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 2385S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | TAILGATE LID R/H (N) | BENT | 1,500.00 | 1,350.80 |
| 1 | TAILGATE LID NISSAN STICKER (N) | SERVICEABLE | 25.50 | - |
| 1 | REAR CARGO DECK END PANEL (N) | TO REPAIR SEE LABOUR | 886.40 | - |
| 1 | REAR LAMP R/H (N) | CRACKED | 248.60 | 210.80 |
| 1 | REAR LAMP PANEL R/H (N) | BENT | 35.00 | 35.00 |
| | LESS 10% DISCOUNT | | -269.55 | -159.66 |
| | | | 2,425.95 | 1,436.94 |
| | SPECIAL NETT ITEMS | | | |
| 1 | TAILGATE LID 70 KM/H STICKER (SN) | SERVICEABLE | 15.00 | - |
| 1 | REAR LICENCE PLATE (SN) | SERVICEABLE | 50.00 | - |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 300.00 | 200.00 |
| 1 | N/S REAR DOOR STICKER (SN) (ADDITIONAL) | NECESSARY | 220.00 | 120.00 |
| | | | 585.00 | 320.00 |
| | <u>LABOUR</u> | | | |
| | TO REINSTALL OF REAR BUMPER PARKING SENSOR. | | 100.00 | 20.00 |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 50.00 | 30.00 |
| | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR CARGO DECK END PANEL. | | 850.00 | 500.00 |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 600.00 | 300.00 |
| | | | 1,600.00 | 850.00 |
| | GRAND TOTAL | | 4,610.95 | 2,606.94 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 2,100.00 |
|---|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | |

Report Ref No. CS/INC20000503/Hsf3e2

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser