

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 6813J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	1,550.00	1,250.50
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	358.00	-
2	FRONT BUMPER SIDE RETAINER @\$140.00	N/S CRUMPLED O/S SERVICEABLE	280.00	90.30
1	N/S HEADLAMP	CRUMPLED	980.00	820.50
1	FRONT BUMPER SPONGE	CRACKED	180.00	180.00
1	FRONT BUMPER PARKING SENSOR L/H	SHORTED	560.00	280.00
	LESS 10% DISCOUNT		-390.80	-
	LESS 50% DISCOUNT		-	-1,310.65
			3,517.20	1,310.65
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENCE PLATE (SN)	SERVICEABLE	50.00	-
			50.00	-
	<u>LABOUR</u>			
	TO REINSTALL OF FRONT BUMPER PARKING SENSOR.		50.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	30.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	250.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	230.00
			1,200.00	530.00
	GRAND TOTAL		4,767.20	1,840.65
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,850.00

Report Ref No. CS/INC20000504/Hsf3e2

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.