



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3605Y

| Qty | Description of Parts   | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>   |             |                           |                   |
| 1   | N/S REAR DOOR  | BENT        | 1,630.00                  | 1,450.50          |
| 1   | N/S REAR DOOR WEATHERSTRIP   | SERVICEABLE | 650.00                    | -                 |
| 1   | N/S REAR DOOR CHROME GARNISH   | SCRATCHED   | 465.00                    | 315.20            |
| 1   | N/S REAR SPORT RIM   | SCRATCHED   | 1,100.00                  | 880.70            |
| 1   | N/S REAR FENDER INNER COWLING  | SERVICEABLE | 250.00                    | -                 |
| 6   | N/S REAR FENDER INNER COWLING CLIP @\$7.00   | SERVICEABLE | 42.00                     | -                 |
| 1   | N/S SIDE SKID (ADDITIONAL)   | SCRATCHED   | 660.00                    | 580.80            |
|     | LESS 10% DISCOUNT  |             | -479.70                   | -                 |
|     | LESS 50% DISCOUNT  |             | -                         | -1,613.60         |
|     |  |             | 4,317.30                  | 1,613.60          |
|     | <b><u>LABOUR</u></b>   |             |                           |                   |
|     | TO TRANSFER OF N/S REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.  |             | 80.00                     | 60.00             |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.  |             | 50.00                     | 30.00             |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS.  |             | 150.00                    | 30.00             |
|     | PANEL BEATING, KNOCKING AND STRAIGHTEN THE N/S FRONT DOOR AND N/S REAR FENDER, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. |             | 650.00                    | 500.00            |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.  |             | 800.00                    | 600.00            |
|     |  |             | 1,730.00                  | 1,220.00          |
|     | <b>GRAND TOTAL</b>   |             | <b>6,047.30</b>           | <b>2,833.60</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>  |             |                           | <b>2,800.00</b>   |

Report Ref No. CS/INC20000505/Hsf3e2

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.