



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2003984  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE INV Date 18/05/2020  
SINGAPORE 189556 Reference CS/INC20000507/Evf3n2  
ATTN: SERENE Code INC



### PROFESSIONAL SERVICE FEE

Vehicle No. SLE 8868S  
Insured Veh. GBH 5990T  
Claim No. MT/1077717-002  
Policy No.  
Accident Date 27/12/2019  
Inspection Date 08/01/2020

Description	Total
Damage Assessment	250.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000507/Evf3n2

73 BRAS BASAH ROAD

Date: 18-05-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: SERENE

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5990T	Veh. Inspected	SLE 8868S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1077717-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	08/01/2020

#### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6CW1071G0124073	Colour	GREY
Odometer	48328 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	5 mm
L/H Front Tyre	205/55 R16	MICHELIN	5 mm
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  DAMAGES SEE DETAILS.
-------------------------------------------------------------------------------------

#### 5. General Information

Accident Date	27/12/2019	Inspect Date / Time	08/01/2020 ( 11:14 AM )
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8868S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (SN)	CUT	1,108.20	1,108.20
1	BRACKET RHS,FRONT BUMPER (SN)	NOT NECESSARY	42.30	-
1	COVER RHS,FOGLAMP (SN)	NOT NECESSARY	78.20	-
10	CLIP,FRONT BUMPER (SN)	NECESSARY	37.00	37.00
1	GROMMET,FRONT BUMPER (SN)	NECESSARY	16.20	16.20
4	RIVET,FRONT BUMPER (SN)	NECESSARY	22.80	22.80
4	RIVET,FRONT BUMPER (SN)	NECESSARY	32.00	32.00
1	FOAM,FRONT REINFORCEMENT (SN)	NOT NECESSARY	79.20	-
2	FASTENER,FRONT REINFORCEMENT (SN)	NECESSARY	12.40	12.40
1	FRONT REINFORCEMENT (SN)	NOT NECESSARY	531.60	-
1	HEADLAMP RHS (SN)	NOT NECESSARY	1,482.00	-
3	CLIP,HEADLAMP (SN)	NOT NECESSARY	19.50	-
1	RIVET,HEADLAMP (SN)	NOT NECESSARY	3.50	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			3,564.90	1,248.60
	<b><u>LABOUR</u></b>			
	TO REPLACE FRONT BUMPER AND FRONT REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,320.00	660.00
	TO RESPRAY FRONT BUMPER,FRONT REINFORCEMENT AND FRONT FENDER RH.		1,890.00	630.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
	-		-	-
	-		-	-
	-		-	-
			4,060.00	1,620.00
	<b>GRAND TOTAL</b>		<b>7,624.90</b>	<b>2,868.60</b>

Report Ref No. CS/INC20000507/Evf3n2



<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,868.60</b>
------------------------------------------------	--	--	-----------------

Report Ref No. CS/INC20000507/Evf3n2

**CHEN TSUE YEE**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 8868S

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

