

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2020		10 Jan 2020 11:58 Edit Adj Rpt	S\$8,688.90 Edit Estimates	S\$8,688.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: SAFE ENGINEERING SERVICES PTE LTD , Co. Reg. No.: -									
Vehicle Reg. No.: GL8888G		Date of Loss: 04/01/2020 15:00 - :59 [2 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM20D200049		Policy/Cover Note No.: DMCVSN30771419000 (Comprehensive)							
Excess: S\$350.00									
Repairer: Jec Auto Centre (HQ) 1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY, 417883 Kaki Bukit - Tel: 6509 6585									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/01/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- CHINA_TAIHING (15/01/2020): Alert - Adj Mandate Approved (S\$8972.95) - GL8888G - Claim Handler: Ben Tang - CHINA_TAIHING (10/01/2020): Alert - Adj Mandate Approved (S\$5601.15) - GL8888G - Claim Handler: Ben Tang									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GL8888G (SNM20D200049)
 OD
 Jan 4 2020 3:00PM
 [SAFE ENGINEERING SERVICES PTE LTD]
 Jec Auto Centre

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/20 12:36	Adjuster Immediate Advice		Load HTM	
2	14/01/20 17:32	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/20 12:37	General View		Load PDF	
2	14/01/20 17:25	Reinspection Photo		Load PDF	
3	30/03/20 17:10	General View		Load JPG	☒
4	30/03/20 17:10	General View		Load JPG	☒
5	30/03/20 17:10	General View		Load JPG	☒
6	30/03/20 17:10	General View		Load JPG	☒
7	30/03/20 17:10	General View		Load JPG	☒
8	30/03/20 17:10	General View		Load JPG	☒
9	30/03/20 17:10	General View		Load JPG	☒
10	30/03/20 17:10	General View		Load JPG	☒
11	30/03/20 17:10	General View		Load JPG	☒
12	30/03/20 17:10	General View		Load JPG	☒
13	30/03/20 17:10	General View		Load JPG	☒
14	30/03/20 17:10	General View		Load JPG	☒
15	30/03/20 17:10	General View		Load JPG	☒
16	30/03/20 17:10	General View		Load JPG	☒
17	30/03/20 17:10	General View		Load JPG	☒
18	30/03/20 17:10	General View		Load JPG	☒
19	30/03/20 17:10	General View		Load JPG	☒
20	30/03/20 17:10	General View		Load JPG	☒
21	30/03/20 17:10	General View		Load JPG	☒
22	30/03/20 17:10	General View		Load JPG	☒
23	30/03/20 17:10	General View		Load JPG	☒
24	30/03/20 17:10	General View		Load JPG	☒
25	30/03/20 17:10	General View		Load JPG	☒
26	30/03/20 17:10	General View		Load JPG	☒
27	30/03/20 17:10	General View		Load JPG	☒
28	30/03/20 17:10	General View		Load JPG	☒
29	30/03/20 17:10	General View		Load JPG	☒
30	30/03/20 17:10	General View		Load JPG	☒
31	30/03/20 17:10	General View		Load JPG	☒
32	30/03/20 17:10	General View		Load JPG	☒
33	30/03/20 17:10	General View		Load JPG	☒
34	30/03/20 17:11	General View		Load JPG	☒
35	30/03/20 17:11	General View		Load JPG	☒
36	30/03/20 17:11	General View		Load JPG	☒
37	30/03/20 17:12	Reinspection Photo		Load JPG	☒
38	30/03/20 17:12	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
39	30/03/20 17:12	Reinspection Photo		Load JPG	☒
40	30/03/20 17:12	Reinspection Photo		Load JPG	☒
41	30/03/20 17:12	Reinspection Photo		Load JPG	☒
42	30/03/20 17:12	Reinspection Photo		Load JPG	☒
43	30/03/20 17:12	Reinspection Photo		Load JPG	☒
44	30/03/20 17:12	Reinspection Photo		Load JPG	☒
45	30/03/20 17:12	Reinspection Photo		Load JPG	☒
46	30/03/20 17:12	Reinspection Photo		Load JPG	☒
47	30/03/20 17:12	Reinspection Photo		Load JPG	☒
48	30/03/20 17:12	Reinspection Photo		Load JPG	☒
49	30/03/20 17:12	Reinspection Photo		Load JPG	☒
50	30/03/20 17:12	Reinspection Photo		Load JPG	☒
51	30/03/20 17:12	Reinspection Photo		Load JPG	☒
52	30/03/20 17:12	Reinspection Photo		Load JPG	☒
53	30/03/20 17:12	Reinspection Photo		Load JPG	☒
54	30/03/20 17:12	Reinspection Photo		Load JPG	☒
55	30/03/20 17:12	Reinspection Photo		Load JPG	☒
56	30/03/20 17:12	Reinspection Photo		Load JPG	☒
57	30/03/20 17:12	Reinspection Photo		Load JPG	☒
58	30/03/20 17:12	Reinspection Photo		Load JPG	☒
59	30/03/20 17:12	Reinspection Photo		Load JPG	☒
60	30/03/20 17:12	Reinspection Photo		Load JPG	☒
61	30/03/20 17:12	Reinspection Photo		Load JPG	☒
62	30/03/20 17:12	Reinspection Photo		Load JPG	☒
63	30/03/20 17:12	Reinspection Photo		Load JPG	☒
64	30/03/20 17:12	Reinspection Photo		Load JPG	☒
65	30/03/20 17:12	Reinspection Photo		Load JPG	☒
66	30/03/20 17:12	Reinspection Photo		Load JPG	☒
67	30/03/20 17:12	Reinspection Photo		Load JPG	☒
68	30/03/20 17:12	Reinspection Photo		Load JPG	☒
69	30/03/20 17:12	Reinspection Photo		Load JPG	☒
70	30/03/20 17:12	Reinspection Photo		Load JPG	☒
71	30/03/20 17:12	Reinspection Photo		Load JPG	☒
72	30/03/20 17:12	Reinspection Photo		Load JPG	☒
73	30/03/20 17:12	Reinspection Photo		Load JPG	☒
74	30/03/20 17:12	Reinspection Photo		Load JPG	☒
75	30/03/20 17:12	Reinspection Photo		Load JPG	☒
76	30/03/20 17:12	Reinspection Photo		Load JPG	☒
77	30/03/20 17:12	Reinspection Photo		Load JPG	☒
78	30/03/20 17:12	Reinspection Photo		Load JPG	☒
79	30/03/20 17:12	Reinspection Photo		Load JPG	☒
80	30/03/20 17:12	Reinspection Photo		Load JPG	☒
81	30/03/20 17:12	Reinspection Photo		Load JPG	☒
82	30/03/20 17:12	Reinspection Photo		Load JPG	☒
83	30/03/20 17:12	Reinspection Photo		Load JPG	☒
84	30/03/20 17:12	Reinspection Photo		Load JPG	☒
85	30/03/20 17:12	Reinspection Photo		Load JPG	☒
86	30/03/20 17:12	Reinspection Photo		Load JPG	☒
87	30/03/20 17:12	Reinspection Photo		Load JPG	☒
88	30/03/20 17:12	Reinspection Photo		Load JPG	☒
89	30/03/20 17:12	Reinspection Photo		Load JPG	☒
90	30/03/20 17:12	Reinspection Photo		Load JPG	☒
91	30/03/20 17:12	Reinspection Photo		Load JPG	☒

Assessment Reports				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
92	30/03/20 17:12	Reinspection Photo		Load JPG	☒
93	30/03/20 17:12	Reinspection Photo		Load JPG	☒
94	30/03/20 17:12	Reinspection Photo		Load JPG	☒
95	30/03/20 17:12	Reinspection Photo		Load JPG	☒
96	30/03/20 17:12	Reinspection Photo		Load JPG	☒
97	30/03/20 17:12	Reinspection Photo		Load JPG	☒
98	30/03/20 17:12	Reinspection Photo		Load JPG	☒
99	30/03/20 17:12	Reinspection Photo		Load JPG	☒
100	30/03/20 17:12	Reinspection Photo		Load JPG	☒
101	30/03/20 17:12	Reinspection Photo		Load JPG	☒
102	30/03/20 17:12	Reinspection Photo		Load JPG	☒
103	30/03/20 17:12	Reinspection Photo		Load JPG	☒
104	30/03/20 17:12	Reinspection Photo		Load JPG	☒
105	30/03/20 17:12	Reinspection Photo		Load JPG	☒
106	30/03/20 17:12	Reinspection Photo		Load JPG	☒
107	30/03/20 17:12	Reinspection Photo		Load JPG	☒
108	30/03/20 17:12	Reinspection Photo		Load JPG	☒
109	30/03/20 17:12	Reinspection Photo		Load JPG	☒
110	30/03/20 17:12	Reinspection Photo		Load JPG	☒
111	30/03/20 17:12	Reinspection Photo		Load JPG	☒
112	30/03/20 17:12	Reinspection Photo		Load JPG	☒
113	30/03/20 17:12	Reinspection Photo		Load JPG	☒
114	30/03/20 17:12	Reinspection Photo		Load JPG	☒
115	30/03/20 17:12	Reinspection Photo		Load JPG	☒
116	30/03/20 17:12	Reinspection Photo		Load JPG	☒
117	30/03/20 17:12	Reinspection Photo		Load JPG	☒
118	30/03/20 17:12	Reinspection Photo		Load JPG	☒
119	30/03/20 17:12	Reinspection Photo		Load JPG	☒
120	30/03/20 17:12	Reinspection Photo		Load JPG	☒
121	30/03/20 17:12	Reinspection Photo		Load JPG	☒
122	30/03/20 17:12	Reinspection Photo		Load JPG	☒
123	30/03/20 17:12	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/01/20 12:37	MARK ESTIMATE		Load PDF	
2	15/04/20 15:21	SUPPLEMENTARY		Load PDF	
3	15/04/20 15:21	PARTS INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20000512/AVD3S2**Date:** 15/04/2020**REFERENCE**

Insured/Claimant: SAFE ENGINEERING SERVICES PTE LTD Policy No: DMCVSN30771419000

Date of Loss: 04/01/2020

Nature of Claim: OD

Claim No: SNM20D200049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GL8888G	Engine No:	1GD8394294
Make & Model:	TOYOTA REGIUS ACE, 2.5 D KDH200 (M)	Chassis No:	GDH2011020905
Reg. Date:	18/10/2019 (Man. Year: 2019)	Odometer:	4214 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R16	Rear Tyre Size:	195R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,138.75	7,288.90	849.85	10.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,400.00	730.00	34.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,268.75	8,688.90	1,579.85	15.39
- Excess (S\$)	350.00	350.00	0.00	0.00
Nett Amount (S\$)	9,918.75	8,338.90	1,579.85	15.93

INSPECTION

Date of Assignment: 10/01/2020

Date Inspected: 08/01/2020

Inspected At:

JEC AUTOMOTIVE
1 KAKI BUKIT AVENUE 6
#02-11 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Apr 2020)	
Parts:	N/A	TOYOTA REGIUS ACE 2.5 D KDH200 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GL8888G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	220.00 F	*220.00 F
2	1		*SET FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
3	2		*FRONT BUMPER SIDE HOLDER (WCP)	Not Necessary	120.00 F	*- F
4	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	60.00 F	*60.00 F
5	1		*FRONT BUMPER TOW COVER (WCP)	Missing	16.00 F	*16.00 F
6	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	105.00 F	*105.00 F
7	1		*FRONT BUMPER TOP BEAM (WCP)	Bent	75.00 F	*75.00 F
8	2		*FRONT BUMPER FOG LAMP (WCP)	Not Necessary	250.00 F	*- F
9	2		*FRONT BUMPER FOG LAMP COVER (WCP)	Not Necessary	72.00 F	*- F
10	1		*FRONT GRILLE (WCP)	Cracked	210.00 F	*210.00 F
11	1		*FRONT GRILLE UPPER CHROME MOULDING (WCP)	Cut	190.00 F	*190.00 F
12	1		*FRONT GRILLE LOWER CHROME MOULDING (WCP)	Cut	205.00 F	*205.00 F
13	2		*HEADLAMP (WCP)	Cracked	1,970.00 F	*1,970.00 F
14	1		*BONNET (WCP)	Distorted	265.00 F	*265.00 F
15	1		*BONNET LOGO (WCP)	Necessary	30.00 F	*30.00 F
16	1		*BONNET LOCK (WCP)	Not Necessary	72.00 F	*- F
17	1		*FRONT SUPPORT PANEL (WCP)	Repair	170.00 F	*- F
18	1		*FRONT SUPPORT PANEL TOP COVER (WCP)	Not Necessary	55.00 F	*- F
19	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS (WCP)	Necessary	10.00 F	*10.00 F
20	1		*WIPER WASHER TANK (WCP)	Deformed	85.00 F	*85.00 F
21	1		*AIR CON CONDENSER (WCP)	Dented	530.00 F	*530.00 F
22	1		*AIR CON DISCHARGE PIPE (WCP)	Bent	210.00 F	*210.00 F
23	1		*AIR CON SUCTION PIPE (WCP)	Bent	225.00 F	*225.00 F
24	1		*AIR CON LIQUID PIPE (WCP)	Bent	215.00 F	*215.00 F
25	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
26	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
27	2		*FRONT BUMPER REINFORCEMENT STAY BRACKET (WCP)	Bent	350.00 F	*350.00 F
28	1		*INTERCOOLER COWLING (WCP)	Cracked	48.00 F	*48.00 F
29	1		*ADBLUE TANK (WCP)	Cracked	385.00 F	*385.00 F
30	2		*FRONT BUMPER BRACKET (WCP)	Bent	72.00 F	*72.00 F
31	1		*RADIATOR (WCP)	Dented	680.00 F	*680.00 F
32	1		*RADIATOR FAN COWLING (WCP)	Cracked	110.00 F	*110.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	7,085.00	6,346.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,053.75	942.90
Total Parts (S\$)	8,138.75	7,288.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS.	New	1,000.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	800.00	500.00
3	WIRING CHECK.	New	50.00	30.00
4	TUFF COAT.	New	100.00	50.00
5	TO REMOVE CONDENSER AND RADIATOR AND TO TOP UP.	New	180.00	120.00
Gross Labour Cost (\$)			2,130.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >