Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20000532/R1KS3Q2

**Date:** 27/05/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: GBE8049H Insured Vehicle No: SMQ3902J

Date of Loss: 31/12/2019 Nature of Claim: TP Claim No: 7230298191SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBE8049H

 Make & Model:
 NISSAN NV200, 1.6 (A)
 Engine No:
 HR16053983D

 Reg. Date:
 24/03/2016 (Man. Year: 2015)
 Chassis No:
 VM20087686

 Colour:
 White
 Odometer:
 70143 km

Engine Capacity: 1597 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,154.87	3,447.99	706.88	17.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,480.00	1,360.00	1,120.00	45.16
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,634.87	4,807.99	1,826.88	27.53
	Approved Total (Overridden) (S\$)		3,850.00		
	(S\$)	6,634.87	3,850.00	2,784.87	41.97
	+ GST 7.00/7.00% (S\$)	464.44	269.50	194.94	41.97
	Nett Amount (S\$)	7,099.31	4,119.50	2,979.81	41.97
	+ Car Rental (5.0 x S\$150.00/day + 7.	.00% GST) (S\$)	802.50		
	Ne	tt Liability (S\$)	4,922.00		
	Global Sum S	Settlement (S\$)	4.700.00		

**INSPECTION** 

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6 Singapore 539365

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE LID	Bent	1,724.60 FN	*1,724.60 FN	
2	1		*TAILGATE LID INNER LOCK	Not Necessary	261.00 FN	*- FN	
3	2		*TAILGATE LID HINGES	Not Necessary	198.20 FN	*- FN	
4	1		*TAILGATE LID NV 200 EMBLEM BADGE	Necessary	87.00 FN	*87.00 FN	
5	1		*TAILGATE LID NISSAN EMBLEM BADGE	Necessary	59.70 FN	*59.70 FN	
6	1		*TAILGATE LID VANETTE EMBLEM BADGE	Necessary	59.70 FN	*59.70 FN	
7	1		*REAR BUMPER	Cut	581.10 FN	*581.10 FN	
8	1		*REAR END PANEL	Bent	358.80 FN	*358.80 FN	
9	1		*TAILGATE LID WEATHERSTRIP	Necessary	63.70 FN	*63.70 FN	
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	154.00 FN	*- FN	
11	1		*REAR BUMPER ABSORBER FOAM	Cracked	84.00 FN	*84.00 FN	
12	1		*REAR END PANEL INNER TRIM	Deformed	133.80 FN	*133.80 FN	
13	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	20.00 FN	*20.00 FN	
14	1		*REAR LAMP O/S	Scratched	358.70 FN	*358.70 FN	
15	1		*TAILGATE LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS	
16	1		*TAILGATE LID 6 PAX STICKER	Necessary	20.00 FS	*10.00 FS	
17	1		*SET REAR BUMPER REVERSE SENSOR	Necessary	320.00 FS	*200.00 FS	
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	65.00 FS	*50.00 FS	
F=Fra	nchise	part. S=Spc	Nett. N=NettItemDisc.				
				Sub Total (S\$)	4,569.30	3,801.10	
	- Nett Item Discount on N Items 10.00/10.00% (S\$)			414.43	353.11		
				Total Parts (S\$)	4,154.87	3,447.99	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	60.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	650.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	500.00
	Gross Labo	Gross Labour Cost (S\$)		1,360.00
Γ	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >