

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000546/UKS3Q2

Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993949

Claimant
Vehicle No : SKA9269Y **Insured Vehicle No :** YP7597T

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: 4357724844SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA9269Y		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4882368
Reg. Date:	29/04/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106143825
Colour:	Black	Odometer:	192165 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,886.90	5,283.99	4,602.91	46.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	3,040.00	1,210.00	28.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,136.90	8,323.99	5,812.91	41.12
Approved Total (Overridden) (S\$)		6,650.00		
Nett Amount (S\$)	14,136.90	6,650.00	7,486.90	52.96
+ Car Rental (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,537.45		
Global Sum Settlement (S\$)		7,530.00		

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 07/01/2020 Inspected At:

Zoom Autowerks Pte Ltd (Bedok)
130 Bedok Reservoir Road, #08-1339
Singapore 470130

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS	Not Necessary	1,304.57 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	89.50 FL	*89.50 FL
3	1		*REAR BOOT LID	Distorted	778.20 FL	*778.20 FL
4	2		*REAR BOOT HINGES	Repair	173.80 FL	*- FL
5	1		*REAR BOOT INNER TRIM	Not Necessary	189.60 FL	*- FL
6	1		*REAR BOOT LAMP O/S	Broken	181.50 FL	*181.50 FL
7	1		*REAR BOOT INNER LOCK	Twisted	166.75 FL	*166.75 FL
8	1		*REAR BOOT LOGO	Necessary	58.50 FL	*58.50 FL
9	1		*REAR BOOT OUTER CHROME MOULDING	Cracked	281.65 FL	*281.65 FL
10	1		*REAR BOOT WEATHERSTRIP	Torn	165.60 FL	*165.60 FL
11	1		*REAR BOOT COROLLA EMBLEM	Necessary	45.30 FL	*45.30 FL
12	1		*REAR BOOT ALTIS EMBLEM	Necessary	42.50 FL	*42.50 FL
13	1		*REAR BOOT 1.6 EMBLEM	Necessary	38.40 FL	*38.40 FL
14	2		*REAR BOOT NUMBER PLATE LAMPS	Cracked (1 PCS ONLY)	85.20 FL	*41.50 FL
15	2		*REAR TAILLAMPS	N/S Cracked / O/S Broken	781.90 FL	*781.90 FL
16	1		*REAR TAILLAMP PANELS	O/S Badly Dented	930.00 FL	*450.50 FL
17	1		*REAR BUMPER SPONGE	Torn	171.00 FL	*171.00 FL
18	1		*REAR END PANEL	Badly Dented	762.60 FL	*615.20 FL
19	1		*REAR END PANEL INNER GARNISH	Twisted	192.50 FL	*192.50 FL
20	1		*REAR BUMPER	Distorted	560.60 FL	*520.30 FL
21	1		*REAR BUMPER SIDE BRACKETS	O/S Dented	97.00 FL	*42.90 FL
22	1		*REAR BUMPER REFLECTORS	O/S Scratched	151.00 FL	*66.50 FL
23	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	131.00 FL	*60.80 FL
24	1		*REAR FLOOR PANEL	Repair	857.60 FL	*- FL
25	1		*REAR FLOOR BOARD	Torn	363.40 FL	*363.40 FL
26	1		*REAR EXHAUST SILENCER	Not Necessary	881.70 FL	*- FL
27	2		*REAR EXHAUST MOUNTINGS	Not Necessary	97.20 FL	*- FL
28	1		*REAR FENDERS	N/S Repair / O/S Badly Dented	2,163.20 FL	*1,081.60 FL
29	1		*REAR FENDER INNER AIR VENT O/S	Cracked	111.20 FL	*111.20 FL
30	1		*REAR FENDER INNER TRIMS	O/S Torn	622.90 FL	*311.45 FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
33	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,005.87	6,948.65
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,118.97	1,664.66
Total Parts (\$\$)	9,886.90	5,283.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECL UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	120.00	0.00
8	TO APPLY UNDERCOATING	New	200.00	100.00
9	PANEL BEATING	New	1,600.00	1,400.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,200.00
Gross Labour Cost (S\$)			4,250.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >