Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000552/ABA3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLK7410D Insured Vehicle No: SGC6068S

Vehicle No:

Date of Loss: 06/01/2020 Nature of Claim: ΤP Claim No: 4576112432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLK7410D Reg No:

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4404868 Reg. Date: 25/01/2017 (Man. Year: 2016) Chassis No: RU11204868 Colour: Odometer: 53507 km Black

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Rear Left Side: Front Left Side: Sportiva 6 mm Sportiva 6 mm Front Right Side: Rear Right Side: Sportiva 6 mm Sportiva 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,343.68	6,735.68	7,608.00	53.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	2,510.00	1,450.00	36.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,303.68	9,245.68	9,058.00	49.49
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	18,303.68	7,400.00	10,903.68	59.57
+ Car Rental (7.0 x S\$10	00.00/day) (S\$)	700.00		
+ Doc/Se	36.45			
Net	t Liability (S\$)	8,136.45		
Global Sum S	ettlement (S\$)	8,100.00		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30

Bartley Biz Centre Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,950.00 FL	*1,100.00 FL
2	1		*TAILGATE HANDLE COVER	Deformed	55.00 FL	*55.00 FL
3	1		*TAILGATE UPPER GARNISH	Cracked	550.00 FL	*325.00 FL
4	2		*TAILGATE RUBBER STOPPER	Not Necessary	12.00 FL	*- FL
5	1		*TAILGATE VEZEL EMBLEM	Not Necessary	85.20 FL	*-FL
6	1		*TAILGATE EDGE WEATHERSTRIP	Cut	310.00 FL	*135.00 FL
7	1		*TAILGATE INNER TRIM GARNISH	Deformed	660.50 FL	*285.00 FL
8	1		*TAILGATE HONDA LOGO	Necessary	81.20 FL	*35.00 FL
9	1		*TAILGATE LOCK	Damaged	495.20 FL	*183.00 FL
10	2		*TAILGATE DAMPER LH & RH	Not Necessary	600.00 FL	*- FL
11	1		*REAR WIPER MOTOR	Not Necessary	355.00 FL	*-FL
12	2		*REAR TAILGATE LAMP LH & RH	N/S Cut / O/S Cracked	1,260.40 FL	*826.00 FL
13	2		*REAR TAILLAMP LH & RH	N/S Cut / O/S Cracked	1,502.60 FL	*949.00 FL
14	2		*REAR TAILLAMP PANEL LH & RH	Repair	599.00 FL	*-FL
15	1		*REAR BUMPER	Distorted	830.00 FL	*830.00 FL
16	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	220.00 FL	*47.00 FL
17	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	182.00 FL	*-FL
18	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	320.00 FL	*-FL
19	1		*REAR BUMPER CORNER PANEL LH & RH	O/S Deformed	440.00 FL	*220.00 FL
20	1		*REAR FENDER WHEEL ARCH LH & RH	O/S Cracked	566.00 FL	*392.00 FL
21	2		*REAR FENDER INNER SHIELD LH & RH	Not Necessary	452.20 FL	*-FL
22	1		*REAR END PANEL	Distorted	952.20 FL	*585.00 FL
23	1		*REAR END PANEL OUTER BEAM	Not Necessary	175.00 FL	*-FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	280.00 FL	*98.00 FL
25	1		*REAR SPARE TYRE PANEL	Repair	1,258.00 FL	*-FL
26	1		*REAR SPARE TYRE BOX LOWER COVER	Deformed	242.10 FL	*242.10 FL
27	1		*REAR SPARE TYRE BOX TOP GARNISH	Deformed	650.00 FL	*307.00 FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	98.00 FL	*- FL
29	1		*REAR EXHAUST SILENCE ASSY	Bent	980.00 FL	*598.00 FL
30	1		*REAR REMOTE CONTROL SENSOR	Cracked	258.00 FL	*85.00 FL
31	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
34	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
35	1		*REAR WINDSCREEN SEALANTS	Necessary	100.00 FS	*60.00 FS
36	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
37	2		*REAR FENDER INNER TRIM BOARD	Deformed	570.00 FL	*570.00 FL
38	1		*REAR BUZZER SENSOR	Cracked	65.00 FL	*65.00 FL
F=Fra	nchise	part. S=Spo	Nett. L=ListItemDisc.	Sub Total (S\$)	47.754.00	9 222 10

 Sub Total (\$\$)
 17,754.60
 8,322.10

 - List Item Discount on L Items 20.00/20.00% (\$\$)
 3,410.92
 1,586.42

Total Parts (S\$) 14,343.68 6,735.68

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,100.00				
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,000.00				
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00				
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	240.00	80.00				
5	TO REMOVE & REFIX /REPLACE REAR TRIMS ,GARNISH AND FITTING SO AS TO FACILITATE REPAIRS AS REAR COMPARTMENT	New	250.00	80.00				
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	100.00				
7	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	150.00	120.00				
	Gross Labour Cost (S\$)		3,960.00	2,510.00				
	Report was unsubmitted durin	g this print-out.						

< END OF ESTIMATES >