

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2005015

INV Date 17/07/2020

Reference CC6/CTI20000556/Fba3n2

Code CT



Vehicle No. SMQ 7182T

Insured Veh. SLZ 8569U

Claim No. SNM20D200088

Policy No. DMPCSN1815981901

Accident Date 04/01/2020

Inspection Date 07/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile							
CHIN	CHINA TAIPING INSURANCE (S) PTE LTD Ref: CC6/CTI20000556/Fba3n2							
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 17-07-2020 Code: CTI						
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SLZ 8569U	Veh. Inspected	SMQ 7182T				
	Policy No.	DMPCSN1815981901	Coverage (\$)	0.00				
	Claim No.	SNM20D200088	Excess (\$)	0.00				
	Assign From		Assign Date	07/01/2020				
2.		Vehicle Partic	culars & Condition					
	Make & Model	MITSUBISHI OUTLANDER	c.c	1998				
	Engine No.	HIDDEN	Year of Reg.	2019				
	Chassis No.	GF7W0602083	Colour	RED				
	Odometer	1756	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	225/55 R18	TOYO	9 mm				
	L/H Front Tyre	225/55 R18	тоуо	9 mm				
	R/H Rear Tyre	225/55 R18	TOYO	9 mm				
	L/H Rear Tyre	225/55 R18	тоуо	9 mm				
4.	T	•	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.					
	DAMAGES SEE D							
5.		General	Information					
	Accident Date	04/01/2020	Inspection Date	07/01/2020				
	Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD							
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443							
5a.			emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	,	·	Days of Repair	-				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days					
	•							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 7182T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER }	CRACKED	889.00	889.00
1	REAR BUMPER MOULDING }	DEFORMED	-	-
1	REAR BUMPER LOWER COVER (SILVER)	SCRATCHED	360.00	360.00
2	REAR BUMPER SIDE BRACKET O/S & N/S (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER INNER SPONGE (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT (NPA)	NOT NECESSARY	-	-
1	TAIL GATE	BUCKLED	963.00	963.00
1	REAR WINDSCREEN MOULDING	NECESSARY	98.00	98.00
1	MITSUBISHI EMBLEM	NECESSARY	65.00	65.00
1	OUTLANDER BADGE	NECESSARY	65.00	65.00
1	TAIL GATE LOCK (NPA)	NOT NECESSARY	-	-
1	TAIL GATE STICKER (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-244.00	-244.00
			2,196.00	2,196.00
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	30.00
			428.00	128.00
	<u>LABOUR</u>			
	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE REAR WINDSCREEN INTO NEW TAIL GATE.		150.00	100.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUSING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE END PANEL,ETC.		700.00	450.00

Report Ref No. CC6/CTI20000556/Fba3n2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,404.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,END PANEL,TAIL GATE.		750.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	80.00
			2,050.00	1,080.00
	GRAND TOTAL		4,674.00	3,404.00

Report Ref No. CC6/CTI20000556/Fba3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 7182T

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 7182T

RE-INSPECTION











