

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000560/QEA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLG5594R **Insured Vehicle No :** SCL8199J

Date of Loss: 30/12/2019 Nature of Claim: TP Claim No: 1775653506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG5594R		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4403968
Reg. Date:	05/10/2016 (Man. Year: 2016)	Chassis No:	RU11203870
Colour:	White	Odometer:	192694 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.48	1,658.00	4,218.48	71.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,050.00	1,290.00	55.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,216.48	2,708.00	5,508.48	67.04
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	8,216.48	2,100.00	6,116.48	74.44
+ GST 7.00/7.00% (S\$)	575.15	147.00	428.15	74.44
Nett Amount (S\$)	8,791.63	2,247.00	6,544.63	74.44
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,429.00		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*972.00 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*56.00 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL
4	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	155.00 FL	*- FL
6	1		*REAR END PANEL	Serviceable	830.00 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Serviceable	155.00 FL	*- FL
8	1		*REAR BUMPER	Dented	955.00 FL	*762.00 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
10	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
11	1		*REVERSE SENSOR	Not Necessary	490.00 FS	*- FS
12	1		*WINDSCREEN SEALANT	Necessary	2,100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,658.10	2,055.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	781.62	397.00
Total Parts (\$\$)	5,876.48	1,658.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR END PANEL ,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY REAR TAILGATE ,END PANEL AND SPARE TYRE PANEL	New	1,000.00	400.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	120.00
4	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	0.00
5	TO CHECK WIRING SYSTEM	New	100.00	30.00
Gross Labour Cost (\$\$)			2,340.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >