

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000562/KHA3Q2

Date: 15/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMA102E

Insured Vehicle No : SJS6122Z

Date of Loss: 31/12/2019

Nature of Claim: TP

Claim No: 9773041147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA102E

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance (A)

Engine No: 1ZR0B52949

Reg. Date: 08/06/2018 (Man. Year: 2018)

Chassis No: MR053REH604582179

Colour: Metallic Red

Odometer: 39595 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size:

215/45 R17

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,347.20 | 2,053.12 | 1,294.08 | 38.66 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,700.00 | 1,330.00 | 370.00 | 21.76 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,047.20 | 3,383.12 | 1,664.08 | 32.97 |
| Approved Total (Overridden) (S\$) | | 2,700.00 | | |
| Nett Amount (S\$) | 5,047.20 | 2,700.00 | 2,347.20 | 46.50 |
| + Car Rental (4.0 x S\$60.00/day) (S\$) | | 240.00 | | |
| + Doc/Search Fee (S\$) | | 7.00 | | |
| Nett Liability (S\$) | | 2,947.00 | | |
| Global Sum Settlement (S\$) | | 2,900.00 | | |

INSPECTION

Date of Assignment: 07/01/2020

Date Inspected: 09/01/2020 Inspected At:

Loh Heng (HQ)

176 Sin Ming Drive, #03-08 Sin Ming

Auto Care

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|--------------------|------------|------------|
| 1 | 1 | | *REAR BOOT COVER | Repair | 793.00 FL | *- FL |
| 2 | 1 | | *REAR BOOT RUBBER | Distorted / Dented | 210.00 FL | *210.00 FL |
| 3 | 1 | | *REAR BUMPER | Bent | 490.00 FL | *488.70 FL |
| 4 | 1 | | *REAR REVERSE SENSOR | Shorted | 250.00 FL | *250.00 FL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 380.00 FL | *344.70 FL |
| 6 | 1 | | *END PANEL | Bent | 580.00 FL | *580.00 FL |
| 7 | 1 | | *BOOT LOCK | Repair | 398.00 FL | *- FL |
| 8 | 1 | | *COROLLA BADGE | Necessary | 48.00 FL | *48.00 FL |
| 9 | 1 | | *ALTIS BADGE | Necessary | 58.00 FL | *58.00 FL |
| 10 | 1 | | *TOYOTA LOGO | Necessary | 59.00 FL | *59.00 FL |
| 11 | 1 | | *TAIL LAMP | Mtg Cracked | 490.00 FL | *380.10 FL |
| 12 | 1 | | *BUMPER RETAINER RIGHT | Serviceable | 109.00 FL | *- FL |
| 13 | 1 | | *TAILLAMP TOP GARNISH | Dented | 134.00 FL | *134.00 FL |
| 14 | 1 | | *ANTENNA SENSOR | Dented | 185.00 FL | *185.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 4,184.00 | 2,737.50 |
| - List Item Discount on L Items 20.00/25.00% (\$\$) | 836.80 | 684.38 |
| Total Parts (\$\$) | 3,347.20 | 2,053.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO CUT AND REWELD NEW TAIL PANEL REPLACE NEW PARTS | New | 800.00 | 600.00 |
| 2 | RESEAL WITH SEALANT ON WELD AREA AND TEST FOR WATER LEAKING | New | 120.00 | 30.00 |
| 3 | RESPRAY OF DAMAGED AREA | New | 780.00 | 700.00 |
| Gross Labour Cost (\$\$) | | | 1,700.00 | 1,330.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >