

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20000564/APA3Q2

Date: 27/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLC4478X	Insured Vehicle No :	SHC1901H
Date of Loss: 02/01/2020	Nature of Claim: TP	Claim No: MCT20010022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4478X		
Make & Model:	NISSAN TEANA 2.5L CVT, 2.5 (A)	Engine No:	QR25521749L
Reg. Date:	16/05/2016 (Man. Year: 2016)	Chassis No:	MNTBCAL33Z0003718
Colour:	Grey	Odometer:	58651 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,676.63	2,793.87	1,882.76	40.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	930.00	980.00	51.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	6,586.63	3,723.87	2,862.76	43.46
Approved Total (Overridden) (\$)		2,950.00		
(S\$)	6,586.63	2,950.00	3,636.63	55.21
+ GST 7.00/7.00% (S\$)	461.06	206.50	254.56	55.21
Nett Amount (\$)	7,047.69	3,156.50	3,891.19	55.21
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	06/01/2020	
Date Inspected:	06/01/2020	Inspected At:
		KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2020)
Parts:	143	NISSAN TEANA 2.5L CVT 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4478X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	652.70 FL	*- FL
2	1		*FRONT FENDER INNER COWLING	Not Necessary	119.70 FL	*- FL
3	10		*FRONT FENDER COWLING CLIPS	Not Necessary	42.00 FL	*- FL
4	1		*FRONT HEAD LAMP	Cracked	1,610.00 FL	*1,470.00 FL
5	1		*FRONT BUMPER	Distorted	944.90 FL	*811.70 FL
6	1		*FRONT BUMPER SIDE RETAINER	Necessary	24.50 FL	*24.50 FL
7	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
8	1		*FRONT BUMPER NOZZLE	Not Necessary	147.80 FL	*- FL
9	1		*FRONT BUMPER NOZZLE COVER	Missing	72.50 FL	*72.50 FL
10	1		*FRONT BUMPER TOWING COVER	Missing	24.00 FL	*24.00 FL
11	1		*FRONT BUMPER FORD LAMP RH	Not Necessary	340.00 FL	*- FL
12	1		*FRONT GRILLE	Cracked	395.40 FL	*395.40 FL
13	1		*FRONT NO PLATE GARNISH	Not Necessary	141.00 FL	*- FL
14	1		*FRONT BUMPER LAMP RH	Cut	162.50 FL	*162.50 FL
15	1		*FRONT FORD LAMP COVER RH	Cut	113.70 FL	*113.70 FL
16	1		*FRONT BUMPER SENSOR SEAL	Not Necessary	320.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,160.70	3,104.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	484.07	310.43
Total Parts (\$\$)	4,676.63	2,793.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	850.00	500.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	900.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIR,REPLAC PANEL	New	80.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
Gross Labour Cost (\$)			1,910.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >