

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20000566/QEA3Q2

**Date:** 17/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994048

**Claimant**  
**Vehicle No :** SLQ3194Y **Insured Vehicle No :** SJC2123G

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: 1502498549SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3194Y		
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Engine No:	LEB5914764
Reg. Date:	04/07/2017 (Man. Year: 2016)	Chassis No:	RU31214754
Colour:	Brown	Odometer:	168500 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/50R15	Rear Tyre Size:	215/50R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,684.00	2,640.00	1,044.00	28.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	1,160.00	350.00	23.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,194.00</b>	<b>3,800.00</b>	<b>1,394.00</b>	<b>26.84</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	363.58	266.00	97.58	26.84
<b>Nett Amount (\$\$)</b>	<b>5,557.58</b>	<b>4,066.00</b>	<b>1,491.58</b>	<b>26.84</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (\$\$)</b>		180.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>4,253.45</b>		

### INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At:

LION CITY RENTALS PTE LTD  
60 JALAN LAM HUAT# 04-01  
CARROS CENTRE, 728862  
SINGAPORE.

Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	955.00 FL	*800.00 FL
2	1		*F/L HEADLAMP	Cracked	2,100.00 FL	*1,250.00 FL
3	1		*F/L FENDER	Crumpled	600.00 FL	*600.00 FL
4	1		*F/L FENDER WHEEL ARCH MOULDING	Scratched	300.00 FL	*250.00 FL
5	1		*SET BUMPER AND CLIPS	Necessary	200.00 FS	*30.00 FS
6	1		*WHEEL COVER	Scratched	120.00 FS	*120.00 FS
7	1		*WHEEL RIM	Bent	200.00 FS	*170.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,475.00</b>	<b>3,220.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	791.00	580.00
<b>Total Parts (\$)</b>	<b>3,684.00</b>	<b>2,640.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND F/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	750.00	500.00
2	TO RESPRAY FRONT BUMPER,F/R FENDER AND F/L FENDER WHEEL ARCH MOULDING	New	700.00	600.00
3	WHEEL ALIGNMENT	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,510.00</b>	<b>1,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >