

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHA 3083 R

MAKE :

MODEL : TOYOTA PRIUS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

DATE: 31/12/2019

TEL : 6483 6016

FAX : 6483 6015

Parts Description/Labour	Qty	Unit Price	Amount
BONNET <i>Dented</i>			\$ 950.50
INSULATOR HOOD <i>HN</i>			\$ 398.10
INSULATOR CLIPS <i>HN</i>			\$ 3.60
BONNET RUBBER <i>HN</i>			\$ 35.50
BONNET CABLE <i>1st turn</i>			\$ 53.20
BONNET HINGE (RH) <i>1st</i>			\$ 57.70
BONNET HINGE (LH) <i>1st</i>			\$ 57.70
BONNET LOCK <i>1st</i>			\$ 132.60
RADIATOR GRILLE <i>crack/broken</i>			\$ 438.00
RADIATOR GRILLE EMBLEM <i>HN</i>			\$ 88.00
FRONT RADIATOR LOWER SUPPORT PANEL <i>1st</i>			\$ 357.70
RADIATOR ASSY <i>1st</i>			\$ 1,841.80
RADIATOR BOTTOM MOUNTING <i>HN</i>			\$ 27.50
STAY,RADIATOR SUPPORT,RH <i>HN</i>			\$ 65.70
STAY,RADIATOR SUPPORT,LH <i>HN</i>			\$ 65.70
RADIATOR FAN BLADE (RH) <i>HN</i>			\$ 233.10
RADIATOR FAN BLADE (LH) <i>HN</i>			\$ 233.10
RADIATOR FAN MOTOR (RH) <i>HN</i>			\$ 543.70
RADIATOR FAN MOTOR (LH) <i>HN</i>			\$ 543.70
DEFLECTOR,RADIATOR SIDE,RH <i>HN</i>			\$ 83.50
DEFLECTOR,RADIATOR SIDE,LH <i>HN</i>			\$ 77.00
LAMP ASSY,FOG,RH <i>broken</i>			\$ 920.00
LAMP ASSY,FOG,LH <i>HN</i>			\$ 920.00
UNIT ASSY,HEADLAMP,RH (LED) <i>broken</i>			\$ 3,455.00
UNIT ASSY,HEADLAMP,LH (LED) <i>money crack</i>			\$ 3,455.00
FRONT HEADLAMP CONTROL UNIT <i>1st o/s crack/broken</i>			\$ 1,280.00
FRONT HEADLAMP PANEL (RH) <i>1st</i>			\$ 240.10
FRONT HEADLAMP PANEL (LH) <i>1st</i>			\$ 240.10
FRONT BUMPER COVER <i>turn</i>			\$ 499.90
FRONT BUMPER REINFORCEMENT <i>Dented</i>			\$ 696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>1st</i>			\$ 165.00
FRONT BUMPER SPONGE <i>turn</i>			\$ 78.80
FRONT BUMPER CENTRE GRILLE <i>money crack/deformed</i>			\$ 301.90
FRONT BUMPER CLIPS <i>HN</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER (RH/LH) <i>o/s broken n/s</i>	<i>HN</i>	\$ 77.00	\$ 154.00
FRONT BUMPER TOP GARNISH <i>crack</i>			\$ 225.40
COVER,FRONT BUMPER,HOLE,RH <i>cut</i>			\$ 28.38
COVER,FRONT BUMPER,HOLE,LH <i>dislodged</i>			\$ 28.38
BRACKET,FRONT BUMPER SIDE,RH <i>HN</i>			\$ 82.30
BRACKET,FRONT BUMPER SIDE,LH <i>HN</i>			\$ 82.30
ENGINE UNDER COVER (RR) <i>HN</i>			\$ 457.40

Acknowledged by Repairer
Signature:
Date:

15690.56

Parts Description/Labour	Qty	Unit Price	Amount
TOP PANEL CENTRE <i>Dented</i>			\$ 364.90
TOP PANEL SIDE,LH <i>1st</i>			\$ 145.90
TOP PANEL SIDE,RH <i>1st</i>			\$ 145.90
BRACE PANEL <i>2 rep</i>			\$ 75.20
HORN <i>HL</i>		\$ 112.71	\$ 225.42
AIRDUCT <i>broken</i>			\$ 129.40
INLET ASSY,AIR CLEANER <i>HL</i>			\$ 132.00
AIRDUCT CENTRE <i>detached</i>			\$ 94.03
COMPRESSOR ASSY,W/MOTOR <i>HL</i>			\$ 2,924.20
CONDENSER ASSY,W/RECEIVER <i>2 1st</i>			\$ 1,336.60
AIRCON DISCHARGE HOSE <i>2 1st</i>			\$ 386.90
AIRCON LIQUID HOSE & PIPE <i>2 1st</i>			\$ 580.45
FENDER SUB-ASSY,FRONT LH <i>Dented</i>			\$ 945.30
FENDER SUB-ASSY,FRONT RH <i>Dented</i>			\$ 945.30
FRONT HOUSING ASSY,RH <i>known Dented</i>			\$ 958.30
FRONT FENDER SHIELD,RH <i>torn</i>			\$ 196.60
FRONT FENDER SHIELD CLIP <i>Hec</i>		\$ 38.00	\$ 76.00
FRONT FENDER HYBRID EMBLEM,LH <i>Hec</i>			\$ 53.50
FRONT FENDER HYBRID EMBLEM,RH <i>Hec</i>			\$ 53.50
FRONT FENDER HOUSING BRACKET,RH <i>repaired 1st</i>			\$ 44.50
FRONT WINDSCREEN GLASS <i>Crack</i>			\$ 1,627.30
FRONT WINDSCREEN GLASS MOULDING <i>Hec</i>			\$ 208.60
WIPER TOP GARNISH <i>Crack</i>			\$ 668.32
WIPER SPARE TANK <i>broken</i>			\$ 183.75
WIPER SPARE TANK MOTOR <i>Dome</i>			\$ 242.70
ENGINE CROSS MEMBER <i>2 Dented 1st</i>			\$ 2,531.70
ENGINE CHASSIS MEMBER (RH) <i>torn</i>			\$ 2,035.10
ENGINE MOUNTING (FRONT) <i>1st</i>			\$ 174.63
ENGINE MOUNTING (REAR) <i>HL</i>			\$ 172.90
WIRING FRONT <i>2 socket broken / wiring torn</i>			\$ 6,685.90
FRONT WIPER GARNISH RH/LH <i>dislodged / broken</i>		\$ 26.50	\$ 53.00
FRONT RADIATOR SPARE TANK <i>2 broken</i>			\$ 395.30
FRONT DOOR RH/LH <i>0/5 Dented n/s rep</i>		\$ 1,264.00	\$ 2,528.00
FRONT DOOR MIRROR OUTER RH <i>broken HL</i>			\$ 212.80
MIRROR ASSY OUTER REAR VIEW RH <i>broken</i>			\$ 1,390.10
FRONT WINDSCREEN PILLAR RH <i>known Dented</i>			\$ 343.10
FRONT WINDSCREEN PILLAR COVER RH <i>dislodged</i>			\$ 196.00
ROCKER PANEL OUTER GARNISH RH <i>1st</i>			\$ 576.00
WATER PUMP ASSY <i>HL crack</i>			\$ 925.30
FAN BELT <i>HL</i>			\$ 155.00
FRONT BUMPER UNDER COVER <i>2 broken</i>			\$ 180.80
FRT ABS WIRE <i>1st torn</i>			\$ 455.10
FRONT WHEEL RIM <i>1st / crack</i>			\$ 1,555.10
FRONT WHEEL CAP <i>HF</i>			\$ 177.70
FRONT WHEEL BEARING RH <i>2 Dome</i>			\$ 560.10
FRONT SHOCK ABSORBER <i>2 broken</i>			\$ 401.80
FRONT SHOCK ABSORBER MOUNTING <i>HL</i>			\$ 196.20

27075.68

[illegible]