

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI20000581/HVD3E2
Date: 12/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00000391900
Claimant Vehicle No :	FBL8109G	Insured Vehicle No :	SLS9007E
Date of Loss:	02/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200103C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL8109G	Engine No:	590226425
Make & Model:	KTM 390 DUKE, 390cc	Chassis No:	VBKJGJ407FC268503
Reg. Date:	16/03/2017 (Man. Year: 2016)	Odometer:	16216 km
Colour:	Orange		
Engine Capacity:	373 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,000.81	2,243.70	11,757.11	83.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	320.00	360.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,680.81	2,563.70	12,117.11	82.54
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	14,680.81	2,050.00	12,630.81	86.04
+ GST 8.00/8.00% (S\$)	1,174.46	164.00	1,010.46	86.04
Nett Amount (S\$)	15,855.27	2,214.00	13,641.27	86.04

INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	09/01/2020 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 May 2023)	
Parts:	N/A	KTM 390 DUKE 390cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL8109G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR	N/S Cut	372.00 FL	*186.00 FL
2	1		*FRONT SIGNAL RL	N/S Cut	330.00 FL	*165.00 FL
3	1		*HANDLE BAR	Bent	355.00 FL	*280.00 FL
4	2		*HANDLE BAR GRIP	Necessary	124.00 FL	*124.00 FL
5	1		*RADIATOR	Not Necessary	468.30 FL	*- FL
6	1		*BRAKE LEVER	Not Necessary	186.00 FL	*- FL
7	1		*FORK ASSY	Repair	1,658.00 FL	*- FL
8	1		*UPPER TANK COVER	Cut	389.00 FL	*389.00 FL
9	1		*LOWER TANK COVER	Not Necessary	245.00 FL	*- FL
10	1		*SIDE BALANCER	N/S Cut	336.00 FL	*68.00 FL
11	2		*FRONT FOOT REST AND BRACKER R/L	Serviceable	386.50 FL	*- FL
12	2		*PILLION FOOT REST AND BRACKER RL	Serviceable	387.80 FL	*- FL
13	1		*KICK START PEDAL	Not Necessary	253.00 FL	*- FL
14	1		*BRAKE PEDAL	Not Necessary	225.30 FL	*- FL
15	1		*CLUTCH PEDAL	Cut	236.00 FL	*137.00 FL
16	1		*BALACER	Not Necessary	226.00 FL	*- FL
17	1		*ENGINE COVER	Cut	387.00 FL	*387.00 FL
18	1		*EXHAUST ASSY	Not Necessary	1,554.00 FL	*- FL
19	1		*EXHAUST MUFFLER	Not Necessary	1,125.00 FL	*- FL
20	1		*EXHAUST BRACKER	Not Necessary	356.00 FL	*- FL
21	1		*TAIL FENDER	Not Necessary	186.00 FL	*- FL
22	1		*TAIL SIGNAL RL	N/S Cut	314.00 FL	*157.00 FL
23	1		*TAIL BRACKET	Not Necessary	165.00 FL	*- FL
24	1		*FRONT RIGHT FAIRING	Not Necessary	686.00 FL	*- FL
25	1		*TAIL RIGHT SIDE COVER	Not Necessary	357.00 FL	*- FL
26	1		*FRONT FENDER	Cut	321.00 FL	*250.00 FL
27	1		*FRONT MASTER PUMP	Not Necessary	483.00 FL	*- FL
28	1		*TAIL LIGHT	Not Necessary	468.00 FL	*- FL
29	1		*SWING ARM	Not Necessary	538.00 FL	*- FL
30	1		*PILLION SEAT	Not Necessary	338.00 FL	*- FL
31	1		*PILLION HOLDER	Not Necessary	253.00 FL	*- FL
32	1		*REAR TYRE	Not Necessary	165.00 FS	*- FS
33	1		*REAR RIM	Not Necessary	359.00 FS	*- FS
34	1		*HELMET (LOCAL REPAIR)	Scratched	280.00 FS	*100.00 FS
35	1		*REAR BOX	Not fitted	280.00 FS	*- FS
36	1		*BOX BRACKET	Repair	148.80 FS	*- FS
37	1		*REAR NUMBER PLATE	Bent	30.00 FS	*15.00 FS
38	1		*STICKER	Necessary	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,371.70	2,458.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,370.89	214.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					14,000.81	2,243.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL	New	80.00	20.00
2	LABOUR	New	600.00	300.00
Gross Labour Cost (\$\$)			680.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >