

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ7047T**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 07.01.20
 TIME OF ACCIDENT : 14:10HRS

27	FRONT DOOR PILLAR (INNER) LH <i>Replaced</i>	1	\$ 894.50	\$ 894.50	✓
28	FRONT DOOR PILLAR (OUTER) LH <i>Replaced</i>	1	\$ 894.30	\$ 894.30	✓
29	FRONT DOOR PILLAR INNER GARNISH LH <i>Replaced</i>	1	\$ 247.10	\$ 247.10	✓
30	FRONT PILLAR SUPPORT BAR <i>Best</i>	1	\$ 946.30	\$ 946.30	✓
31	FRONT STEP PANEL GARNISH LH <i>new</i>	1	\$ 318.90	\$ 318.90	+
32	FRONT DOOR LH <i>Dislodged</i>	2	\$ 1,769.70	\$ 3,539.40	1769.70
33	FRONT DOOR FRAME RUBBER LH <i>new</i>	1	\$ 236.10	\$ 236.10	+
34	FRONT DOOR INNER RUBBER LH <i>lt</i>	1	\$ 201.40	\$ 201.40	✓
35	FRONT DOOR OUTER MOULDING LH <i>Replaced</i>	1	\$ 191.10	\$ 191.10	✓
36	FRONT DOOR HINGE LH <i>Best</i>	2	\$ 78.90	\$ 157.80	✓
37	FRONT DOOR CHECKER LH <i>Best</i>	1	\$ 149.50	\$ 149.50	✓
38	FRONT DOOR WEATHER STRIP LH <i>lt</i>	1	\$ 195.60	\$ 195.60	✓
39	FRONT DOOR ARCH RUBBER LH <i>Replaced</i>	1	\$ 264.60	\$ 264.60	✓
40	FRONT DOOR GLASS CHANNEL LH <i>Best</i>	1	\$ 198.10	\$ 198.10	✓
41	FRONT DOOR INNER LOCK LH <i>Replaced</i>	1	\$ 306.40	\$ 306.40	✓
42	FRONT DOOR LOCK INNER HANDLE LH <i>new</i>	1	\$ 327.70	\$ 327.70	+
43	FRONT DOOR LOCK CATCH LH <i>new</i>	1	\$ 42.10	\$ 42.10	+
44	FRONT DOOR POWER SWITCH CONTROL C/W PANEL <i>new</i>	2	\$ 545.40	\$ 1,090.80	+
45	FRONT DOOR STOPPER LH <i>new</i>	2	\$ 19.80	\$ 39.60	+
46	FRONT DOOR INNER HOLDER <i>new</i>	2	\$ 64.10	\$ 128.20	+
47	FRONT DOOR INNER TRIM BOARD <i>Replaced</i>	2	\$ 942.60	\$ 1,885.20	942.60
48	FRONT DOOR GLASS LH <i>Shattered</i>	1	\$ 725.90	\$ 725.90	✓
49	FRONT DOOR GLASS SIDE GARNISH LH <i>new</i>	1	\$ 96.40	\$ 96.40	+
50	FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 596.30	\$ 596.30	+
51	FRONT DOOR REGULATOR LH <i>Replaced</i>	1	\$ 436.60	\$ 436.60	✓
52	FRONT DOOR WIRE HARNESS LH <i>new</i>	1	\$ 769.40	\$ 769.40	+
53	FRONT DOOR SPEAKER LH <i>new</i>	1	\$ 348.10	\$ 348.10	+
54	FRONT WHEEL ARCH PANEL LH <i>Repaired</i>	1	\$ 649.90	\$ 649.90	+
55	FRONT WHEEL ARCH RUBBER LH <i>Replaced</i>	1	\$ 365.40	\$ 365.40	+
56	FRONT FLOOR PANEL SIDE GARNISH LH <i>Replaced</i>	1	\$ 343.10	\$ 343.10	✓
57	FRONT DASHBOARD <i>Repaired</i>	1	\$ 1,250.40	\$ 1,250.40	✓
58	FRONT DASHBOARD GLOVE COMPARTMENT C/W AIRBAG <i>Repaired</i>	1	\$ 3,878.20	\$ 3,878.20	✓
59	FRONT DASHBOARD CENTER LOWER COVER GARNISH <i>Replaced</i>	1	\$ 396.40	\$ 396.40	✓
60	FRONT DASHBOARD SWITCH CONTROL PANEL <i>Replaced</i>	1	\$ 764.30	\$ 764.30	✓
61	FRONT SPEEDOMETER <i>Replaced</i>	1	\$ 1,151.70	\$ 1,151.70	✓

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ7047T**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 07.01.20
 TIME OF ACCIDENT : 14:10HRS

62	FRONT SPEEDOMETER COVER <i>could</i>	1	\$ 346.30	\$ 346.30	✓
63	AIR BAG CONTROL UNIT <i>new</i>	1	\$ 782.20	\$ 782.20	✓
64	FRONT ROOF LINING <i>could</i>	1	\$ 1,388.90	\$ 1,388.90	✓
65	CARBIN HINGE (FRONT) <i>new</i>	1	\$ 2,468.30	\$ 2,468.30	+
66	CABIN ROOF PANEL <i>Reps</i>	1	\$ 1,758.10	\$ 1,758.10	+
67	CABIN ROOF SIDE PANEL (INNER) LH <i>Reps</i>	1	\$ 285.70	\$ 285.70	+
68	CABIN ROOF SIDE PANEL (OUTER) LH <i>Reps</i>	1	\$ 348.60	\$ 348.60	+
69	CABIN BACK PILLAR (OUTER) LH <i>Reps</i>	1	\$ 469.90	\$ 469.90	+
70	CABIN BACK PILLAR (INNER) LH <i>Reps</i>	1	\$ 327.80	\$ 327.80	+
71	CABIN BACK CHASSIS MEMBER LH <i>Reps</i>	1	\$ 896.70	\$ 896.70	+
72	CABIN CHASSIS MEMBER COVER GARNISH LH <i>new</i>	1	\$ 87.40	\$ 87.40	✓
73	CABIN LOCK SYSTEM <i>new</i>	1	\$ 983.10	\$ 983.10	+
74	CABIN FLOORPANEL <i>Reps</i>	1	\$ 2,414.40	\$ 2,414.40	+
75	CABIN FLOOR MATT <i>new</i>	1	\$ 863.70	\$ 863.70	+
76	WASHER TANK <i>Detid</i>	1	\$ 168.30	\$ 168.30	✓
77	AIR CON CONDENSER <i>Detid</i>	1	\$ 987.70	\$ 987.70	✓
78	AIR CON CONDENSER SUPPORT BRACKET <i>Detid</i>	1	\$ 236.30	\$ 236.30	✓
79	AIR CON CONDENSER FAN MOTOR C/W COWLING <i>could</i>	1	\$ 429.80	\$ 429.80	✓
80	AIR CON BLOWER <i>could</i>	1	\$ 1,758.60	\$ 1,758.60	✓
81	AIR CON COOLING COIL <i>could</i>	1	\$ 2,379.20	\$ 2,379.20	✓
82	AIR CON HEATER <i>new</i>	1	\$ 983.80	\$ 983.80	+
83	AIR CON PIPE <i>Set</i>	2	\$ 396.50	\$ 793.00	✓
84	FRONT WIRE HARNESS <i>new</i>	1	\$ 7,200.70	\$ 7,200.70	+

35341
26505.75

TOTAL PRICE \$ 65,003.80
 LESS 25% \$ 16,250.95
SUB TOTAL PRICE \$ 48,752.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	LED LIGHT (SPECIAL TYPE) (SET) <i>new</i>	1	\$ 480.00	\$ 480.00	+
3	FRONT WINDSCREEN GLASS SEALANT <i>Reps</i>	1	\$ 80.00	\$ 80.00	40
4	FRONT WINDSCREEN GLASS INNER SEAL	1	\$ 60.00	\$ 60.00	40
5	FRONT ERP BRACKET <i>new</i>	1	\$ 40.00	\$ 40.00	26
6	FRONT DOOR PILLAR SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	FRONT DOOR LTA STICKER <i>new</i>	1	\$ 40.00	\$ 40.00	30
8	FRONT FLOOR PANEL SIDE GARNISH CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20

TQ : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ7047T**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 07.01.20
 TIME OF ACCIDENT : 14:10HRS

9	FRONT DASHBOARD CLIP (SET) <i>me</i>	1	\$ 150.00	\$ 150.00	<i>50</i>
10	FRONT ROOF LINING CLIP (SET) <i>me</i>	1	\$ 150.00	\$ 150.00	<i>80</i>
11	CABIN ROOF SIDE PANEL (INNER) SEALANT LH <i>2</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	CABIN ROOF SIDE PANEL (OUTER) SEALANT LH <i>1</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
13	CABIN CHASSIS MEMBER COVER GARNISH CLIP LH (SET) <i>me</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
14	RADIO <i>me</i>	1	\$ 1,200.00	\$ 1,200.00	<i>+</i>
<i>286</i>			TOTAL	\$ 2,680.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 4,800.00	<i>2400 2800 -</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 2,800.00	<i>1600</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 380.00	<i>200</i>
7	TRANSFER FRONT DOOR MECHANISM X2	\$ 180.00	<i>80</i>
8	REMOVE AND REFIX AND AUDIO SYSTEM	\$ 200.00	<i>120</i>
9	REMOVE AND REFIX AIR CON BLOWER AND AIR CON CENDENSER	\$ 400.00	<i>80</i>
10	REMOVE AND REFIX CABIN	\$ 1,200.00	<i>600</i>
11	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
12	REMOVE AND REFIX DASHBOARD	\$ 650.00	<i>220</i>
13	REMOVE AND REFIX WIRE HARNESS	\$ 1,800.00	<i>x</i>
14	RESET AIR BAG SYSTEM	\$ 550.00	<i>380</i>
15	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	<i>✓</i>

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBJ7047T**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 07.01.20
 TIME OF ACCIDENT : 14:10HRS

16	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$	350.00 100
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00 +

TOTAL \$ **14,180.00** 6450

ESTIMATE REPORT

TOTAL PARTS COST : \$ 51,432.85
 TOTAL LABOUR COST : \$ 14,180.00
 TOTAL REPAIR COST : \$ 65,612.85

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY (HP:9856 4815)

Adrian Ling
 r/s 09/01/20.

28 Days.

total: 83241.75
 r/s: 26.5K

26.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: