



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20000583/Ayd3e2

50 RAFFLES PLACE  
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 07-04-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                 |                       |            |
|---------------------|-----------------|-----------------------|------------|
| <b>Insured Veh.</b> | YP 731T         | <b>Veh. Inspected</b> | GBJ 7047T  |
| <b>Policy No.</b>   |                 | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | CMTD2000147/GPL | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | GRACE TEO       | <b>Assign Date</b>    | 09/01/2020 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |          |
|-------------------------|-------------------|---------------------|----------|
| <b>Make &amp; Model</b> | TOYOTA DYNA       | <b>c.c</b>          | 2982     |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2019     |
| <b>Chassis No.</b>      | JTFAT35Y10K213613 | <b>Colour</b>       | WHITE    |
| <b>Odometer</b>         | 30453             | <b>Steering</b>     | IN ORDER |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | NIL      |
| <b>General</b>          | GOOD              |                     |          |

### 3. Conditions of Tyres

|                       | Size       | Make        | Balance |
|-----------------------|------------|-------------|---------|
| <b>R/H Front Tyre</b> | 195/75 R15 | BRIDGESTONE | 6 mm    |
| <b>L/H Front Tyre</b> | 195/75 R15 | BRIDGESTONE | 6 mm    |
| <b>R/H Rear Tyre</b>  | 155 R12    | BRIDGESTONE | 6 mm    |
| <b>L/H Rear Tyre</b>  | 155 R12    | BRIDGESTONE | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |   |                        |            |
|-----------------------|---|------------------------|------------|
| <b>Accident Date</b>  | 07/01/2020  | <b>Inspection Date</b> | 09/01/2020 |
| <b>Survey held at</b> | VISION AUTOWORK PTE LTD<br>8 KAKI BUKIT AVE 4,<br>#08-09 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                        |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **28 Working Days**