

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000585/UES3Q2

**Date:** 09/04/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900010017  
**Claimant**  
**Vehicle No :** GBD2973J **Insured Vehicle No :** SMG6917A  
Date of Loss: 09/01/2020 Nature of Claim: TP Claim No: 3480381847SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD2973J**  
Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) Engine No: K9KC400D053749  
Reg. Date: 29/08/2014 (Man. Year: 2014) Chassis No: VSKYBAM20Z0087453  
Colour: Grey Odometer: 74627 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,229.00	7,479.10	6,749.90	47.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	3,190.00	410.00	11.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,829.00</b>	<b>10,669.10</b>	<b>7,159.90</b>	<b>40.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,500.00</b>		
<b>(S\$)</b>	17,829.00	8,500.00	9,329.00	52.32
<b>+ GST 7.00/7.00% (S\$)</b>	1,248.03	595.00	653.03	52.32
<b>Nett Amount (S\$)</b>	<b>19,077.03</b>	<b>9,095.00</b>	<b>9,982.03</b>	<b>52.32</b>
<b>+ Loss of Use (11.0 x S\$60.00/day) (S\$)</b>		660.00		
<b>Nett Liability (S\$)</b>		<b>9,755.00</b>		

#### INSPECTION

Date of Assignment: 09/01/2020  
Date Inspected: 09/01/2020 Inspected At: Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883  
Estimated Period of Repair: 10.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR LH	Badly Dented	1,462.30 F	*1,281.00 FL
2	1		*REAR BACK DOOR WIPER MOTOR LH	Shorted / Jammed	285.00 F	*285.00 FL
3	1		*REAR BACK DOOR WIPER MOTOR ARM LH	Not Necessary	89.30 F	*- FL
4	1		*REAR BACK DOOR WIPER BLADE LH	Not Necessary	45.20 F	*- FL
5	1		*REAR BACK DOOR LICENCE PLATE LAMP	Not Necessary	245.30 F	*- FL
6	1		*REAR BACK DOOR OUTER GARNISH LH	Torn	289.50 F	*289.50 FL
7	1		*REAR BACK DOOR INNER HANDLE	Not Necessary	66.50 F	*- FL
8	1		*REAR BACK DOOR INNER LOCK TOP LH	Not Necessary	90.50 F	*- FL
9	1		*REAR BACK DOOR INNER LOCK BOTTOM LH	Twisted	165.80 F	*145.00 FL
10	1		*REAR BACK DOOR INNER LOCK MECHANISM LH	Jammed	188.20 F	*188.20 FL
11	1		*REAR BACK DOOR INNER TRIM BOARD LH	Not Necessary	193.30 F	*- FL
12	1		*REAR BACK DOOR HINGES (LH)	Lower Bent	197.00 F	*98.50 FL
13	1		*REAR BACK DOOR RH	Repair	1,053.70 F	*- FL
14	1		*REAR BACK DOOR RUBBER CENTRE	Twisted	88.50 F	*88.50 FL
15	1		*REAR BACK DOOR INNER LOCK TOP RH	Not Necessary	90.50 F	*- FL
16	1		*REAR BACK DOOR INNER LOCK BOTTOM RH	Not Necessary	165.80 F	*- FL
17	1		*REAR BACK DOOR INNER TRIM RH	Not Necessary	193.30 F	*- FL
18	2		*REAR BACK DOOR HINGES (RH)	Not Necessary	197.00 F	*- FL
19	1		*REAR BUMPER	Deformed	652.00 F	*624.80 FL
20	1		*REAR BUMPER RETAINERS	N/S Bent	70.00 F	*35.00 FL
21	2		*REAR BUMPER REFLECTORS	Not Necessary	95.80 F	*- FL
22	1		*REAR BUMPER SPONGE	Torn	98.50 F	*98.50 FL
23	1		*REAR SPARE TYRE BRACKET	Not Necessary	242.80 F	*- FL
24	1		*REAR SPARE TYRE BRACKET LOCK	Not Necessary	60.50 F	*- FL
25	1		*REAR END PANEL INNER	Badly Dented	345.00 F	*245.80 FL
26	1		*REAR END PANEL OUTER	Badly Dented	485.10 F	*485.10 FL
27	1		*REAR FLOOR PANEL	Crumpled / Buckled	2,162.30 F	*1,751.00 FL
28	1		*NV 200 EMBLEM	Necessary	163.50 F	*79.90 FL
29	1		*DCI EMBLEM	Necessary	155.20 F	*80.90 FL
30	1		*NISSAN LOGO	Necessary	35.80 F	*35.80 FL
31	1		*REAR END PANEL TOP GARNISH	Torn	198.60 F	*198.60 FL
32	1		*REAR END PANEL WEATHERSTRIP	Torn	82.80 F	*82.80 FL
33	1		*TAILLAMPS	N/S Cracked	639.40 F	*252.10 FL
34	1		*REAR FLOOR PANEL TOP MAT	Not Necessary	650.00 F	*- FL
35	1		*REAR FENDER N/S	Badly Dented / Buckled	1,985.00 F	*1,553.00 FL
36	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*- FS
37	1		*SET REAR BACK DOOR INNER TRIM BOARD CLIPS LH	Necessary	30.00 FS	*30.00 FS
38	1		*SET REAR BACK DOOR INNER TRIM BOARD CLIPS RH	Not Necessary	30.00 FS	*- FS
39	1		*70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
40	1		*6 PAX STICKER	Necessary	20.00 FS	*10.00 FS
41	1		*BOL REAR BACK DOOR GLASS SEALANTS	N/S Necessary	100.00 FS	*40.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	10.00 FS	*- FS
44	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
46	1		*SET REAR CORPORATE STICKER	Not fitted	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 14,229.00 8,269.00**

**- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 789.90**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (\$)</b>	<b>14,229.00</b>	<b>7,479.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	100.00	50.00
2	TO REMOVE & REFIX REAR BACK DOOR GLASS LH	New	150.00	100.00
3	TO TRANSFER REAR BOTH BACK DOOR MECHANISM	New	150.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,900.00	1,800.00
6	TO SPRAY RUST PROOFING	New	100.00	100.00
7	TO PUTTY & SPRAY PAINTING	New	1,100.00	1,080.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,600.00</b>
				<b>3,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >