

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000586/UDA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800022832

Claimant
Vehicle No : FBN790E **Insured Vehicle No :** SLW6289G

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: 9150276497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN790E	Engine No:	E3F5E044967
Make & Model:	YAMAHA YBR125, 124cc (M)	Chassis No:	LBP101000059687
Reg. Date:	04/07/2018 (Man. Year: 2017)	Odometer:	55646 km
Colour:	Black		
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-18	Rear Tyre Size:	80-90-18
Front Left Side:	FKR 6 mm	Rear Left Side:	FKR 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,839.10	1,714.60	2,124.50	55.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	505.00	280.00	225.00	44.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,344.10	1,994.60	2,349.50	54.08
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	4,344.10	1,500.00	2,844.10	65.47
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,600.00		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 09/01/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	65.00 FL	*65.00 FL
2	1		*TOP COWLING	Cracked	105.00 FL	*105.00 FL
3	1		*WINDSHIELD	Cracked	55.00 FL	*55.00 FL
4	1		*HEADLAMP	Scratched	105.00 FL	*105.00 FL
5	2		*FORK INNER TUBES	Bent / Twisted	270.00 FL	*270.00 FL
6	2		*FORK OUTER TUBES	Not Necessary	290.00 FL	*- FL
7	1		*FORK UNDER BRACKET	Bent	145.00 FL	*145.00 FL
8	1		*FRONT BRAKE DISC	Serviceable	155.00 FL	*- FL
9	1		*FRONT RIM SHAFT	Scratched	45.00 FL	*45.00 FL
10	1		*FRONT SPORT RIM	Bent / Cut	320.00 FL	*320.00 FL
11	1		*FRONT SIGNAL	Scratched	58.00 FL	*58.00 FL
12	1		*HANDLE -BAR	Bent	95.00 FL	*95.00 FL
13	1		*SET HANDLE -BAR GRIP	Torn	50.00 FL	*50.00 FL
14	1		*BRAKE LEVER	Scratched	30.00 FL	*30.00 FL
15	1		*SIDE MIRROR -R/H	Cut	50.00 FL	*50.00 FL
16	1		*SIDE COWLING -R/H	Cut	155.00 FL	*155.00 FL
17	1		*FRONT FOOTREST -R/H	Bent	45.00 FL	*45.00 FL
18	1		*FRONT FOOTREST RUBBER	Torn	28.00 FL	*28.00 FL
19	1		*BRAKE PEDAL	Cut	48.00 FL	*48.00 FL
20	1		*REAR FOOTREST -R/H	Not Necessary	35.00 FL	*- FL
21	1		*REAR FOOTREST BRACKET	Not Necessary	80.00 FL	*- FL
22	1		*EXHAUST PIPE	Not Necessary	485.00 FL	*- FL
23	1		*EXHAUST PROTECTOR	Cut	35.00 FL	*35.00 FL
24	1		*REAR TAILBOARD	Not Necessary	145.00 FL	*- FL
25	1		*MAIN STAND	Not Necessary	95.00 FL	*- FL
26	1		*SET NUMBER PLATE	Cut	28.00 FS	*10.00 FS
27	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
28	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
29	1		*SET STEERING CONE	Necessary	85.00 FS	*85.00 FS
30	1		*REAR BOX	Serviceable	350.00 FS	*- FS
31	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
32	1		*GRAB FOOD BAG	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,138.00	1,885.00
- List Item Discount on L Items 10.00/10.00% (S\$)	298.90	170.40
Total Parts (S\$)	3,839.10	1,714.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	45.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	280.00
Gross Labour Cost (\$\$)			505.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >