

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2020 Edit Reg		08 Jan 2020 00:00 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM PETER , ID: S1731502A		
Main Claimant:	CHEN KANGXING		
Vehicle Reg. No.:	SLL1500L	Date of Loss:	06/01/2020 14:00 - :59 [26 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4306335620SG	Policy/Cover Note No.:	1800105514 (Comprehensive)
Vehicle Reg. No. (Insured):	SMD8876L	Policy No. (Claimant):	1700069456-02
		Excess:	
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (08/10/2020): **Alert - Adj Mandate Approved (S\$16881.39) - SLL1500L - Claim Handler: Syed-Yusof...**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SLL1500L (4306335620SG)
[SMD8876L]
TP
CHEN KANGXING
Jan 6 2020 2:00PM
[LIM PETER]
Vision Autowork Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	29/01/20 10:32		General View													Load JPG		☒		
2	29/01/20 10:32		General View													Load JPG		☒		
3	29/01/20 10:32		General View													Load JPG		☒		
4	29/01/20 10:32		General View													Load JPG		☒		
5	29/01/20 10:32		General View													Load JPG		☒		
6	29/01/20 10:32		General View													Load JPG		☒		
7	29/01/20 10:32		General View													Load JPG		☒		
8	29/01/20 10:32		General View													Load JPG		☒		
9	29/01/20 10:32		General View													Load JPG		☒		
10	29/01/20 10:32		General View													Load JPG		☒		
11	29/01/20 10:32		General View													Load JPG		☒		
12	29/01/20 10:32		General View													Load JPG		☒		
13	29/01/20 10:32		General View													Load JPG		☒		
14	29/01/20 10:32		General View													Load JPG		☒		
15	29/01/20 10:32		General View													Load JPG		☒		
16	29/01/20 10:32		General View													Load JPG		☒		
17	29/01/20 10:32		General View													Load JPG		☒		
18	29/01/20 10:32		General View													Load JPG		☒		
19	29/01/20 10:32		General View													Load JPG		☒		
20	29/01/20 10:32		General View													Load JPG		☒		
21	29/01/20 10:32		General View													Load JPG		☒		
22	29/01/20 10:32		General View													Load JPG		☒		
23	29/01/20 10:32		General View													Load JPG		☒		
24	29/01/20 10:32		General View													Load JPG		☒		
25	29/01/20 10:32		General View													Load JPG		☒		
26	29/01/20 10:32		General View													Load JPG		☒		
27	29/01/20 10:32		General View													Load JPG		☒		
28	29/01/20 10:32		General View													Load JPG		☒		
29	29/01/20 10:32		General View													Load JPG		☒		
30	29/01/20 10:32		General View													Load JPG		☒		
31	29/01/20 10:32		General View													Load JPG		☒		
32	29/01/20 10:32		General View													Load JPG		☒		

Letters/Correspondences			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	29/01/20 10:32	General View	 Load JPG	☒
34	29/01/20 10:32	General View	 Load JPG	☒
35	29/01/20 10:32	General View	 Load JPG	☒
36	29/01/20 10:32	General View	 Load JPG	☒
37	29/01/20 10:32	General View	 Load JPG	☒
38	29/01/20 10:32	General View	 Load JPG	☒
39	29/01/20 10:32	General View	 Load JPG	☒
40	29/01/20 10:32	General View	 Load JPG	☒
41	29/01/20 10:32	General View	 Load JPG	☒
42	29/01/20 10:32	General View	 Load JPG	☒
43	29/01/20 10:32	General View	 Load JPG	☒
44	29/01/20 10:32	General View	 Load JPG	☒
45	29/01/20 10:32	General View	 Load JPG	☒
46	29/01/20 10:32	General View	 Load JPG	☒
47	29/01/20 10:32	General View	 Load JPG	☒
48	29/01/20 10:32	General View	 Load JPG	☒
49	29/01/20 10:32	General View	 Load JPG	☒
50	29/01/20 10:32	General View	 Load JPG	☒
51	29/01/20 10:32	General View	 Load JPG	☒
52	29/01/20 10:32	General View	 Load JPG	☒
53	29/01/20 10:32	General View	 Load JPG	☒
54	29/01/20 10:32	General View	 Load JPG	☒
55	29/01/20 10:32	General View	 Load JPG	☒
56	29/01/20 10:32	General View	 Load JPG	☒
57	29/01/20 10:32	General View	 Load JPG	☒
58	29/01/20 10:32	General View	 Load JPG	☒
59	29/01/20 10:32	General View	 Load JPG	☒
60	29/01/20 10:32	General View	 Load JPG	☒
61	29/01/20 10:32	General View	 Load JPG	☒
62	29/01/20 10:32	General View	 Load JPG	☒
63	29/01/20 10:32	General View	 Load JPG	☒
64	29/01/20 10:32	General View	 Load JPG	☒
65	29/01/20 10:32	General View	 Load JPG	☒
66	29/01/20 10:32	General View	 Load JPG	☒
67	29/01/20 10:32	General View	 Load JPG	☒
68	29/01/20 10:32	General View	 Load JPG	☒
69	29/01/20 10:32	General View	 Load JPG	☒
70	29/01/20 10:32	General View	 Load JPG	☒
71	29/01/20 10:32	General View	 Load JPG	☒
72	29/01/20 10:32	General View	 Load JPG	☒
73	29/01/20 10:32	General View	 Load JPG	☒
74	29/01/20 10:32	General View	 Load JPG	☒
75	29/01/20 10:32	General View	 Load JPG	☒
76	29/01/20 10:32	General View	 Load JPG	☒
77	29/01/20 10:32	General View	 Load JPG	☒
78	29/01/20 10:32	General View	 Load JPG	☒
79	29/01/20 10:32	General View	 Load JPG	☒
80	29/01/20 10:32	General View	Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	29/01/20 10:32	General View	 Load JPG	
82	29/01/20 10:32	General View	 Load JPG	
83	29/01/20 10:32	General View	 Load JPG	
84	29/01/20 10:32	General View	 Load JPG	
85	29/01/20 10:32	General View	 Load JPG	
86	29/01/20 10:32	General View	 Load JPG	
87	29/01/20 10:32	General View	 Load JPG	
88	29/01/20 10:32	General View	 Load JPG	
89	29/01/20 10:32	General View	 Load JPG	
90	29/01/20 10:32	General View	 Load JPG	
91	29/01/20 10:32	General View	 Load JPG	
92	29/01/20 10:32	General View	 Load JPG	
93	29/01/20 10:32	General View	 Load JPG	
94	29/01/20 10:32	General View	 Load JPG	
95	29/01/20 10:32	General View	 Load JPG	
96	29/01/20 10:32	General View	 Load JPG	
97	29/01/20 10:32	General View	 Load JPG	
98	29/01/20 10:32	General View	 Load JPG	
99	29/01/20 10:32	General View	 Load JPG	
100	29/01/20 10:32	General View	 Load JPG	
101	29/01/20 10:32	General View	 Load JPG	
102	29/01/20 10:32	General View	 Load JPG	
103	29/01/20 10:32	General View	 Load JPG	
104	29/01/20 10:32	General View	 Load JPG	
105	29/01/20 10:32	General View	 Load JPG	
106	29/01/20 10:32	General View	 Load JPG	
107	29/01/20 10:32	General View	 Load JPG	
108	29/01/20 10:33	General View	 Load JPG	
109	29/01/20 10:33	General View	 Load JPG	
110	29/01/20 10:33	General View	 Load JPG	
111	29/01/20 10:33	General View	 Load JPG	
112	29/01/20 10:33	General View	 Load JPG	
113	29/01/20 10:33	Reinspection Photo	 Load JPG	
114	29/01/20 10:33	Reinspection Photo	 Load JPG	
115	29/01/20 10:33	Reinspection Photo	 Load JPG	
116	29/01/20 10:33	Reinspection Photo	 Load JPG	
117	29/01/20 10:33	Reinspection Photo	 Load JPG	
118	29/01/20 10:33	Reinspection Photo	 Load JPG	
119	29/01/20 10:33	Reinspection Photo	 Load JPG	
120	29/01/20 10:33	Reinspection Photo	 Load JPG	
121	29/01/20 10:33	Reinspection Photo	 Load JPG	
122	29/01/20 10:33	Reinspection Photo	 Load JPG	
123	29/01/20 10:33	Reinspection Photo	 Load JPG	
124	29/01/20 10:33	Reinspection Photo	 Load JPG	
125	29/01/20 10:33	Reinspection Photo	 Load JPG	
126	29/01/20 10:33	Reinspection Photo	 Load JPG	
127	29/01/20 10:33	Reinspection Photo	 Load JPG	
128	29/01/20 10:33	Reinspection Photo	Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
129	29/01/20 10:33	Reinspection Photo	Load JPG	☒
130	29/01/20 10:33	Reinspection Photo	Load JPG	☒
131	29/01/20 10:33	Reinspection Photo	Load JPG	☒
132	29/01/20 10:33	Reinspection Photo	Load JPG	☒
133	29/01/20 10:33	Reinspection Photo	Load JPG	☒
134	29/01/20 10:33	Reinspection Photo	Load JPG	☒
135	29/01/20 10:33	Reinspection Photo	Load JPG	☒
136	29/01/20 10:33	Reinspection Photo	Load JPG	☒
137	29/01/20 10:33	Reinspection Photo	Load JPG	☒
138	29/01/20 10:33	Reinspection Photo	Load JPG	☒
139	29/01/20 10:33	Reinspection Photo	Load JPG	☒
140	29/01/20 10:33	Reinspection Photo	Load JPG	☒
141	29/01/20 10:33	Reinspection Photo	Load JPG	☒
142	29/01/20 10:33	Reinspection Photo	Load JPG	☒
143	29/01/20 10:33	Reinspection Photo	Load JPG	☒
144	29/01/20 10:33	Reinspection Photo	Load JPG	☒
145	29/01/20 10:33	Reinspection Photo	Load JPG	☒
146	29/01/20 10:33	Reinspection Photo	Load JPG	☒
147	29/01/20 10:33	Reinspection Photo	Load JPG	☒
148	29/01/20 10:33	Reinspection Photo	Load JPG	☒
149	29/01/20 10:33	Reinspection Photo	Load JPG	☒
150	29/01/20 10:33	Reinspection Photo	Load JPG	☒
151	29/01/20 10:33	Reinspection Photo	Load JPG	☒
152	29/01/20 10:33	Reinspection Photo	Load JPG	☒
153	29/01/20 10:33	Reinspection Photo	Load JPG	☒
154	29/01/20 10:33	Reinspection Photo	Load JPG	☒
155	29/01/20 10:33	Reinspection Photo	Load JPG	☒
156	29/01/20 10:33	Reinspection Photo	Load JPG	☒
157	29/01/20 10:33	Reinspection Photo	Load JPG	☒
158	29/01/20 10:33	Reinspection Photo	Load JPG	☒
159	29/01/20 10:33	Reinspection Photo	Load JPG	☒
160	29/01/20 10:33	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/20 14:13	ACKNOWLEDGEMENT EMAIL TO AIG DD 08.01.2020	Load PDF	
2	09/01/20 14:13	EMAIL FROM AIG DD 08.01.2020	Load PDF	
3	09/01/20 14:13	NOTIFICATION FROM WORKSHOP +TP GIA REPORT	Load PDF	
4	14/05/20 12:47	LETTER TO OI	Load PDF	
5	04/10/20 13:59	LOD, REPAIR BILL, ATA,RENTAL INVOICE, RENTAL AGREEMENT, LTA SEARCH	Load PDF	
6	04/11/20 11:56	Authorisation to Act	Load PDF	
7	04/11/20 11:56	LTA SEARCH	Load PDF	
8	04/11/20 11:56	Release Voucher	Load PDF	
9	04/11/20 11:56	RENTAL RECEIPT	Load PDF	
10	04/11/20 11:56	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/01/20 12:05	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMD8876L (Insd veh)	Model:	KIA CERATO K3 1.6 SUNROOF
	SLL1500L (TP veh)		(A)
Date of Accident:	06/01/2020		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No
Repair Estimate	:	\$			36,711.17
Final Repair Cost	:	\$			16,880.00
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$			7 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$			16,880.00

Is Third Party Workshop GIA Registered? ☐ [] **YES** ☒ [X] **NO** (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Vision Autowork Pte Ltd	: \$	16,880.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

04 Nov
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20000587/AKA3S2**Date:** 04/11/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800105514
Claimant Vehicle No :	SLL1500L	Insured Vehicle No :	SMD8876L
Date of Loss:	06/01/2020	Nature of Claim:	TP
		Claim No:	4306335620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL1500L	Engine No:	G4FGHH682708
Make & Model:	KIA CERATO K3, 1.6 SUNROOF (A)	Chassis No:	KNAFZ411MJ5748772
Reg. Date:	27/10/2017 (Man. Year: 2017)	Odometer:	38010 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,369.50	16,711.20	9,658.30	36.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,940.00	3,840.00	4,100.00	51.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,309.50	20,551.20	13,758.30	40.10
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	34,309.50	15,000.00	19,309.50	56.28
+ GST 7.00/7.00% (S\$)	2,401.67	1,050.00	1,351.67	56.28
Nett Amount (S\$)	36,711.17	16,050.00	20,661.17	56.28
+ Car Rental (7.0 x S\$110.00/day + 7.00% GST) (S\$)		823.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,881.35		
Global Sum Settlement (S\$)		16,880.00		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 09/01/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI
 BUKIT
 Singapore 415875

11/4/2020

Adjuster Report

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	668.00 FL	*668.00 FL
2	2		*FRONT BUMPER SIDE AIR DUCT	Not Necessary	78.00 FL	*- FL
3	1		*FRONT BUMPER LOGO	Necessary	47.00 FL	*47.00 FL
4	2		*FRONT BUMPER FOGLAMP	Cracked	536.00 FL	*536.00 FL
5	1		*FRONT BUMPER TOWING COVER	Deformed	17.00 FL	*17.00 FL
6	4		*FRONT BUMPER SENSOR	Damaged 2pcs Only	708.00 FL	*354.00 FL
7	4		*FRONT BUMPER SENSOR HOLDER	Necessary	168.00 FL	*168.00 FL
8	1		*FRONT BUMPER NUMBER PLATE GARNISH	Cracked	101.00 FL	*101.00 FL
9	1		*FRONT BUMPER UPPER GRILLE CHROME	Cracked	328.00 FL	*328.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Cracked	79.00 FL	*79.00 FL
11	1		*FRONT BUMPER TOP BEAM	Deformed	180.00 FL	*180.00 FL
12	1		*FRONT BUMPER TOP RUBBER	Not Necessary	43.00 FL	*- FL
13	2		*FRONT BUMPER SIDE RETAINER	Necessary	34.00 FL	*34.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	398.00 FL	*398.00 FL
15	1		*FRONT BUMPER LOWER BEAM	Bent	121.00 FL	*121.00 FL
16	1		*FRONT BUMPER SPONGE	Cracked	123.00 FL	*123.00 FL
17	1		*FRONT FENDER	N/s Buckled	1,168.00 FL	*584.00 FL
18	2		*FRONT FENDER INNER COWLING	Not Necessary	218.00 FL	*- FL
19	2		*HEAD LAMP (HID)	Cracked	4,418.00 FL	*4,418.00 FL
20	2		*HEAD LAMP LOWER BRACKET	Cracked	90.00 FL	*90.00 FL
21	1		*FRONT WINDSCREEN MOULDING	Not Necessary	166.00 FL	*- FL
22	1		*FRONT WINDSCREEN PILLAR LH	Repair	1,342.00 FL	*- FL
23	1		*FRONT WIPER PANEL GARNISH	Cracked	396.00 FL	*396.00 FL
24	2		*FRONT WIPER PANEL SIDE GARNISH	Not Necessary	104.00 FL	*- FL
25	1		*BONNET	Dented	877.00 FL	*877.00 FL
26	2		*BONNET HINGE	Not Necessary	128.00 FL	*- FL
27	1		*BONNET LOCK	Damaged	65.00 FL	*65.00 FL
28	2		*BONNET STOPPER	Not Necessary	42.00 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Buckled	776.00 FL	*776.00 FL
30	1		*FRONT SUPPORT PANEL BOTTOM GARNISH	Deformed	110.00 FL	*110.00 FL
31	2		*AIRCON CONDENSER SIDE GARNISH	Deformed	42.00 FL	*42.00 FL
32	1		*AIR CON CONDENSER	Dented	668.00 FL	*668.00 FL
33	1		*AIRCON PIPE	Not Necessary	246.00 FL	*- FL
34	1		*AIR CLEANER	Not Necessary	294.00 FL	*- FL
35	1		*AIRCON HOSE (SUCTION)	Not Necessary	203.00 FL	*- FL
36	1		*AIRCON HOSE (PRESSURE)	Not Necessary	265.00 FL	*- FL
37	1		*AIR DUCT	Deformed	144.00 FL	*144.00 FL
38	1		*RADIATOR	Dented	692.00 FL	*692.00 FL
39	2		*RADIATOR TOP BRACKET	Not Necessary	42.00 FL	*- FL
40	1		*RADIATOR FAN COWLING	Not Necessary	394.00 FL	*- FL
41	1		*HORN	Not Necessary	82.00 FL	*- FL
42	1		*REAR BUMPER	Deformed	698.00 FL	*698.00 FL
43	1		*REAR BUMPER (CENTRE LOWER)	Deformed	286.00 FL	*286.00 FL
44	2		*REAR BUMPER REFLECTOR	Not Necessary	302.00 FL	*- FL
45	1		*REAR BUMPER SIDE INNER GARNISH	N/s Torn	170.00 FL	*85.00 FL
46	5		*REAR BUMPER BRACKET	Damaged 2pcs Only	175.00 FL	*70.00 FL
47	2		*REAR BUMPER SIDE RETAINER	Necessary	54.00 FL	*54.00 FL
48	1		*REAR BUMPER REINFORCEMENT	Cracked	390.00 FL	*390.00 FL
49	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	130.00 FL	*- FL
50	2		*REAR FENDER INNER COWLING	Not Necessary	190.00 FL	*- FL
51	2		*REAR FENDER INNER TRIM	Not Necessary	370.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*TAIL LAMP	N/s Cracked	1,596.00 FL	*798.00 FL
53	1		*BOOT LID	Repair	1,073.00 FL	*- FL
54	1		*BOOT LID LOGO	Necessary	33.00 FL	*33.00 FL
55	2		*BOOT LID STOPPER	Not Necessary	38.00 FL	*- FL
56	2		*BOOT LID HINGE	Not Necessary	132.00 FL	*- FL
57	1		*BOOT LID INSULATOR	Not Necessary	82.00 FL	*- FL
58	1		*BOOT LID WEATHERSTRIP	Cut	110.00 FL	*110.00 FL
59	1		*BOOT LID DETECTOR (INNER)	Cracked	265.00 FL	*265.00 FL
60	1		*BOOT LID DETECTOR (OUTER)	Cracked	272.00 FL	*272.00 FL
61	1		*BOOT LID LOCK	Not Necessary	117.00 FL	*- FL
62	1		*BOOT LID LOWER LOCK	Not Necessary	26.00 FL	*- FL
63	1		*REAR END PANEL	Dented	375.00 FL	*375.00 FL
64	1		*REAR END PANEL TOP GARNISH	Deformed	84.00 FL	*84.00 FL
65	1		*REAR FLOOR PANEL TOP BAORD	Torn	210.00 FL	*210.00 FL
66	4		*REVERSE SENSOR	Damaged 2pcs Only	708.00 FL	*354.00 FL
67	4		*REVERSE SENSOR HOLDER	Necessary	168.00 FL	*168.00 FL
68	1		*FRONT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
69	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
70	1		*SET FRONT BUMPER NUMBER PLATE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
71	1		*FRONT BUMPER LOWER LIP (SPECIAL TYPE)	Deformed	1,200.00 FS	*800.00 FS
72	1		*FRONT BUMPER LOWER RUBBER (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
73	2		*FRONT LOWER LIP BLACK STICKER (SPECIAL TYPE)	Necessary	300.00 FS	*100.00 FS
74	1		*SET CENTER GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
75	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
76	1		*SET FRONT WIPER PANEL GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
77	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
78	1		*FRONT WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
79	1		*SET FRONT SUPPORT PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
80	1		*COOLANT	Necessary	120.00 FS	*50.00 FS
81	1		*SET REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
82	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
83	1		*REAR BUMPER LOWER LIP (SPECIAL TYPE)	Deformed	1,200.00 FS	*800.00 FS
84	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
85	1		*BOOT LID EMBLEM C&C	Necessary	120.00 FS	*50.00 FS
86	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
87	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
88	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
89	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
90	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,835.00	18,338.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,465.50	1,626.80
Total Parts (\$\$)	26,369.50	16,711.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	1,400.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	1,400.00	1,000.00
3	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING.	New	160.00	110.00
4	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS.	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	New	80.00	60.00
6	REFOCUS HEADLAMP BEAM.	New	60.00	0.00
7	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS.	New	1,600.00	600.00
8	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS.	New	1,600.00	800.00
9	TUFF COAT.	New	250.00	60.00
10	WIRING CHECK.	New	180.00	30.00
11	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	350.00	60.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.	New	80.00	60.00
13	REAR CHASSIS ALIGNMENT.	New	250.00	0.00
14	TRANSFER BOOTLID MECHANISM.	New	80.00	0.00
15	CONDUCT WATER LEAKAGE TEST.	New	150.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (S\$)			7,940.00	3,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >