



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7515E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	1,185.30	1,004.10
1	FRONT BUMPER LOWER SPOILER	NOT NECESSARY	384.50	-
1	FRONT BUMPER SIDE GRILLE	NOT NECESSARY	315.10	-
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	215.10	-
	LESS 10% DISCOUNT		-210.00	-100.41
			1,890.00	903.69
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT BUMPER FOG LAMP CLIPS (SN)	NOT NECESSARY	80.00	-
1	RIM RH (SN)	NOT NECESSARY	1,000.00	-
1	TYRE RH (SN)	NOT NECESSARY	400.00	-
			1,560.00	30.00
<u>LABOUR</u>				
	CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	100.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	PANEL BEATING ON AFFECTED AREA.		800.00	200.00
	SPRAY PAINTING ON AFFECTED AREA.		500.00	200.00
	APPLY ANTI RUST ON AFFECTED AREA.	NOT NECESSARY	100.00	-
			1,600.00	400.00
GRAND TOTAL			5,050.00	1,333.69
RECOMMENDED COST OF REPAIRS				1,333.69

Report Ref No. CC4/FCI20000588/Gka3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.