Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CC4/III20000589/KGS3Q2 Our File No:

Date: 19/10/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015 Claimant SJT4883T Insured Vehicle No: SHC8474C

Vehicle No:

Date of Loss: 03/01/2020 Nature of Claim: TP Claim No: MCT20010034

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SJT4883T** Reg No:

Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 3ZZ4935284

Chassis No: Reg. Date: 15/10/2009 (Man. Year: 2009) MR053ZEE106155900

Colour: Metallic Silver Odometer: 132096 km

1598 cc **Engine Capacity:** 

Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: No Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Rear Left Side: Front Left Side: Michelin 8 mm Michelin 8 mm Front Right Side: Rear Right Side: Michelin 8 mm Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	807.65	483.10	324.55	40.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	680.00	320.00	32.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,807.65	1,163.10	644.55	35.66
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,807.65	900.00	907.65	50.21
+ GST 7.00/7.00% (S\$)	126.54	63.00	63.54	50.21
Nett Amount (S\$)	1,934.19	963.00	971.19	50.21
+ Car Rental (3.0 x S\$85.00/day + 7.	00% GST) (S\$)	272.85		
Ne	tt Liability (S\$)	1,235.85		

**INSPECTION** 

Date of Assignment: 08/01/2020

Date Inspected: 18/02/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2020)

TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SJT4883T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Mtg Cracked	423.60 FL	*423.60 FL
2	1		*FRONT BUMPER INNER TOP RUBBER	Necessary	44.30 FL	*44.30 FL
3	1		*FRT BUMPER LOGO	Necessary	60.13 FL	*60.13 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	51.94 FL	*51.94 FL
5	5		*FRONT BUMPER CLIPS	Necessary	17.50 FL	*17.50 FL
6	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	93.03 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	339.70 FL	*- FL
8	1		*FRONT BUMPER PLATE	Dented	35.00 FS	*35.00 FS
F=Fra	nchise	part. S=Spo	Nett. L=ListItemDisc.			
				Sub Total (S\$)	1,065.20	632.47
	- List Item Discount on L Items 25.00/25.00% (S\$)				257.55	149.37
				Total Parts (S\$)	807.65	483.10

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS ,LOWER SKIRT ,HEADLAMP ,KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	New	400.00	280.00
2	PUTTY & RESPRAY FRT BUMPER ,LOWER SKIRT ,REINFORCEMENT ,BONNET & ALL AFFECTED AREAS	New	600.00	400.00
	Gross Labou	r Cost (S\$)	1,000.00	680.00
	Report was unsubmitted durin	a this print-out.		

< END OF ESTIMATES >