



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005253  
INV Date 28/07/2020  
Reference CC4/FCI20000592/T1da3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SGZ 1789G  
Insured Veh. SHC 7545M  
Claim No. D19008063MFSH  
Policy No. D-19092579MFSH  
Accident Date 20/12/2019  
Inspection Date 14/01/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000592/T1da3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSES SINGAPORE 068877

Date : 28-07-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHC 7545M	<b>Veh. Inspected</b>	SGZ 1789G
<b>Policy No.</b>	D-19092579MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D19008063MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERINA CHIA	<b>Assign Date</b>	08/01/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	KIA CERATO K3	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	KNAFZ411MJ5745994	<b>Colour</b>	WHITE
<b>Odometer</b>	45000	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/45 R17	ROADSTONE	6 mm
<b>L/H Front Tyre</b>	215/45 R17	ROADSTONE	6 mm
<b>R/H Rear Tyre</b>	215/45 R17	ROADSTONE	6 mm
<b>L/H Rear Tyre</b>	215/45 R17	ROADSTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	20/12/2019	<b>Inspection Date</b>	14/01/2020
<b>Survey held at</b>	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 1789G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	C&C EMBLEM (SN)	NOT NECESSARY	50.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	EMBLEM -CERATO (SN)	NOT NECESSARY	35.00	-
1	LOGO ASSY -KIA SUB (SN)	NOT NECESSARY	37.00	-
1	COVER-RR BUMPER ,CTR (SN)	DEFORMED	347.00	347.00
1	COVER -RR BUMPER (SN)	DEFORMED	688.00	688.00
2	BRACKET -RR BEAM LWR MTG (SN)	NECESSARY	10.00	10.00
1	BRACKET-RR BEAM LWR ,CTR (SN)	NECESSARY	5.00	5.00
1	BEAM -RR BUMPER (SN)	NOT NECESSARY	318.00	-
1	ANTENNA ASSY -SMARTKEY (SN)	NOT NECESSARY	69.00	-
1	BRACKET -RR BEAM UPR MTG (SN)	NECESSARY	3.00	3.00
1	BRACKET -RR BEAM UPR MTG ,RH (SN)	NOT NECESSARY	3.00	-
1	STAY -RR BUMPER LH (SN)	NOT NECESSARY	120.00	-
1	STAY -RR BUMPER RH (SN)	NOT NECESSARY	120.00	-
1	BRACKET -RR BUMPER SIDE MTG ,LH (SN)	NECESSARY	29.00	29.00
1	BRACKET -RR BUMPER SIDE MTG ,RH (SN)	NOT NECESSARY	29.00	-
1	WIRING HARNESS -BWS EXT (SN)	NOT NECESSARY	216.00	-
1	ULTRASONIC SENSOR ASSY -P.A.S (SN)	NOT WORKING	177.00	177.00
1	ULTRASONIC SENSOR ASSY -P.A.S (SN)	NOT NECESSARY	177.00	-
1	PANEL ASSY -BACK (SN)	TO REPAIR SEE LABOUR	324.00	-
1	LAMP ASSY -REAR COMBINATION ,LH (SN)	NOT NECESSARY	788.00	-
1	NEW K3 SNOW WHITE PEARL SWP (SN)	CRACKED	1,177.00	1,177.00
			4,772.00	2,456.00
<b><u>LABOUR</u></b>				
	TO REPLACE REAR BUMPER ,REAR BODY KIT & AFFECTED AREA TO REPAIR ON REAR LH FENDER ,BOOT & END PANEL.INCLUSIVE OF THE REPAIR OF PANEL ASSY -BACK .		2,200.00	550.00
	PAINT WORK ON REAR BUMPER ,REAR LH FENDER ,END PANEL & BOOT .		1,680.00	1,260.00
	TO REMOVE & INSTALL REAR PARKING ASSIST.		150.00	150.00

Report Ref No. CC4/FCI20000592/T1da3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY SEALANT ON AFFECTED AREA.	NOT NECESSARY	80.00	-
	PERFORM RUST PREVENTION.	NOT NECESSARY	160.00	-
	CHECK ELECTRICAL SYSTEM.		80.00	80.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		180.00	180.00
			4,530.00	2,220.00
GRAND TOTAL			9,302.00	4,676.00

RECOMMENDED COST OF REPAIRS				4,676.00
-----------------------------	--	--	--	----------

Report Ref No. CC4/FCI20000592/T1da3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGZ 1789G

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGZ 1789G

RE-INSPECTION

