

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000595/ABS3Q2

**Date:** 07/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** GBA3529T

**Insured Vehicle No :** SLW174T

Date of Loss: 06/01/2020

Nature of Claim: TP

Claim No: 5867673128SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA3529T**

Make & Model: TOYOTA DYNA 100 MANUAL, 3.0 D (M)

Engine No: 1KD1639276

Reg. Date: 06/06/2007 (Man. Year: 2007)

Chassis No: JTFNT24Y405000098

Colour: Silver

Odometer: 323039 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/70R15

Rear Tyre Size:

155R12C

Front Left Side: Yokohama 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,160.00	2,083.68	4,076.32	66.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,480.00	200.00	11.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,840.00</b>	<b>3,563.68</b>	<b>4,276.32</b>	<b>54.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,850.00</b>		
<b>(S\$)</b>	7,840.00	2,850.00	4,990.00	63.65
<b>+ GST 7.00/7.00% (S\$)</b>	548.80	199.50	349.30	63.65
<b>Nett Amount (S\$)</b>	<b>8,388.80</b>	<b>3,049.50</b>	<b>5,339.30</b>	<b>63.65</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,656.95</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,560.00</b>		

### INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At:

KAI MOTOR TRADING (HQ)

BLK 3007 UBI ROAD 1, #01-440

Singapore 408701

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Dented	1,121.10 F	*1,121.10 FL
2	1		*REAR DOOR TOYOTA STICKER	Necessary	215.00 F	*215.00 FL
3	1		*REAR DOOR 70 STICKER	Necessary	48.50 FS	*10.00 FS
4	1		*REAR DOOR 13 STICKER	Necessary	48.50 FS	*10.00 FS
5	1		*REAR DOOR MEMBER	Repair	1,321.10 F	*- FL
6	1		*SPARE TYRE BRACKET	Not Necessary	298.70 F	*- FL
7	1		*REAR SPARE TYRE SUPPORT BRACKET	Not Necessary	298.70 F	*- FL
8	1		*REAR LAMP	N/S Cracked	570.20 F	*285.10 FL
9	2		*REAR NUMBER PLATE LAMP	Not Necessary	104.20 F	*- FL
10	2		*REAR SIDE BRACKET RUBBER	Damaged	130.00 F	*130.00 FL
11	1		*REAR NUMBER PLATE	Bent	55.00 F	*55.00 FL
12	1		*REAR STAP BRACKET	Bent	350.00 FS	*250.00 FS
13	1		*REAR FLOOR PANEL	Repair	1,390.00 F	*- FL
14	1		*LH DOOR SIDE BRACKET	Bent	209.00 F	*209.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,160.00</b>	<b>2,285.20</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	201.52
<b>Total Parts (\$\$)</b>	<b>6,160.00</b>	<b>2,083.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	850.00	800.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	750.00	650.00
3	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,680.00</b>	<b>1,480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >