

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20000597/HES3Q2

Date:

07/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993937

Claimant Vehicle No : SFM8189Y

Insured Vehicle No :

GBD3048Z

Date of Loss: 04/01/2020

Nature of Claim:

TP

Claim No:

6571300076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFM8189Y**

Make & Model: BMW X3, 2.0 SDRIVE 20I LED SR NAV (A)

Engine No:

A7671616N20B20A

Reg. Date: 30/05/2017 (Man. Year: 2017)

Chassis No:

WBAWY920500W22546

Colour: Black

Odometer:

66883 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size:

245/50 R18

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side:

Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,190.07	10,199.30	9,990.77	49.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,570.00	2,270.00	59.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,030.07	11,769.30	12,260.77	51.02
Approved Total (Overridden) (S\$)		9,400.00		

(S\$)	24,030.07	9,400.00	14,630.07	60.88
+ GST 7.00/7.00% (S\$)	1,682.10	658.00	1,024.10	60.88
Nett Amount (S\$)	25,712.17	10,058.00	15,654.17	60.88
+ Car Rental (5.0 x S\$160.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		10,894.45		

INSPECTION

Date of Assignment: 09/01/2020

Date Inspected: 24/02/2020

Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,497.55 FL	*1,497.55 FL
2	1		*FRONT BUMPER FOGLAMP RH	Cracked	391.10 FL	*391.10 FL
3	1		*FRONT BUMPER FOGLAMP LOWER GARNISH RH	Crumpled	122.55 FL	*122.55 FL
4	1		*FRONT BUMPER SENSOR RH (2 PCS)	Shorted (1 PCS ONLY)	553.70 FL	*276.85 FL
5	1		*FRONT BUMPER CENTER GARNISH	Cracked	698.55 FL	*698.55 FL
6	1		*FRONT BUMPER CENTER BOTTOM GARNISH	Serviceable	465.65 FL	*- FL
7	1		*FRONT BUMPER NUMBER PLATE GARNISH	Serviceable	147.95 FL	*- FL
8	1		*FRONT BUMPER CENTER GRILLE	Cracked	343.65 FL	*343.65 FL
9	1		*FRONT BUMPER SPONGE (2 PCS)	Cracked (1 PCS ONLY)	454.90 FL	*227.45 FL
10	1		*FRONT BUMPER CENTER BRACKET	N/S Not Necessary / O/SCracked	149.30 FL	*74.65 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	697.55 FL	*697.55 FL
12	2		*FRONT GRILLE C/W CHROME	Serviceable	221.70 FL	*- FL
13	2		*FRONT GRILLE CHROME BRACKET	Serviceable	64.40 FL	*- FL
14	1		*FRONT LOWER GRILLE	Cracked	476.80 FL	*476.80 FL
15	1		*HEADLAMP (LED)	O/S Cracked / N/SNot Necessary	8,548.10 FL	*4,274.05 FL
16	1		*HEADLAMP NOZZLE RH	Cracked	196.45 FL	*196.45 FL
17	1		*HEADLAMP NOZZLE COVER RH	Serviceable	75.95 FL	*- FL
18	1		*HEADLAMP NOZZLE TUBE RH	Serviceable	62.15 FL	*- FL
19	1		*HEADLAMP LOWER BRACKET RH	Repair	185.25 FL	*- FL
20	1		*FRONT BONNET	Repair	1,767.55 FL	*- FL
21	1		*FRONT BONNET LOGO	Necessary	69.50 FL	*69.50 FL
22	1		*FRONT BONNET LOCK	Serviceable	85.80 FL	*- FL
23	1		*FRONT BONNET INSULATOR	Serviceable	179.65 FL	*- FL
24	1		*FRONT AIR DUCT	Serviceable	398.95 FL	*- FL
25	1		*FRONT AIR DUCT BASE GARNISH	Serviceable	687.90 FL	*- FL
26	1		*FRONT FENDER RH	Bent	1,296.35 FL	*1,296.35 FL
27	1		*FRONT FENDER CHROME SIGN RH	Necessary	72.40 FL	*72.40 FL
28	1		*FRONT FENDER ARCHED GARNISH -RH	Deformed	267.35 FL	*267.35 FL
29	1		*FRONT FENDER COWLING RH	Cracked	194.20 FL	*194.20 FL
30	1		*FRONT FENDER SUPPORT BRACKET RH	Serviceable	58.75 FL	*- FL
31	1		*FRONT NUMBER PLATE	Serviceable	50.00 FS	*- FS
32	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*SET FRONT BUMPER FOGLAMP LOWER GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
34	1		*SET FRONT BUMPER CENTER GARNISH CLIP	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*SET FRONT BUMPER CENTER BOTTOM GARNISH CLIP	Not Necessary	60.00 FS	*- FS
36	1		*SET FRONT BUMPER NUMBER PLATE GARNISH CLIP	Not Necessary	60.00 FS	*- FS
37	1		*SET FRONT LOWER GRILLE CLIP	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BONNER SEALANT	Necessary	150.00 FS	*30.00 FS
39	1		*SET FRONT BONNER INSULATOR CLIP	Necessary	80.00 FS	*30.00 FS
40	1		*SET FRONT AIR DUCT BASE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
41	1		*SET FRONT FENDER ARCED GARNISH CLIP RH	Necessary	50.00 FS	*30.00 FS
42	1		*SET FRONT FENDER COWLING CLIP RH	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,211.65	11,317.00
- List Item Discount on L Items 5.00/10.00% (S\$)	1,021.58	1,117.70
Total Parts (S\$)	20,190.07	10,199.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	700.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
5	REFOCUS HEADLAMP BEAM	New	80.00	30.00
6	REMOVE AND REFIX FRONT BUMPER SENSOR	New	80.00	20.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/ CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	680.00	120.00
Gross Labour Cost (S\$)			3,840.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >