

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20000604/HKA3Q2

**Date:** 27/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SML7790P

**Insured Vehicle No :** GZ6226G

Date of Loss: 30/12/2019

Nature of Claim: TP

Claim No: 6715639077SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML7790P**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: A2183328JSUX0431

Reg. Date: 03/06/2019 (Man. Year: 2019)

Chassis No: W0VZM6EF3K1035033

Colour: Blue

Odometer: 68143 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,700.68	2,377.88	322.80	11.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,280.00	550.00	30.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,530.68</b>	<b>3,657.88</b>	<b>872.80</b>	<b>19.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>(S\$)</b>	4,530.68	2,900.00	1,630.68	35.99
<b>+ GST 7.00/7.00% (S\$)</b>	317.15	203.00	114.15	35.99
<b>Nett Amount (S\$)</b>	<b>4,847.83</b>	<b>3,103.00</b>	<b>1,744.83</b>	<b>35.99</b>
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,105.00</b>		

### INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 4.0 days

**Adjuster:** LEE HOCK ANN**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,429.20 FL	*1,429.20 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	646.00 FL	*646.00 FL
3	2		*REAR BUMPER REFLECTOR	Serviceable	246.00 FL	*- FL
4	2		*SET REAR BUMPER SENSOR	Shorted	596.00 FL	*500.00 FL
5	2		*REAR BUMPER SENSOR HOLDER	Necessary	28.00 FL	*28.00 FL
6	1		*REAR BUMPER NUMBER PLATE	Cracked	50.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,995.20</b>	<b>2,638.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	294.52	260.32
<b>Total Parts (\$)</b>	<b>2,700.68</b>	<b>2,377.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	30.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	20.00
4	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	600.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>1,830.00</b>	<b>1,280.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**