

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20000607/KDS3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHC5297S **Insured Vehicle No :** SKQ7779X

Date of Loss: 06/01/2020 **Nature of Claim:** TP **Claim No:** 6248114252SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5297S
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C001024
Reg. Date: 21/03/2014 (Man. Year: 2013) **Chassis No:** VF1ABL15AUC276744
Colour: Metallic White/Red **Odometer:** 346029 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Sailun 8 mm **Rear Left Side:** Giti 7 mm
Front Right Side: Sailun 8 mm **Rear Right Side:** Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,368.63	5,050.12	14,318.51	73.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,380.00	2,530.00	15,850.00	86.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,748.63	7,580.12	30,168.51	79.92
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	37,748.63	6,050.00	31,698.63	83.97
+ GST 7.00/7.00% (S\$)	2,642.40	423.50	2,218.90	83.97
Nett Amount (S\$)	40,391.03	6,473.50	33,917.53	83.97
+ Car Rental (9.0 x S\$81.13/day) (S\$)		730.17		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,211.16		

INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 08/01/2020 **Inspected At:** Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
8	1		*BUMPER RETAINER LH REAR	Distorted	54.20 FL	*54.20 FL
9	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
13	1		*BUMPER BLOCK LH REAR	Serviceable	75.70 FL	*- FL
14	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*- FL
15	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	*- FL
16	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP (50%)	Distorted / Dented	160.38 FS	*89.10 FS
19	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
20	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
21	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
22	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
23	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
24	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
26	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
27	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
28	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
29	1		*BOOT LOCK	Repair	246.60 FL	*- FL
30	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
31	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
32	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
33	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
34	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
35	1		*TAILLAMP RH	Repair	313.10 FL	*- FL
36	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
37	1		*TAILLAMP LH	Cracked	401.40 FL	*401.40 FL
38	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
39	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
40	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
41	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*- FL
42	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
43	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
44	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
45	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
46	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
47	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
49	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
54	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
55	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*- FS
56	1		*EXHAUST BRACKET REAR	Not Necessary	24.80 FS	*- FS
57	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
58	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
59	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
61	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
62	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
63	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
64	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
65	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
66	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
67	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
68	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
69	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
70	1		*REAR RENAULT TYRE 215/60/16	Serviceable	300.00 FS	*- FS
71	1		*REAR RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,171.55 5,556.90
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,802.92 506.78

Total Parts (\$\$) 19,368.63 5,050.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	880.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	7,500.00	1,200.00
3	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST}	New	170.00	100.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST }	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREE GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
13	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
15	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
16	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
17	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
18	TOWING FEES	New	150.00	0.00
Gross Labour Cost (\$\$)			18,380.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >