

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20000624/AGA3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKH9770D	Insured Vehicle No :	SH7624L
Date of Loss: 08/01/2020	Nature of Claim: TP	Claim No: MCT20010196

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH9770D	Engine No:	CAXC62779
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)	Chassis No:	WVWZZZ16ZDM040082
Reg. Date:	31/01/2013 (Man. Year: 2012)	Odometer:	114184 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Crucero 6 mm	Rear Left Side:	Crucero 6 mm
Front Right Side:	Crucero 6 mm	Rear Right Side:	Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,817.40	8,189.52	6,627.88	44.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	2,930.00	2,020.00	40.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,767.40	11,119.52	8,647.88	43.75
Approved Total (Overridden) (\$\$)		8,900.00		
Nett Amount (\$\$)	19,767.40	8,900.00	10,867.40	54.98
+ Car Rental (9.0 x S\$100.00/day) (\$\$)		900.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		9,836.45		
Global Sum Settlement (\$\$)		9,800.00		

INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	10/01/2020 Inspected At:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2020)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH9770D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Dented	1,759.30 FL	*1,537.00 FL
2	1		*REAR FENDER INNER SHIELD	Not Necessary	178.60 FL	*- FL
3	1		*REAR WINDSCREEN INNER SHIELD	Necessary	80.00 FL	*80.00 FL
4	1		*REAR TAILAMP LH	Not Necessary	685.20 FL	*- FL
5	1		*REAR BUMPER	Deformed	1,392.50 FL	*1,392.50 FL
6	1		*REAR BUMPER SIDE REAINER	Necessary	105.20 FL	*105.20 FL
7	1		*REAR BUMPER ATTACHMENT RETAINER	Not Necessary	105.60 FL	*- FL
8	1		*FRONT DOOR LH	Repair	1,963.50 FL	*- FL
9	1		*REAR DOOR LH	Dented	1,562.30 FL	*1,562.30 FL
10	1		*REAR DOOR INNER TRIM LH	Repeated	987.60 FL	*- FL
11	1		*REAR DOOR SPEAKER LH	Not Necessary	180.00 FL	*- FL
12	1		*REAR DOOR INNER TRIM LH	Cracked	558.20 FL	*558.20 FL
13	1		*REAR DOOR WEATHERSTRIP (DOOR) LH	Necessary	168.50 FL	*168.50 FL
14	1		*REAR DOOR WEATHERSTRIP (FRAME) LH	Not Necessary	245.60 FL	*- FL
15	1		*REAR DOOR INNER LOCK LH	Not Necessary	375.60 FL	*- FL
16	1		*REAR DOOR CATCH LH	Not Necessary	56.30 FL	*- FL
17	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	154.20 FL	*- FL
18	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	125.30 FL	*- FL
19	1		*REAR DOOR OUTER HANDLE COVER LH	Not Necessary	54.20 FL	*- FL
20	1		*SIDE ROCKER PANEL LH	Repair	985.60 FL	*- FL
21	1		*REAR RIM LH	Cut	850.20 FL	*850.20 FL
22	1		*REAR UPPER ARM LH	Bent	305.80 FL	*305.80 FL
23	1		*REAR LOWER ARM LH	Bent	480.50 FL	*480.50 FL
24	1		*REAR CONTROL ARM LH	Not Necessary	437.80 FL	*- FL
25	1		*REAR KNUCKLE ARM LH	Damaged	818.10 FL	*818.10 FL
26	1		*REAR WHEEL HUB BEARING LH	Necessary	425.60 FL	*425.60 FL
27	1		*REAR ABSORBER LH	Bent	548.90 FL	*548.90 FL
28	1		*REAR WHEEL SPEED SENSOR LH	Not Necessary	195.80 FL	*- FL
29	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
30	1		*REAR TYRE LH	Not Necessary	220.00 FS	*- FS
31	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*SET REAR DOOR INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*SET REAR DOOR CUSTOMIZED STICKER	Necessary	200.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,396.00	9,072.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,578.60	883.28
Total Parts (\$\$)	14,817.40	8,189.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL	New	1,800.00	1,100.00
2	TO RESPRAY AFFECTED AREAS	New	1,800.00	1,100.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	100.00
4	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	80.00
5	TO APPLY SEALANT TO THE AFFECTED AREAS	New	150.00	60.00
6	TO REMOVE/REFIT WIRING CHECKS ON REAR TAILAMP	New	120.00	30.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO REMOVE/REPLACE /REFIT REAR UNDERCARRIAGE	New	180.00	180.00
9	TO REMOVE/REFIT REAR WINDSCREEN	New	120.00	120.00
10	TO PERFORM COMPUTERISED WHEEL ALIGNMMENT (BEFORE & AFTER)	New	160.00	80.00
11	TO REMOVE/REPLACE TRANSFER REAR DOOR MECHANISM	New	120.00	80.00
Gross Labour Cost (\$\$)			4,950.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >