

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20000628/KHA3Q2**Date:** 11/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMD8410Y **Insured Vehicle No :** SMN1909U

Date of Loss: 07/01/2020 Nature of Claim: TP Claim No: 9902566856SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD8410Y	Engine No:	1NZ8393733
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NHP1707109698
Reg. Date:	07/09/2018 (Man. Year: 2017)	Odometer:	110938 km
Colour:	Metallic Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	MAXIMUM 6 mm	Rear Left Side:	Roadstone 8 mm
Front Right Side:	MAXIMUM 6 mm	Rear Right Side:	Roadstone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,586.15	2,770.35	1,815.80	39.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,500.00	260.00	14.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,346.15	4,270.35	2,075.80	32.71
+ GST 7.00/7.00% (S\$)	444.23	298.92	145.31	32.71
Nett Amount (S\$)	6,790.38	4,569.27	2,221.11	32.71
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,271.27		

INSPECTION

Date of Assignment: 09/01/2020

Date Inspected: 10/01/2020 Inspected At:

9A SERANGOON NORTH AVE 5
SINGAPORE 554500

Repairer: Optima Werkz Pte Ltd (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,186.50 FL	*1,086.00 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	65.60 FL	*65.60 FL
3	1		*REAR TAILGATE INNER LOCK	Dented	452.70 FL	*430.00 FL
4	1		*REAR TAILGATE RUBBER	Distorted / Dented	356.60 FL	*356.60 FL
5	8		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	49.60 FL	*- FL
6	1		*REAR WINDSCREEN RUBBER	Necessary	112.00 FL	*112.00 FL
7	1		*REAR TAILGATE PULL HANDLE	Dented	58.40 FL	*58.40 FL
8	1		*REAR END PANEL UPPER COVERING	Buckled	376.80 FL	*207.00 FL
9	6		*REAR END PANEL UPPER COVERING CLIPS	Necessary	37.20 FL	*37.20 FL
10	1		*REAR BUMPER	Bent	1,178.60 FL	*485.00 FL
11	1		*REAR BUMPER SIDE COVER LH	Serviceable	67.20 FL	*- FL
12	8		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
13	1		*REAR FLOOR PANEL TRAY BOX	Serviceable	674.40 FL	*- FL
14	1		*REAR FLOOR PANEL TRAY BOX UPPER BOARD	Dented	472.40 FL	*321.00 FL
15	1		*REAR BUMPER COVER	Bent	396.20 FL	*171.00 FL
16	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
17	2		*REAR WINDSCREEN STOPPER	Serviceable	30.00 FS	*- FS
18	1		*REAR BUMPER REVERSE SENSOR LH	Dented	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,968.20	3,613.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,382.05	843.45
Total Parts (\$\$)	4,586.15	2,770.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	500.00	500.00
2	LABOUR CHARGES TO REMOVE,REPLACE ,READJUST ,REAR BUMPER REVERSE SENSOR& ETC	New	80.00	50.00
3	LABOUR CHARGES TO REMOVE & REFIX ,REPLACE REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT ,REAR WINDSCREEN MOULDING & ETC ,EFFECT REPLACE OF REAR TAILGATE & ETC	New	150.00	120.00
4	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	800.00	750.00
5	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL WIRING SYSTEMS & ETC	New	80.00	20.00
6	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATION	New	150.00	60.00
Gross Labour Cost (\$\$)			1,760.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >