

ASS. REC. BY: Sun Pin

REF:

N TUC NS/INC20000633/Qvd3sz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: PC1318Y

Policy No. _____

Claims No. MT/1078768-003

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 16382 Yr Regn: 04/04/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Toyota Prius c.c. 1700Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 7464.59 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TDKIN360405748145

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 06/01/2020 D.O.I. 7/1/2020Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHB 16382 - CC3/CTI18022528 / Jda 3.2</u>
	<u>PC1318Y-X</u>
	<u>No Policy Found</u>
	<u>DOA 12/12/2016</u>
	<u>TAX/01/20/2017</u>
	<u>PC1318Y</u>
	<u>RECEIVED 21 JAN 2020</u>
<u>20/2/2020</u>	<u>Confirm with Poh Sun</u>
	<u>Finalise \$3,500 @ 4 days (2/5) (Red 14,299.12, 80%)</u>

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2) 21/1 - typist

Rep. Formas:

TP

Lump Sum / L.B.I.:

3500Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Phone

Others

TOTAL

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Tuesday, 21 January 2020 10:13 AM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Dear Sir/Mdm,

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1078768-003	SMRT TAXIS PTE LTD	SHB 1638Z	PC 1318'

Thank you

With Regards

Joreen Ang
Senior Admin Assistant
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 21 January 2020 7:53 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1		SMRT TAXIS PTE LTD	SHB 1638Z	PC 1318'

D.O.A	Time of Accident	Estimate	Tentative repair cost
6/1/2020	9:15	\$17,799.12	\$3500.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/01/2020 10:53
Date Of Accident 06/01/2020 09:15
Exact Location Of Accident GUL RD & PIONEER SECTOR LANE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB1638Z
Insured/Policyholder
Name Of Registered Owner SMRT TAXIS PTE LTD
Co Reg No 1XXXXX369K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-80000000
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-19093197MFSH
Cover Note Number
Driver
Name of Driver CHEONG KENG SOON
NRIC No SXXXX806B
Date Of Birth 13/02/1954
Occupation OUTDOOR
Date Of Driving Pass 19/04/1978
Driving Experience 41 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-80000000
Fax Number
Contact Number
Email Address NOEMAIL

Address	572A
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED AT PIONEER SECTOR LANE WANTED TO TURN LEFT INTO GUL ROAD. I STOPPED AT THE STOP LINE TO WATCH OUT FOR TRAFFIC BEFORE I COULD MOVE ON WHEN SUDDENLY THE BUS PC1318X FROM MY RIGHT SIDE WHILE MAKING A LEFT TURN, IT CUT TOWARDS MY TRAVEL PATH. I HONK FOR ABOUT MORE THAN 2 MINUTES HOWEVER THE BUS DID NOT STOP AND COLLIDED ONTO THE RIGHT FRONT PORTION OF MY STATIONARY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC1318X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

GUL RD

A - SHB 16382
B - PC 13184

A B

PIONEER SECTOR
LANE

[illegible]

I/We declare the foregoing particulars are true in every respect.

are the foregoing

Kenison

WFL 06/01/20

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 08/07/20
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHB1638Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR5907525
Chassis No.:	JTDKN36U405748145
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	04 Sep 2014
First Registration Date:	04 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2022
PARF Rebate Amount:	\$5,661.00

Intended COE Rebate Details

COE Expiry Date:	03 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$16,817.00
Total Rebate Amount:	\$22,478.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jan 2020

OK

Case Details

Case Reference Number :
TAX/01/20/2017

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1638Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10030-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 06/01/2020 01:15 AM

Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give * X SVC
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	0	0	Not Give * X SVC
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give * X SVC
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check * X SVC
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check * X SVC
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Check * X SVC
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check * X SVC
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	1	336.23	Replace * / CRU
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Check * X SVC

Total Spare Part Cost 11,108.03

Surveyor Total 2,790.75

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,886.42

Final Sur Total 2,232.60

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace	* / cut.
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. RH	1	49.30	49.30	25.00	36.97	Replace	1	36.97	Replace	* / Nec
One Time Key In	Main			FENDER APRON SUB FRT/RH	1	637.80	637.80	25.00	478.35	Replace	0	0	Check	* X Svc
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Check	* X Svc
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	* X Svc.
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	174.10	174.10	25.00	130.57	Replace	1	130.57	Replace	* / SCH.
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	* X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	* / Nec
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace	* / CR4.
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	1	36.97	Replace	* / Nec
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	* X Svc
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	* / CR4
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	* / NR
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	* X Svc

Total Spare Part Cost 11,108.03

Surveyor Total 2,790.75

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,886.42

Final Sur Total 2,232.60

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	* X SVC
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	* X SVC
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	10.00	279.99	Replace	0	0	Check	* X SVC
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0	Check	* X SVC
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	* X SVC

Total Spare Part Cost 11,108.03

Surveyor Total 2,790.75

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,886.42

Final Sur Total 2,232.60

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	* X
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Check	* X
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	* / CRA
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	* / DD
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	* / NEC

Total Spare Part Cost 11,108.03

Surveyor Total 2,790.75

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 8,886.42

Final Sur Total 2,232.60

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	400	/
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	/
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200	/
4	Main	TO RESPRAY RIM	180.00	0	
5	Main	TO RESPRAY FRONT DOOR RH	378.00	200	/
6	Main	RESPRAY MIRROR COVER RH	180.00	0	
Total:			1,674.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	✓
2	Main	TOWING CHARGE	55.00	0	
3	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓
7	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓
8	Main	TO WASH AND VACUUM	60.00	0	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
Total:			1,072.88	396.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,886.42	2,232.60
Total Labour Cost	507.00	400.00
Total Spray Painting	1,674.00	600.00
Other	1,072.88	396.88
Overall Total	12,140.30	4,187.53
Lump Sum Repair Option	✓	✓
Lump Sum Total	12,150.00	4,200.00
Surveyor Approved Amount		4,200.00
No of Repair Days*	6	4
Remarks	-	Lump sum repair, after paint photo.
Surveyor Name		Sun Pin (LKK)
Signature		

10/1/2020

Save

Clear

Survey Date

Estimator Assessment(\$)

Surveyor Assessment(\$)

07/01/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

WEGA ENGINEERING PTE LTD				
Contractor:				
Accident Case Number	7A4 / 01 / 20 / 2017	Date of Collection	9 / 1 / 20	
Vehicle No	SHB 1638 Z	Date of Request	10 / 1 / 20	
Vehicle Model	20407A PRWS	Number of Days to Extend (If any)		

S/N	Part Number	Part Description	Quantity	Unit Price
	6195, 96, 97	Grime Radiator		\$310.60
	6198, 99, 100, 101	Bumper Art Absorber Lower		\$127.70

/cut
/cut

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
[Signature]

Signature of person making this declaration
[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff		
Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB1638Z
Case Reference Number	TAX/01/20/2017
Registration Date	4/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHEONG KENG SOON
Type of Accident	Side Swipe
Accident Date and Time	6/1/2020 9:15 AM
Accident Reported Date and Time	6/1/2020 11:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	Yes
Towed Back Date and Time	6/1/2020 9:30 AM
Replacement Vehicle issued?	No
Job Card Number	24105185
Special Instruction to ARC, if any	RIGHT FRONT PORTION
Prepared Date and Time	6/1/2020 6:05 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$1,674.00	\$600.00
Total Spare Part Cost	\$11,436.75	\$2,992.80
Total Other Cost	\$1,072.88	(\$492.80)
TOTAL COST	\$14,690.64	\$3,500.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	13/01/2020 8:44 AM	11/01/2020 11:15 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	Lump sum repair, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2001-0276	Invoice Number	
Quotation Date	19.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$400.00 /
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 /
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 /
TOWING CHARGE	\$56.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88 /
Lump Sum Adjustment by Surveyor	\$0.00	(\$889.68)
Total Other Costs	\$1,072.88	(\$492.80)

Nec SN

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X
		75310-47010	EMBLEM FRONT	0.00	\$86.50	0.00	\$0.00	Replace	Not Given X
		53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given Y
		53289-47032	COVER, RADIATOR	0.00	\$122.80	0.00	\$0.00	Replace	Check X
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check X
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check X

SVC

4415.68

SMRT Accident Vehicle Repair Estimates

Date Generated : 20/01/2020

User ID : 1 PohSuan

76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X	SVC
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X	SVC
51410-12105	UNDER COVER CENTER	1.00	\$448.30	25.00	\$336.23	Replace	Replace	/	CRU
53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Check	X	SVC
53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	/	CRU
53851-47040	FENDER LINER PAD, FR WHEEL RH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	/	NEC
53701-47050	FENDER APRON SUB FRT/RH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X	SVC
42611-47140	WHEEL DISC, FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Check	X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
42602-47080	CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace	/	SCR
67001-47070	DOOR FRT/RH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R	
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	/	NEC
53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	/	CRU
53852-47020	FENDER LINER PAD, FR WHEEL, LH	1.00	\$49.30	25.00	\$36.98	Replace	Replace	/	NEC
87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X	SVC
81730-52090	MIRROR LAMP RH	0.00	\$85.30	0.00	\$0.00	Replace	Not Given	X	SVC
879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X	SVC
52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	/	CRU
52161-18010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	/	NEC
52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X	
52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X	
52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$76.80	0.00	\$0.00	Replace	Check	X	
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	X	
57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X	
57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	X	
52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given	X	
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X	
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X	SVC
52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X	
52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given	X	
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check	X	
82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Check	X	
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given	X	
81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X	
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.60	0.00	\$0.00	Replace	Not Given	X	
51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Check	X	
51443-12080	UNDER COVER SIDE/RH	0.00	\$46.10	0.00	\$0.00	Replace	Check	X	
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X	
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/	CRU

12 169.84

		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	DD
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	RC
Total					\$14,092.45		\$2,664.07			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53111-47040	GRILLE, RADIATOR	1.00	\$310.80	25.00	\$232.95	Replace	Replace ✓
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace ✓
Total					438.30		328.73		

1213.60

2992.80,
+ 400.00,
+ 996.88,

17360.82
17799.12

4389.68

- 202

3511.74

US \$ 3500/-
4 days

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 21 January 2020 9:38 AM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB1638Z

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]
Sent: Monday, 20 January 2020 7:23 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHB1638Z

Dear Poh Suan,

Confirm the finalize amount \$3,500. Repair day 4 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 20 January, 2020 3:54 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB1638Z

Hi Sun Pin,

Attached herewith the repair estimate of SHB 1638Z having Case No: TAX/01/20/2017.

There is no change to the approved amount of \$3,500 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Monday, 20 January 2020 3:58 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Monday, 20 January, 2020 7:23 PM
To: 'Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)'
Subject: RE: SHB1638Z

Dear Poh Suan,

Confirm the finalize amount \$3,500. Repair day 4 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Monday, 20 January, 2020 3:54 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB1638Z

Hi Sun Pin,

Attached herewith the repair estimate of SHB 1638Z having Case No: TAX/01/20/2017.

There is no change to the approved amount of \$3,500 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Monday, 20 January 2020 3:58 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20000633/Qvd3s2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 04-02-2020	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 1318Y	Veh. Inspected	SHB 1638Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078768-003	Excess (\$)	0.00
Assign From		Assign Date	07/01/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405748145	Colour	MAROON
Odometer	746959	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/01/2020	Inspection Date	07/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1638Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	UNDER COVER CENTER (DISC 25%)	CRUSHED	448.30	336.23
1	FENDER LINER FRT/RH (DISC 25%)	CUT	171.70	128.78
1	FENDER LINER PAD, FR WHEEL, RH (DISC 25%)	NECESSARY	49.30	36.98
1	CAP SUB-ASSY, WHEEL (DISC 25%)	SCRATCHED	174.10	130.58
1	FENDER LINER FRT/LH (DISC 25%)	CRUSHED	171.70	128.78
1	FENDER LINER PAD, FR WHEEL, LH (DISC 25%)	NECESSARY	49.30	36.98
1	BUMPER FRT (DISC 25%)	CRUSHED	482.00	361.50
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	FENDER FRT/RH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	HEAD LAMP RH (DISC 10%)	CRACKED	945.20	850.68
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	LENS & BODY, FR TURN RH	SERVICEABLE	511.80	-
1	EMBLEM FRONT	SERVICEABLE	86.50	-
1	HOOD END PANEL SEAL	SERVICEABLE	35.50	-
1	COVER, RADIATOR	SERVICEABLE	122.80	-
1	GRILLE, RADIATOR	SERVICEABLE	310.60	-
1	GRILLE, RADIATOR LOWER NO.2	SERVICEABLE	94.60	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	FENDER PROTECTOR FRT/RH SIDE	SERVICEABLE	113.90	-
1	FENDER APRON SUB FRT/RH	SERVICEABLE	637.80	-
1	WHEEL DISC, FRONT	SERVICEABLE	1,484.20	-
1	TYRE	SERVICEABLE	126.74	-
1	MIRROR ASSY, RH	SERVICEABLE	1,307.10	-
1	MIRROR LAMP RH	SERVICEABLE	65.30	-
1	COVER, OUTER MIRROR, RH	SERVICEABLE	107.40	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-

Report Ref No. NS/INC20000633/Qvd3s2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	NUMBER PLATE FRAME	SERVICEABLE	12.00	-
1	NUMBER PLATE	SERVICEABLE	15.00	-
1	COVER, FR BUMPER HOLE LH	SERVICEABLE	18.50	-
1	COVER, FR BUMPER HOLE RH	SERVICEABLE	18.50	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	LENS & BODY, FR TURN LH	SERVICEABLE	511.80	-
1	UNDER COVER SIDE/LH	SERVICEABLE	46.10	-
1	UNDER COVER SIDE/RH	SERVICEABLE	46.10	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	DOOR FRT/RH	TO REPAIR SEE LABOUR	894.40	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
1	GRILLE, RADIATOR (DISC 25%)	CUT	310.60	232.95
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	CUT	127.70	95.78
			14,842.12	3,289.68
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF DOOR FRT/RH.		507.00	400.00
	SPRAY PAINT.		1,674.00	600.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TOWING CHARGE.		56.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00

Report Ref No. NS/INC20000633/Qvd3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION. TO WASH AND VACUUM.	NOT NECESSARY	80.00 60.00 2,957.00	20.00 - 1,100.00
GRAND TOTAL			17,799.12	4,389.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,500.00

Report Ref No. NS/INC20000633/Qvd3s2

OI SUN PIN

Asst. Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.