

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20000656/ASD3E2

Date: 28/05/2020

REFERENCE

Insured/Claimant:	TAN YU ZHUO	Policy No:	1700070803	
Date of Loss:	07/01/2020	Nature of Claim:	OD	Claim No: 7023220376SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT4545X			
Make & Model:	AUDI A3, 999cc TFSI S-TRONIC (A)	Engine No:	CHZ557050	
Reg. Date:	30/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V7J1018277	
Colour:	White	Odometer:	34355 km	
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$87,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,545.00	1,095.68	5,449.32	83.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,047.00	2,697.68	6,349.32	70.18
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	8,747.00	2,397.68	6,349.32	72.59
+ GST 7.00/7.00% (\$\$)	612.29	167.84	444.45	72.59
Nett Amount (\$\$)	9,359.29	2,565.52	6,793.77	72.59

INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	10/01/2020	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,830.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	146.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	488.00 FS	*- FS
5	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	540.00 FS	*- FS
6	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	296.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	1,301.00 FS	*1,040.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
12	1		*FOAM FILLER PIECE COVER	Not Necessary	111.00 FS	*- FS
13	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
14	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
15	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	44.00 FS	*- FS
16	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	11.00 FS	*- FS
17	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
18	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,545.00** **1,095.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >