



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2006845
INV Date 06/10/2020
Reference CC4/EQI20000657/Uga3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. WGK 5389
Insured Veh. GBB 5211R
Claim No. DM19HO03254/JT
Policy No. DMCPHQ19-002519
Accident Date 09/12/2019
Inspection Date 10/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI20000657/Uga3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 06-10-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 5211R	Veh. Inspected	WGK 5389
	Policy No.	DMCPHQ19-002519	Coverage (\$)	0.00
	Claim No.	DM19HO03254/JT	Excess (\$)	0.00
	Assign From		Assign Date	10/01/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA NV400CS	c.c	398
	Engine No.	HIDDEN	Year of Reg.	1998
	Chassis No.	NC262000003	Colour	MULTI COLOUR
	Odometer	34718	Steering	AFFECTED
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90-90-21	BRIDGESTONE	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	110-80-15	BRIDGESTONE	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/12/2019	Inspection Date	10/01/2020
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WGK 5389

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	DISTORTED	200.00	165.00
1	HEADLAMP	SERVICEABLE	320.00	-
1	HEADLAMP BRACKET	NOT NECESSARY	65.00	-
1	FRONT FORK ASSY	BENT / TWISTED	1,720.00	1,600.00
1	FORK UNDER BRACKET	BENT	375.00	375.00
1	FRONT BRAKE DISC	BENT	455.00	399.00
1	FRONT RIM SHAFT	BENT	68.00	68.00
1	SET FRONT RIM SET	BENT	550.00	550.00
1	FRONT BRAKE CALIPER	CRACKED	310.00	310.00
1	HANDLE BAR	BENT	150.00	150.00
1	SET HAND GRIP	BENT	80.00	80.00
1	SIDE MIRROR -L/H	SERVICEABLE	95.00	-
1	CLUTCH LEVER	CUT	58.00	58.00
2	FRONT SIGNALS	N/S CRACKED	352.00	85.00
1	FRONT FOOTREST -L/H	BENT	75.00	75.00
1	FRONT FOOTREST BRACKET	BENT	245.00	245.00
1	BRAKE PEDAL	NOT NECESSARY	98.00	-
1	GEAR PEDAL	BENT	115.00	115.00
1	REAR FOOTREST -L/H	CUT	100.00	100.00
1	RADIATOR	PUNCTURE	700.00	700.00
1	SIDE STAND	TO REPAIR SEE LABOUR	80.00	-
1	REAR SIGNAL -L/H	CRACKED	85.00	85.00
1	REAR TAILBOARD	TO REPAIR SEE LABOUR	335.00	-
	LESS 10% DISCOUNT		-663.10	-516.00
			5,967.90	4,644.00
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NO SUCH PARTS	30.00	-
2	FORK OIL SEALS (SN)	NO SUCH PARTS	56.00	-

Report Ref No. CC4/EQI20000657/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NOT NECESSARY	80.00	-
1	E.R.P IU (SN)	SERVICEABLE	175.00	-
1	FRONT TYRE (SN)	SERVICEABLE	180.00	-
1	SET CRASH BAR (SN)	TO REPAIR SEE LABOUR	280.00	-
			829.00	-
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF SIDE STAND,REAR TAILBOARD AND SET CRASH BAR.		480.00	400.00
	TO RESPRAY PAINTING.		700.00	300.00
			1,230.00	735.00
GRAND TOTAL			8,026.90	5,379.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC4/EQI20000657/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WGK 5389

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. W GK 5389

RE-INSPECTION

