

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000662/UPA3Q2

Date: 20/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMM2738U	Insured Vehicle No :	SHD3501K
Date of Loss: 07/01/2020	Nature of Claim: TP	Claim No: MCT20010165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2738U		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B25510511
Reg. Date:	24/06/2019 (Man. Year: 2019)	Chassis No:	MRHFC5650KT000508
Colour:	Silver	Odometer:	34005 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Achilles 8 mm	Rear Left Side:	Achilles 8 mm
Front Right Side:	Achilles 8 mm	Rear Right Side:	Achilles 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,843.44	1,381.84	461.60	25.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,020.00	710.00	41.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,573.44	2,401.84	1,171.60	32.79
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,573.44	1,900.00	1,673.44	46.83
+ GST 7.00/7.00% (S\$)	250.14	133.00	117.14	46.83
Nett Amount (S\$)	3,823.58	2,033.00	1,790.58	46.83
+ Car Rental (3.0 x S\$70.00/day) (S\$)		210.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,272.00		
Global Sum Settlement (S\$)		2,270.00		

INSPECTION

Date of Assignment:	09/01/2020	
Date Inspected:	10/01/2020 Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Feb 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2738U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	617.50 FL	*617.20 FL
2	1		*REAR BUMPER SIDE RETAINER-RH	Not Necessary	28.00 FL	*- FL
3	1		*REAR BUMPER SENSOR-RH	Shorted	148.30 FL	*148.30 FL
4	1		*REAR BUMPER REFLECTOR-RH	Scratched	30.40 FL	*30.40 FL
5	1		*REAR BUMPER REFLECTOR COVER-RH	Distorted	90.20 FL	*90.20 FL
6	1		*REAR BUMPER LOWER PAD	Deformed	145.20 FL	*145.20 FL
7	1		*REAR BUMPER LOWER PAD CHROME	Scratched	102.40 FL	*102.40 FL
8	4		*REAR BUMPER LOWER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*REAR END PANEL	Repair	385.70 FL	*- FL
10	1		*REAR TAIL LAMP-RH	Scratched	307.40 FL	*307.40 FL
11	1		*REAR TAIL LAMP LOWER BRACKET	Cracked	181.00 FL	*18.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	246.20 FL	*246.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,304.30	1,727.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	460.86	345.46
Total Parts (\$\$)	1,843.44	1,381.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	450.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	0.00
4	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
5	TO SPRAY PAINTING	New	680.00	500.00
Gross Labour Cost (\$\$)			1,730.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >